


CABLE ASSEMBLY INSTRUCTIONS

SOLDER (US STANDARD)



- STEP 1. All parts of the connector are shown.
- STEP 2. Strip the cable inner conductor, dielectric, braid, and jacket as per "RECOMMENDED CABLE STRIPPING DIM'S" in catalog.
- STEP 3. Slide the SHELL onto cable, then screw the MAIN BODY onto cable and solder it as shown.
- STEP 4. Slide the SHELL forward and screw in place on the MAIN BODY.