

Discount Drainage - CCTV SUMMARY

Following the CCTV inspection of the Sanitary Sewer drain, at 46a Pacific Road
we found the drain to be laid in 100mm PVC and in good operating condition.

Constuction features can be found on the attached CCTV Inspection Logsheets.

DISCOUNT DRAINAGE CCTV INSPECTION LOGSHEET

ADDRESS

46a Pacific Road

DATE _____

Disc Number / File Number

05-11-15

Disc 1 / File 1 and 2

FINISHING POINT

DRAIN MATERIAL

50.5m Downstream

100mm PVC

Remarks

30.3	
------	--

ЛНВ, IP

END OF CAMERA CABLE - END OF INSPECTION

YJ = Y Junction, IP = Inspection point, EW = Earthenware, RHB = Right Hand Bend, LHB = Left Hand Bend, BDY = Boundary, DP = Downpipe, BUS = Bubble up Sump, TV = Terminal Vent, GT = Gulley Trap, BDY = Boundary CP = Collapsed Pipe, BP = Broken Pipe, Dip = Slump in Pipe, FO = Foreign Object, RI = Root Intrusion FJ = Faulty Joint, CR = Cracked Pipe, SD = Silt/Debris, MH = Manhole, HOL = Head Of Line



~~DATA~~

TV

3.3

6.1

BACK
Hous

12.9

9.7

BDY

উদ্য

BDY

26.7

31.4

FRONT HOUSE

 43.2

50.5

46A Pacific Rd.