## Home Energy Certificate

## Landlord's compliance for healthy home

This home has been assessed to the Home Performance criteria and has passed meeting the following Healthy Homes Standards

	Proper	ty Add	lress: 65 Coope	er Ro	ad						
	Ceiling	insulo	ation compliant to	NZS	4246						
	Under floor insulation size complies to NZS4246 (including if concrete floor) Ground Vapor Barrier (250 micron)										
1											
	Ventiliation / Exhaust Fans										
	☑ Range hood										
	☐ Bathroom extraction fan										
<u></u>	Bathroom 2 ensuite										
<ul> <li>☑ Energy Efficient Heating is installed to Healthy Homes Standards</li> <li>☑ Smoke detectors fitted to NZBC F7/AS1 3.2 &amp; NZS4514</li> </ul>											
			*								
	_		ping complies to nplies to Healthy				urus				
_	Drama	ge con	- Pices to Fiedering	110111	es staridara						
<u>Ceilir</u>	<u>ng insul</u>	<u>lation</u>	1								
Type		7	Fiberglass		Polyester		Wool		Mixed		
			Blown		Other						
Compl	lies	7	Yes		No						
R Rati	ng / thic	ckness	(if applicable) 1	80m	m						
	r floor										
Type			Fiberglass		Polyester		Wool		Mixed		
			Concrete floor		None - too	clos	e to the gr	ound			
		Other Xpol Panels							_	eal of Air	L
		Condition								5	Ł
Compl	lies	<b>7</b>	Yes		No						
R Rati	ng / thic	ckness	(if applicable) _						7	oft basison	F
Compl	liant on	date o	of inspection					An	proved Aud	itors	
Compliant on date of inspection  Overall notes							•••				
Obera	itt Hotes										•
N	Coircon Dean Kerr										
A	> UL heating	cooling   vent	illation								
All the co	omfort of warm	1. cool clas	n air				EECA		Chuict	church	







