





APPENDIX A.2


Mapping showing the Differences in 100-year Floodplain Inundation between With-Dam Conditions and the Reroute and Removal Option







































NOTE: MAPPING NOT PREPARED USING FEMA GUIDELINES AND SHOULD NOT BE USED TO ASSESS FLOOD DAMAGES.




Mussetter
Engineering
Inc.

1730 South College Ave. Suite 10C
Fort Collins, Colorado 80525

- Subreach Limits
- Cross Sections
- MEI Station Line

Difference in Inundated Area

- Baseline 78 Exceeds Reroute 78
- Reroute 78 Exceeds Baseline 78



 Mussetter Engineering Inc. 1730 South College Ave. Suite 10C Fort Collins, Colorado 80525	Subreach Limits	Difference in Inundated Area
	Cross Sections MEI Station Line	Baseline 85 Exceeds Reroute 85 Reroute 85 Exceeds Baseline 85