


TR80-80WM

Instruction manual




TR80-80WM2



TR80-80WM2




P4 × 1




40 x 40 Corner Brackets with Cap

CB1 × 2



40 x 80 Anodized Corner Bracket

CB4 × 2



M8x25 Hex Screw

S4 × 2



M8x16 Hex Screw

S2 × 8




M8x20 Hex Screw

S3 × 16



M6x20 Hex Screw

S6 × 4




Flat Washer

W1 × 18




Lock Washer

W2 × 18






M8 Flange Nut

N1 × 6





M8 T-Nut

N2 × 20





1




P4x1

1a





N2x14

1b




2




N2x6


2a





3




3a



4





CB1x2



CB4x2


5




S2x8



5a




6




W1x4




W2x4





S3x4



6a




7



WM3×2


7a




W1×8






W2×8




S3×8





WM2x2


8a




W1x2




W2x2




S3x2




N1x2



8b




9



WM1x1


9a




W1x2




W2x2




S4x2




N1x2



9b




10




W1x2




W2x2




S3x2



N1x2



10a



FINISHED



Share your build online and tag us to be featured!



@trakracer



@trakracer



@trak_racer