



## Supervisor Talking Points

---

- As a group discuss the following:
  - Potential ignition sources that may cause a dust explosion (hot work, overheated bearings, ferrous metal, misaligned belts, tramp metal, faulty electrical equipment, smoking, etc.)
  - Types of hazard monitoring equipment at the facility (bearing monitoring, motion detection, belt alignment, etc.)
  - Priority housekeeping areas, inspection frequency, and methods used for cleaning (brooms, compressed air, etc.)
  - Requirements for performing hot work within the facility (permit process, removal of dust, wetting down the area, fire hose/extinguishers, fire watch, etc.)
  - Preventive Maintenance Program including frequency and documentation of equipment inspection. (Bucket elevators, dust collection equipment, grain dryers, etc.)
  - Procedure for cleaning out a choked leg
  - The facility's no smoking policy
  - Emergency action plan including evacuation routes and the assembly area for fires and explosions.