


CABLE ASSEMBLY INSTRUCTIONS

CLAMP



- STEP 1. All parts of the connector are shown.
- STEP 2. Strip the cable inner conductor, dielectric, outer conductor, and jacket as per "RECOMMENDED CABLE STRIPPING DIM'S" in catalog.
- STEP 3. Thread the GASKET onto the cable until it is against the cable jacket.
- STEP 4. Thread the CLAMP NUT onto the cable until the A dimension is 1–1.5 mm, then push the TOP HAT onto the outer conductor of cable inside as shown.
- STEP 5. Thread the MAIN BODY onto the CLAMP NUT and tighten the connection with wrenches, hold the CLAMP NUT and turn only the MAIN BODY.