

# Powder Mill Watershed Inventory

<b>Pond PM1</b>	
<p>PM1 is a pond located on private property and is close to the Maynard Gun Club, making it unsafe to access. It is also close to the site of the Maynard landfill, which is now capped and closed. Pond PM1 flows into Second Division brook, and may be a factor contributing to the polluted water in Second Division Brook.</p>	
<b>Pond PM2</b>	
<p>PM2 is a pond located on private property on Powder Mill Road.</p> <p>It is not visible from the Road.</p>	
<b>Pond PM3</b>	
<p>PM3 is a pond located on private property adjacent to Pond PM2 on Powder Mill Road.</p> <p>It is barely visible from the road and appeared to be almost entirely covered by algae and/or aquatic plants when the photo was taken in late July.</p>	

<p><b>Pond PM4</b></p> <p>PM4 is a small pond located on private property behind the houses on the corner of Powers Road and Maynard Farm Road.</p> <p>It is partially visible from Maynard Farm Road and appeared to be almost entirely covered by algae and/or aquatic plants when the photo was taken in late July.</p> <p>It appears to flow into a brook that feeds into Second Division Brook.</p>	
<p><b>Pond PM5</b></p> <p>PM5 is a pond located on privately owned property west of Powers Road across from Cedar Creek Road.</p> <p>It flows into stream PMA, which then flows into Second Division Brook.</p>	
<p><b>Pond PM6</b></p> <p>PM6 is a pond located on privately owned property east of Maynard Farm Road.</p> <p>It flows into stream PMA, which then flows into Second Division Brook.</p>	
<p><b>Pond PM7</b></p> <p>PM7 is a pond located on privately owned property behind the cul-de-sac at the end of Paddock Way.</p> <p>It appears to flow into brook PMA, which flows into Second Division Brook.</p> <p>It is not visible from the road.</p>	

<b>Pond PM8</b>	
<p>PM8 is a pond located on privately owned property at the corner of Dakin Road and Paddock Way. It is partially visible from the road behind a thin buffer of trees and shrubs.</p> <p>The pond was nearly entirely covered by algae and/or aquatic plants when the photo was taken in late July. However, it appears the owners have installed a water circulator as evidenced by a strong flow of bubbles surfacing in the middle of the pond.</p>	
<b>Pond PM9</b>	
<p>PM9 is a pond on privately owned land on the East side of Dakin Road along the Concord border. Approximately half of the pond lies in Sudbury.</p> <p>The photo was taken in late July, looking East from Dakin Road. The water surface appeared free of aquatic plants.</p>	
<b>Pond PM10</b>	
<p>PM10 is a pond on privately owned land at the end of Maynard Farm Circle.</p> <p>It appears to flow into a brook that feeds into Second Division Brook.</p> <p>It is not visible from the Road.</p>	

<p><b>Pond PMA</b></p> <p>PMA is a stream flowing from Pond PM5 to Pond PM6 into Second Division Brook. It crosses under Maynard Farm Road.</p>	
<p><b>Second Division Brook</b></p> <p>Second Division Brook emanates from Powder Mill Pond in Maynard, upstream of pond PM1.</p> <p>It flows across private property at the Maynard Gun Club and is also close to the site of the Maynard landfill, which is now capped and closed.</p> <p>It crosses Powder Mill Road between Tavern Circle and Cranberry Circle, where the photo was taken in late July.</p> <p>The water appears heavily polluted. It is very rusty in color, low volume and is slow moving. It practically dries up in the wetland area between Tavern Circle and Cranberry Circle.</p> <p>Second Division Brook (ID: MA82B-09) has been identified by the EPA but not assessed.</p>	 <p>Crossing Power Mill Road looking North</p>  <p>Wetland area between Tavern Circle and Cranberry Circle, from Cranberry Circle looking South</p>