


PART LIST ESB5

DIAGRAM NO.	PART NAME	QTY	ORDERING NO
1	BACKREST	1	C1352-E26
2	BACK SUPPORT	1	C2197-E26
3	SWING ARM	1	C0190-C01
4	ADJUSTABLE FOOT	1	C0188-C01
5	SMALL FOAM ROLLER 1" X 5"	2	C0417-B05
6	HANDLEBAR 1" X 12"	1	C6265-E26
7	PAD BAR 3/4" X 16"	1	C6061-A14
8	LARGE FOAM ROLLER 3 1/4" X 7"	2	C0443-E02
9	SUPPORT PLATE	2	LL-0062
10	DECAL	1	DE-4199
30	5/16" X 2 1/4" HEX HEAD BOLT	1	HH-5323
31	5/16" X 2 3/4" HEX HEAD BOLT	1	HH-5058
32	1/4" X 2 1/2" CARRIAGE BOLT	2	HH-5333
33	1/4" X 3/4" MACHINE SCREW	4	HH-5022
34	5/16" NYLON LOCK NUT	2	HH-5012
35	1/4" NYLON LOCK NUT	2	HH-5011
36	2" ROUND PLASTIC CAP	4	AA-8018
37	1" ROUND PLASTIC CAP	2	AA-8005
38	3/4" ROUND PLASTIC CAP	2	AA-8004
39	2" SQUARE PLASTIC CAP	1	AA-8002
40	LARGE LOCKING PIN	1	WW-7031
41	SMALL LOCKING PIN	1	WW-7006
	HARDWARE BAG	1	C5906-E26
	INSTRUCTION MANUAL	1	NN-1140



- ☐ Bolt SUPPORT PLATES (9) to BACK SUPPORT (2) with 1/4" X 2 1/2" CARRIAGE BOLTS (32) and 1/4" NYLON LOCK NUTS (35).
- ☐ Press 2" ROUND PLASTIC CAPS (36) into end tube of BACK SUPPORT (2).
- ☐ Assemble BACKREST (1) to BACK SUPPORT (2) by bolting up through SUPPORT PLATES (9) using 1/4" X 3/4" MACHINE SCREWS (33).
- ☐ Fasten BACK SUPPORT (2) to outside hole in welded brackets with 5/16" X 2 3/4" HEX HEAD BOLT (31) and 5/16" NYLON LOCK NUT (34). DO NOT OVERTIGHTEN OR SWING ARM WILL NOT FOLD FREELY!