


REMOVAL OVERVIEW STEPS


Preparing to Cut & Lift

- Lines will be placed under the ship to enable placement of cutting chain.
- Lifting brackets welded to top of wreck.
 - Distributes lifting load.
 - Stabilizes section during lift.
- The section to be cut will be wrapped to contain debris.



Section Cutting

- The US-flagged VB-10,000 floating crane will be positioned over wreck.
- VB-10,000's lifting blocks will operate the cutting chain.
- Once a cut is complete, the VB-10,000 will lift the section onto a barge inside the EPB and secure it for transport.
- Lifting brackets welded to top of wreck.
- Distributes lifting load.
- Stabilizes section during lift.



Lifting Preparations

