

Shifter Stop Upgrade for PERRIN Shifter Stop w/o Short Throw Shifter

2024-11-06

PSP-INR-02

Thank you for purchasing this PERRIN product for your car! Installation of this product should only be performed by persons experienced with installation of aftermarket performance parts and proper operation of high perfonce vehicles. If vehicle needs to be raised off the ground for installation, the installer must use proper jacks, jack-stands and/or a professional vehicle hoist for safety of the installer and to protect property. If the vehicle is lifted improperly, serious injury or death may occur! Please read through all instructions before performing any portion of installation. If you have any questions, please contact our tech department prior to starting installation. We can be reached in any of the following methods:

Email Tech@PERRIN.com
Instant Chat off the main page of www.PERRIN.com
Or simply call our tech team at 503-693-1702



WARNING: This product can expose you to chemicals including Lead which is known to the State of California to cause cancer birth defects or other reproductive harm. For more information, go to www.P65Warnings.ca.gov

GENERAL MODIFICATION NOTE

Modifications to any vehicle can change the handling and performance. As with any vehicle extreme care must be used to prevent loss of control or roll-over during sharp turns or abrupt maneuvers. Always wear seat belts, and drive safely, recognizing that reduced speeds and specialized driving techniques may be required. Failure to drive a vehicle safely may result in serious injury or death. Do not drive a vehicle unless you are familiar with its unique handling characteristics and are confident of your ability to maintain control under all driving conditions. Some modifications (and combinations of modifications) are not recommended and may not be permitted in your state or country. Consult the owner's manual, service manual, instructions accompanying these products, and local laws before purchasing and installing these modifications. You are responsible for the legality and safety of the vehicle you modify using these components.

Special Notes:


- This kit will NOT work on cars that have any kind of short throw shifter or shifter plate installed!! If you find you have something other than a stock shifter and shift plate installed do NOT install these and contact the seller.
- This kit is designed to work with the PERRIN Shifter Stop that has already been installed. This part will NOT work with any other brand of shifter stop.

Parts Included with the PERRIN Shifter Stop:

QTY	Part Number	Description
(2)	X-BLT-M6X25CSL-SS	M6 X 25 Low Head Socket Cap Screw SS
(1)	X-PSP-INR-020FRD	Shifter Stop Front for 2015+ WRX w/o Short Shifter Red
(1)	X-PSP-INR-020RRD	Shifter Stop Rear for 2015+ WRX w/o Short Shifter Red

Installation Instructions:

- 1. Remove shift knob from car and place shifter into neutral.
- 2. Grab around inside edges of shifter boot and silver trim ring. Pull straight up to remove shift boot and ring in one step. This will expose shifter mechanism.
- 3. The rest of this installation revolves around the PERRIN Shifter Stop (PSP-INR-018 or 019) previously being installed and also adjusted properly. Before continuing, ensure that the PERRIN Shifter Stop is installed properly and that reverse is NOT selectable during a 5th to 6th gear shift. See instructions on website with any questions regarding how to setup the PERRIN Shifter Stop.
- 4. Remove front M6 bolt securing PERRIN Shifter Stop (Black "C" shaped part) and install supplied PERRIN Front Shifter Stop (Red part with "020F" engraved on bottom) into slot as shown picture below.
- 5. Install supplied M6x25 bolt to secure in place and tighten to 10ft-lbs.
- 6. Remove rear M6 bolt securing PERRIN Shifter Stop (Black "C" shaped part) and install supplied PERRIN Rear Shifter Stop (Red part with "020R" engraved on bottom) into slot as shown picture below.
- 7. Install supplied M6x25 bolt to secure in place and tighten to 10ft-lbs.



Checking For Play In Shift Knob

The amount of play found in the shift knob is very important to have to ensure proper engagement of each gear position. If there is NO play in the shift knob after the installation and adjustment has occurred, STOP and remove the parts as transmission damage may occur! If you have an excessive amount of play in the shift knob, it may indicate some aftermarket parts are installed that you are unaware of, or the wrong part number was installed.

- 1. Depress clutch and shift into 3rd gear, then release the clutch.
- 2. The shifter should hit the PERRIN Shifter Stop (red part) when you push it forward and when you pull it toward neutral it should stop on the internal stops built inside of the transmission.
 - a. This "play" in the shift knob should be around 1/4"
 - b. This play indicates that you are able to fully select the gear without interference from the PERRIN Shifter Stop.
 - c. If there is NO play or it takes excessive force to hit the PERRIN Shifter Stop as described, see adjustment section below before removing.
- 3. Depress clutch and shift into 4^{th} gear, then release the clutch.
- 4. Just as in the above step, the shifter should hit the PERRIN Shifter Stop (red part) when you pull it toward the back of the car and when you push it toward neutral it should stop on the internal stops built inside of the transmission.
 - a. This "play" in the shift knob should be around 1/4"
 - b. This play indicates that you are able to fully select the gear without interference from the PERRIN Shifter Stop.
 - c. If there is NO play or it takes excessive force to hit the PERRIN Shifter Stop as described, see adjustment section below before removing.
- 5. Shift transmission into all gears and check that a similar amount of play is felt though the entire range. If there are some differences in how it feels, see adjustment section below.
- 6. Install shifter boot back onto center console and reinstall shift knob.
- 7. Recheck shifter mechanism allows all gears to be easily selected and take for a test drive.
- 8. Re-check hardware after a week of driving. Note: It will be normal to find some wear on the plastic part of the shifter.

Make Sure Shifter
Has Roughly 1/4"
Of Play When In Gear

Play Is In The Shifter Hitting The PERRIN Shifter Stop And Moving Toward Neutral

Adjustment of PERRIN Shifter Stops

As mentioned above, NO play in the shift knob can cause damage to the transmission. If you are unable to adjust the PERRIN Shifter Stop so there is the 1/4" or so of play at the knob, then remove parts and do NOT drive the car. If there is excessive play in the knob and you can't adjust it using the below steps, damage to the transmission will NOT occur but this may indicate you have some aftermarket parts you are unaware of or the wrong part number is installed.

Some adjustment may be needed, or some aftermarket part may be installed that you are an aware of.

- If the play is different from the front 1/3/5 gears to back 2/4/6 gears, loosen the (2) M6 bolts and move the entire PERRIN Shifter Stop Assembly front to back slightly to adjust the play to be the same. Make sure to check the left to right shifter stops after any adjustment to ensure nothing has changed and that reverse is NOT selectable during a 5th to 6th gear change.
- There is a slight rotational adjustment of the PERRIN Front and Rear Shifter Stops. Adjusting these can also aid in making all the play in all the gears match.
- If after adjusting all (3) parts, if NO play is found in shift knob, remove parts from car and determine if incorrect part number was purchased or aftermarket parts were installed that you were unaware of. Contact PERRIN Tech Support to help with further trouble shooting.

Questions, Comments and Suggestions Contact: Tech@PERRIN.com
Visit Our Website for Instant Chat Options at www.PERRIN.com
Call Our Tech Team at 503-693-1702