

UC Berkeley researchers who work with pyrophoric materials outside of an inert atmosphere glove box are required to wear:



Protective Eyewear

Fire resistant (FR) Lab Coats

Fire Resistant Liners

Chemical Resistant Outer Gloves



*Contact EH&S to get your fire resistant liners.
ppe@berkeley.edu*