





unplug equipment (use locks and tags,





Remove any small parts that come off and clean and sanitize them following standard procedure





Wash and rinse all surfaces that can't be removed

> Wipe or spray with >> sanitizing solution (make sure it is at the right concentration)





Air dry all parts

Put the equipment back together and re-sanitize surfaces you touched



