

2/85 Trafalgar Street - Garage Partition

Caleb Griffioen <caleb@griffioen.nz>

To: Inspected Residential <adam@inspectedresidential.co.nz>

Wed, Sep 17, 2025 at 3:32 PM

Hey Adam,

As discussed re this partition wall, attached are the following:

- · Photos from when it was put up
- · Original construction plans
- · Email to buyer's agent explaining its construction (for context)
- · The purchaser's building inspection report

I think it'd be helpful to have something to send through and say "this is the advice we've received given the work wasn't completed by a LBP" and let the purchaser make their own decision.

Let me know if you're happy to have a look through.

Cheers,

Caleb

4 attachments



Trafalgar Street 2-85 PPI.pdf 2042K



ownly Mail - 2:85 Trafalgar Street.pdf 56K



[10 124581]378 85 TRAFALGAR STREET Scanned Documents.pdf 241K



2-85TRA - Construction Photos.pdf 1480K



Caleb Griffioen

Caleb Griffioen Owner & Salesperson 027 637 0231

2/85 Trafalgar Street - Garage Partition

Adam Brownie <Adam@inspectedresidential.co.nz> To: Caleb Griffioen <caleb@griffioen.nz>

Wed, Sep 17, 2025 at 5:46 PM

Hey Caleb,

That is all very low-risk work. The best thing to satisfy them would to have had photos of the wall framing and doorway framing. This isn't restricted building work that needs LBP supervision (so long as the doorway hasn't altered any specific systems, i.e. weathertightness, bracing elements, firewalls etc). What they seem to want to know is that the framing installation meets the standard NZS3604, which the only way to tell this now, would be to remove the wall linings, which is a bit overkill. The best case in this scenario would have been to have some photos of the framing work. Essentially, a producer statement and photos would supply good information, but producer statements are also not a warranty or compliance certificate; they are simply an opinion and basic information about what's been completed.

Again, it's all very low-risk alterations by the looks of things, and if they really want to rip plasterboard off to see the framing, that is about all they will be able to do if they are concerned about it.

Best, Image Image **Adam Brownie Managing Director** 027 914 9087 adam@inspectedresidential.co.nz www.inspectedresidential.co.nz **Image Image** From: Caleb Griffioen <caleb@griffioen.nz> Sent: Wednesday, 17 September 2025 3:32 pm To: Adam Brownie <Adam@inspectedresidential.co.nz> Subject: 2/85 Trafalgar Street - Garage Partition