

This is a detailed exploded view diagram of a mechanical assembly, likely a lighting fixture or a similar device. The diagram shows the main body and various components that attach to it, with dashed lines indicating the assembly path. The parts are numbered as follows:


- Main Body and Structural Components:** 1, 2, 3, 6, 11, 12, 15, 19, 20, 21, 23, 25, 30, 35, 38, 39, 42, 43, 44, 45, 46, 47, 48, 52, 53, 54, 55, 56, 57, 59, 60, 61, 100, 102, 103, 104, 110, 111, 112, 113, 114, 115, 116, 117, 118, 119.
- Fasteners and Small Components:** 1, 2, 3, 6, 11, 12, 15, 19, 20, 21, 23, 25, 30, 35, 38, 39, 42, 43, 44, 45, 46, 47, 48, 52, 53, 54, 55, 56, 57, 59, 60, 61, 100, 102, 103, 104, 110, 111, 112, 113, 114, 115, 116, 117, 118, 119.
- Internal Components and Mounting Hardware:** 1, 2, 3, 6, 11, 12, 15, 19, 20, 21, 23, 25, 30, 35, 38, 39, 42, 43, 44, 45, 46, 47, 48, 52, 53, 54, 55, 56, 57, 59, 60, 61, 100, 102, 103, 104, 110, 111, 112, 113, 114, 115, 116, 117, 118, 119.

The diagram illustrates the assembly process, showing how the various components fit together to form the final product. The main body is a long, rectangular structure with a series of circular holes along its length. The components are shown in their relative positions, with dashed lines indicating the assembly path. The numbering is consistent throughout the diagram, allowing for easy identification of each part.

32


EXPLODED DRAWING B

Model No. PETL13716.0 R0416A



EXPLODED DRAWING C

Model No. PETL13716.0 R0416A



EXPLODED DRAWING D

Model No. PETL13716.0 R0416A

