







<b>TITLE:</b> <b>EXP VIEW DWG- BFX LX5 LATERAL TRNR 2 BOX</b>			
<b>DRAWN:</b> J.MORGAN	<b>DOC. PART NO.:</b> 100899-W	<b>PRODUCT SKU NO.:</b> 100899	<b>REV.:</b> B
<b>DATE:</b> 06/11/2019			



**\* When replacing lateral link ref # 24 also send link puller tool ref # 900**



**\* When replacing lateral shrouds ref #s 45, 46, 47, or 48 on an assembled machine also send lateral link puller tool ref# 900 as link must be removed to replace shrouds.**