


# HURUNUI DISTRICT COUNCIL

P.O. Box 13 | Amberley | 7441 | 66 Carters Road | Amberley | 7410  
Phone 03 314-8816 | Fax 03 314-9181 | Email info@hurunui.govt.nz  
Web hurunui.govt.nz | facebook.com/HurunuiDistrictCouncil  
Skype hdc\_customer\_services | twitter.com/hurunuidc



## Solid/Liquid/Fuel Heater Installer's Installation Certificate

Building Consent Number : 210544

Site Address : 4 Coleman Lane, Amberley

Make : Woodsman

Model : Flare

Clean Air Registration Number : 134775

☒ Solid Fuel Heater

☐ Liquid Fuel Heater

☒ Free Standing

☐ Inbuilt

	Yes	No	N/A
The existing chimney has been cleaned prior to installation	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Is the fireplace surround/chimney face junction sealed up with heat resistant material	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
The flue pipe is constructed of austenitic stainless steel	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Seismic restraint has been fitted	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
The flue sections are secured together with stainless steel rivets	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
The flue is secured to the appliance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
The chimney void has been vented at the top	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Is the Solid Fuel Burner and Flue as per the building consent	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Flue joints sealed in accordance with manufactures instructions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Fire safety valve connected and working correctly (diesel burners)	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Flue and appliance clearances have been achieved in terms of the manufacturer's instructions (NZS 7421 or AS/NZS 2918:2001)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
The flue height meets the minimum specified in the manufacturer's instructions, NZS7421, and Regional Council rules	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
The application has been installed and commissioned in accordance with the manufacture's installation and operating instructions (Liquid fuel only)	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
The liquid fuel storage tank and feed system has been installed in accordance with AS1691, or equivalent, and with the requirements of the Council's Hazardous Substances Officer	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Smoke detectors as detailed on the building consent documents are installed	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

If response to any of the items is 'no' please comment :

Water heater – model and part number :

| Jonathan Toulson

(name) certify that the above specified installation has been carried out as described and in accordance with the manufacturers installation instructions and the current approved building code requirements

Installers Signature :

(Installer) Date : 20/9/2022

### RESOURCE MANAGEMENT ACT MATTERS – LIQUID FUEL HEATER

Does the fuel storage tank have secondary containment in accordance with the District Plan  
(NB: Audit monitoring will be carried out)

Yes	No
<input type="checkbox"/>	<input type="checkbox"/>

If response is 'no' please comment why :