Site Inspection Sheet

071693

Application

A C BEAT & N A WILLIAMS STONEWOOD HOMES

PO BOX 11036

CHRISTCHURCH

Issue date

18/02/08

Project

Description New (& prebuilt) House, Unit, Bach, Crib, Town House etc.

Being Stage 1 of an intended 1 Stages

DOMESTIC DWELLING

Intended Life Indefinite, but not less than 50 years

Intended Use 4 Bedroom Domestic Dwelling with Study and attached Double

Garage (202 sqm)

Estimated Value \$239,386

Location SOUTHFIELD DRIVE, LINCOLN

RAPID:

Legal Description LOT 45 DP 364100

Valuation No. 2404002445

Builder



AMENDMENTS	

BCA CODE COMPLIANCE CERTIFICATE CIRCULATION SHEET

OWNER: BEAT, U	JULIAMS			CONS	SENT NO:	O7	1693	
A OFNIT	DO HOMES			ON A	CCOUNT:		ES / N	0
SIG	PECTOR T & C OFFICER SN OFF SIGN OFF	BC SJGNA		CUSTOMER SERVICES	FINANCE OFFICE (For Reconciliate		T/LEA STAT C	
COMPLETED	20109102	Gludd	14/9/08		25.9.08 Of		*	
INTENDED USE (if changed from	m BC):		08					
CUSTOMER SERVICES	INITIAL & DATE	FURTHER	INFORMATIC	N REQUESTED:	*		FI APPROV	/ED:
RECEIVED & ENTERED BY:	TP 8-9-08			nonatoro o manda na m				
CCC SENT BY:	of 1519108							
INSPECTOR	INITIAL & DATE		- 1 105	6 (5)	- P. O D - N	7.6	~	
ALL INSPECTIONS CARRIED OUT	YES (NO) 200/09/08	-> INDECT	DU N. 7:- 1	DOLY CLADIONIC SYS	now LZZ upowier	WIM TT	ZINCLESS.	
ALL INFORMATION INCLUDED	(YES) NO 6 09/09/08							
ALL CONSENT CONDITIONS/NOTES MET	YES) NO DA/OA/OZ							
ENERGY CERTIFICATES PROVIDED	YES) NO LU CA/CA/CZ							
P/S 3's & P/S 4's	YES) NO LU 09/09/08-							
INTENDED USE CORRECT	(YES) NO LU 09/09/08.						WW	
POST BC AND CCC COST								
DATE INITIALS	ADMINISTRATION	UNITS		CESSING / RE-INSPI		UNITS	TRAVEL	MILAGE
3/4/08 Ohmal As bu	uilt MUSS	3	Remspectron	Post wrop.		5		Z
9-6-08 CMS			Reinspection	Post was		4	1	2
LIVER D. EALL			G-IND: SALT	MY DANNALLY ENTS CA	SOLD.F. TIME SHEET.			
20/21/8 73			sitive	, /				
3/2/8			NOT RI	FASY				
	BANGET ALL THE RESERVE TO THE RESERV							
	/						1	
Reconciliation Completed:	Invoice Generated:	Rafiun	d:	No further	action resulting from rec	ongilar		



2 NORMAN KIRK DRIVE PO BOX 90, ROLLESTON 7643 PH: (03) 347 2800 FAX: (03) 347 2799

REF No....

Code Compliance Certificate

071693

Section 95, Building Act 2004

The Owner

Name of Owner: Beat Andrew Charles & Williams Nicola Ann

Mailing address: c/- Stonewood Homes, 47 Waterloo Road,

Christchurch

Street address/registered office:

Phone number:

Landline: Daytime: 341 4981

Mobile: 021 886 693 After hours:

Facsimile number: 359 5952

Email address: nicky.williams@tait.co.nz

Website:

The Building Work

Street Address of Building: SOUTHFIELD DRIVE, LINCOLN

Legal Description of land where building is located: LOT 45 DP 364100

Valuation Number: 2404002445

Type of Work: DOMESTIC DWELLING

Intended Use: 4 Bedroom Domestic Dwelling with Study and

attached Double Garage (202 sqm)

Estimated Value: \$239,386

Location of building within

site/block number:

Building Name: Year Construction 2008

Commenced:

Code Compliance Certificate:

The Building Consent Authority named above is satisfied on reasonable grounds, thatthe Building work complies with the Building Consent

Selwyn District Council Building Consent Authority Signatory

Issue Date: 14/09/08



Code Compliance Certificate Application

(BAM 006)

Date Received:

(Only complete items that are applicable to your project)

APPL	LICATION	大学出	disa Pinakanan
Street Address (or Rapid No if applicable):	Legal Description:	Lot: 45	DP: 364100
244 SOUTHFIELD DRIVE	Valuation Roll Num		104002445
Project Memorandum No. 07/693	Building Consent N		71693
	ESTIC DH	JELLIN) G
Building Consent issued by: (Name of Building Consent Authority) SELWYA	DISTRI	CT CC	DUNCIL
Address Code Compliance Certificate to be posted to			
STONEWOOD HOMES, 47	WATERL	00 RD	CHCH
	OWNER		
Owner's Name: ACREAT & NA WILLIAMS		THE RESERVE OF THE PARTY OF THE	LEW BEAT
Mailing/Billing Address: 244 SOUTHE	IELD DRI	JE LI	NCOLN.
Street Address/Registered Office: AS	BOUE		
E-mail Address:		Phone Day:	
Phone A'Hours: Fax:		Cellphone: O	21359065
THE AGENT Note - The Agent will be the first point of c Authority regarding this application/building	ontact for communication	ns with the Cou all corresponde	ncil/Building Consent nce including all invoices.
Agent's Name: STONEWOOD HOMES Mailing/Billing Address: 47 WATERL Street Address/Registered Office: AS ABO	00 RD, S	OCKBUI	RN CH CH
E-mail Address: John & Stone wood	d.co.n2	Phone Day:	3443687
Phone A'Hours: Fax: 03	3499039	Cellphone: O	272550004
	ERSONNEL		B. ideation Number
Name of Designer: STONEWOOD HO			Registration Number:
Mailing Address: 47 WHTER LOO	RO		
E-mail Address:	0.1	Phone Day:	
Name of Engineer: ELIOT SINCLAIR			Registration Number:
Mailing Address: LEVEL 5 151 KILMO	DREST C	HCH	2701 711
E-mail Address: espaeliotsinclair	.co.n2.	Phone Day:	3794014
Name of Builder: ANGUS CHIS	SHOLM		Registration Number:
Mailing Address: 41 SEVENOAKS D	RIVE CH	CH	
E-mail Address:	. , ,	Phone Day:	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
Name of Craftsman Plumber: CLYNE & BE	NNIE/DAVE	GILLESPIE	Registration Number:
Mailing Address: 33 SHAKESPEARE	RD CHC	1	00178
E-mail Address: - james eclyne-bennie	e.co. n2	Prone Day:	3663058
Code Compliance Certificate Application for application to the Mainland Building Consent Authorities Group.		REGIONIT	an VIMRUESEM BAM 006-V

Code Compliance Certificate Application for application to the Mainland Building Consent Authorities Group.

I NO COPIND WATMINGS KEY PERSONNEL (continued) Registration Number: Name of Registered Drainlayer Mailing Address Phone Day: E-mail Address: Registration Number Name of Registered Electrician Mailing Address: E-mail Address: Name of Craftsman Gasfitter: Mailing Address: E-mail Address: Phone Day: Registration Number: Other: Mailing Address: Phone Day: E-mail Address: Add any additional people on another sheet. NOTES BY APPLICANT (Other notes or comments which you as the applicant may wish to add) SIGNATURE I request that you issue a Code Compliance Certificate for this work under Section 95 of the Building Act 2004. Signed by or for and on behalf of the Owner:

ADDITIONAL INFORMATION TO NOTE:

authorised to act as Agent of the Owner".

Agent


Owner

1. You must submit your Code of Compliance Certificate Application prior to a final inspection being carried out.

Date:

Note: If acting "for and on behalf", please read the following declaration before signing: "I hereby declare that I am

- The Code Compliance Certificate will be based on the approved building consent documents, so any variations to the original approved plans are required to be documented and approved prior to the work being carried out.
- 3. A Code Compliance Certificate will not be issued until all of the information required on this form that is relevant to the job is provided to the Council. This includes all Names, Certificates from personnel who carried out the work, Registration Numbers, Producer Statements, or any other required documents. Refer to our Customer Guide 'Applying for a Code Compliance Certificate' for further details.
- 4. Certificates that relate to energy work (Electrical and Gasfitters).
- 5. The specified systems listed on the attached form are to be contained in the compliance schedule for the building. In the opinion of the personnel who installed them, they are capable of performing to the performance standards set out in the building consent.





Code Compliance Certificate Application



(BAM 006)

Project No:

Project No:

Project No:

Project No:

(Only complete items that are applicable to your project)

	APPL	ICATION		
Street Address (or Rapid No if applicable	e):	Legal Description	: Lot: 45	DP: 364100
244 SOUTHFIELD	DRIVE	Valuation Roll Nu		104002445
	1693	Building Consent		71693
Type of Building work: (eg. Domestic Dwell	ing) DOME	ESTIC DI		
Building Consent issued by: (Name of Building Consent Authority)		DISTR		
Address Code Compliance Certificate	to be posted to:			
STONEWOOD HOM	ES, 47	WATERL	00 RE	CHCH
		OWNER		
Owner's Name: ACBEAT & NA WI	LLIAMS	Contact Person: (if owner is not an indiv	ridual) ANDA	REW BEAT
Mailing/Billing Address: 244	SOUTHE	ELD DRI	VE L	INCOLN.
Street Address/Registered Office:	AS A	BOUE		
E-mail Address:			Phone Day:	
Phone A'Hours:	Fax:		Cellphone: ()	21359065
THE AGENT Note - The Agent will be Authority regarding this				ncil/Building Consent nce including all invoices.
Agent's Name: STONEWOOD	HOMES	Contact Person: (if Agent is not an indiv	idual) JOHA	V BLANKEN
Mailing/Billing Address: 47	NATERLO	O RO, S	OCKBU	RN CH CH
Street Address/Registered Office:	15 ABOU	JE '		
E-mail Address: John & Sto	one wood	.co.n2	Phone Day:	3443687
Phone A'Hours:	Fax: 03 3	499039		272550004
		RSONNEL		
Name of Designer: STONEWO	DOD HOM	1ES		Registration Number:
Mailing Address: 47 WA76	-RLOO F	20	_	
E-mail Address:			Phone Day:	
Name of Engineer: FLIOT &	SINCLAIR	O PARTN	ERS	Registration Number:
Mailing Address: LEVEL 5 1	51 KILMO	REST C	HCH	
E-mail Address: espaeliots	sinclair.	co.n2.	Phone Day:	3794014
Name of Builder:	aus CHIS	HOLM		Registration Number:
Mailing Address: 41 SEVEN	DAKS DE	ZIVE CH	The second secon	
E-mail Address:		, ,	Phone Day:	0274778-270
Name of Craftsman Plumber:	NEOBEA	INIE/DAVE	GILLESPIE	Registration Number:
Mailing Address: 33 SHAK	PSPEARE I	RD CHO	CH.	00178
E-mail Address: - 10mes cclyn	e-hennie	.CO. 02	none Day:	3663058

Name of Registered Drainlayer: Mailing Address: Be-mail Address: Phone Description of Registered Electrician: Mailing Address: Mailin	
E-mail Address: Phone D	Registration Number:
Name of Registered Electrician: Mailing Address: 137 TURNERS RD MARSHLANDS CH E-mail Address: Mame of Craftsman Gasfitter: Mailing Address: SHEFFIELD CRES CH CH E-mail Address: Contenbury GGS & Parachse net no Phone D Other: Mailing Address: Phone D Other: Mailing Address: Phone D Other: Mailing Address: Phone D Other: Motes by APPLICANT (Other notes or comments which you as the applied of the Owner) Signature I request that you issue a Code Compliance Certificate for this work under Section Signed by or for and on behalf of the Owner:	18538
Mailing Address: 137 TURNERS RD MARSHLANDS CH E-mail Address: KJELECTRICA BINGS CO. 22 Phone D Name of Craftsman Gasfitter: GREGG SIMITH/CHNTERBURY Mailing Address: SHEFFIELD CRES CH CH E-mail Address: Contenbury GGS Parachse net no Phone D Other: Mailing Address: E-mail Address: Phone D Add any additional people on another sheet. NOTES BY APPLICANT (Other notes or comments which you as the applied of the Owner) SIGNATURE I request that you issue a Code Compliance Certificate for this work under Section Signed by or for and on behalf of the Owner:	ay: 021229 301
E-mail Address: Name of Craftsman Gasfitter: GREGE SMITH / CIANTERBURY Mailing Address: SHEFFIELD CRES CHCH E-mail Address: Contembury Gas & Parachse net 12 Phone D Other: Mailing Address: Phone D Mailing Address: Phone D Add any additional people on another sheet. NOTES BY APPLICANT (Other notes or comments which you as the applied of the Owner: SIGNATURE I request that you issue a Code Compliance Certificate for this work under Section Signed by or for and on behalf of the Owner: Signature Signature	Registration Number:
Mailing Address: SHFFIELD CRES CH CH E-mail Address: Contenburyggs & paradise net no Phone D Other: Mailing Address: Phone D Add any additional people on another sheet. NOTES BY APPLICANT (Other notes or comments which you as the applied of the Owner: I request that you issue a Code Compliance Certificate for this work under Section Signed by or for and on behalf of the Owner:	CH E3428
Mailing Address: SHFFFELD CRES CH CH E-mail Address: Contenburygas & paradise net no Phone D Other: Mailing Address: E-mail Address: Phone D Add any additional people on another sheet. NOTES BY APPLICANT (Other notes or comments which you as the applied of the Owner) SIGNATURE I request that you issue a Code Compliance Certificate for this work under Section Signed by or for and on behalf of the Owner:	ay: 02743253
E-mail Address: Contendury GGS & Paracise net no Phone D Other: Mailing Address: Phone D Add any additional people on another sheet. NOTES BY APPLICANT (Other notes or comments which you as the application of the Compliance Certificate for this work under Section Signed by or for and on behalf of the Owner:	Registration Number:
Mailing Address: E-mail Address: Phone D Add any additional people on another sheet. NOTES BY APPLICANT (Other notes or comments which you as the application of the comments of the application of the compliance Certificate for this work under Section Signed by or for and on behalf of the Owner:	01061
E-mail Address: Add any additional people on another sheet. NOTES BY APPLICANT (Other notes or comments which you as the applied of the Owner: SIGNATURE I request that you issue a Code Compliance Certificate for this work under Section of the Owner:	ay:3574783
E-mail Address: Add any additional people on another sheet. NOTES BY APPLICANT (Other notes or comments which you as the appliance of the ap	Registration Number:
NOTES BY APPLICANT (Other notes or comments which you as the application of the applicati	
SIGNATURE I request that you issue a Code Compliance Certificate for this work under Section Signed by or for and on behalf of the Owner:	ay:
I request that you issue a Code Compliance Certificate for this work under Section Signed by or for and on behalf of the Owner:	
I request that you issue a Code Compliance Certificate for this work under Section Signed by or for and on behalf of the Owner:	
I request that you issue a Code Compliance Certificate for this work under Section Signed by or for and on behalf of the Owner:	
I request that you issue a Code Compliance Certificate for this work under Section Signed by or for and on behalf of the Owner:	
I request that you issue a Code Compliance Certificate for this work under Section Signed by or for and on behalf of the Owner:	
Signed by or for and on behalf of the Owner:	
	95 of the Building Act 2004.
Owner Agent Date: <u>5/09/08</u>	
Note: If acting "for and on behalf", please read the following declaration before signing: "I authorised to act as Agent of the Owner".	

ADDITIONAL INFORMATION TO NOTE:

- 1. You must submit your Code of Compliance Certificate Application prior to a final inspection being carried out.
- The Code Compliance Certificate will be based on the approved building consent documents, so any variations to the original approved plans are required to be documented and approved prior to the work being carried out.
- 3. A Code Compliance Certificate will not be issued until all of the information required on this form that is relevant to the job is provided to the Council. This includes all Names, Certificates from personnel who carried out the work, Registration Numbers, Producer Statements, or any other required documents. Refer to our Customer Guide 'Applying for a Code Compliance Certificate' for further details.
- 4. Certificates that relate to energy work (Electrical and Gasfitters).
- 5. The specified systems listed on the attached form are to be contained in the compliance schedule for the building. In the opinion of the personnel who installed them, they are capable of performing to the performance standards set out in the building consent.



Code Compliance Certificate Application Checklist (BAM 006-C)

(in conjunction with Code Compliance Certificate Application Form)

PROJECT NO: 07/693 DATE RECEIVED:

Have all the inspections listed in the Building Consent been carried out YES NO. (Please circle)	pe		only .
If NO, please book the inspection/s before proceeding with this application.	Supplied	N/A	I Use
NB The following is required on application in sufficient detail to show compliance with all aspects of the relevant Building Consent. Please complete this Checklist in FULL. Additional information may be requested during processing of the application.	A STATE OF		Council Use only
Application form COMPLETED, dated & signed			1/
Check you have included: Valuation number and Building Consent number	-		\ <u>'</u>
Address CCC to be posted to	-		V/
Current Certificate of Title			~
Key Personnel-			7,
Name, address, phone number, registration number for ALL key personnel			~
Eg. Builder, Electrician, Drainlayer, Plumber, etc.	1 1		
Trade Certificates * - Provided for all Key Personnel	1		
Documentation-			-
Electrical Certificate			1
Gas Certificate		-	4
Pressure test (1500KPA) statement, if requested by Building Inspector		1	1
Producer Statement Construction (PS3) if required by Building Consent conditions			7
Producer Statement Design Review (PS4) if required by Building Consent conditions		1	V
Proof of Potability of water (3 tests results- 1x chemical + 3x Bacteria)		1	W.
Exterior Cladding – Construction Statement required by Building Consent conditions. Eg			/
cated Buildings - Copy of Code Compliance Certificate for the building issued by the		1	
ocal authority whom's district the building was constructed in.		/	
Pile Driving records for driven piles. Septic tanks- Confirmation from Ecan that they have received and approved the certificate	-	/	
of construction from the drainlayer/designer (Compliance Monitoring report)			
Evidence that specified systems are capable of performing to the performance standards set out in the Building Consent including-			
Installers Certificates	-	-	_
FPIS Certificates	1	+	-
Dangerous Goods Location – Test Certificate issued by an ERMA approved test certifier.	7	+	
Approvals from Other Authorities - Approvals for discharges to land, air, or water from	14	1	
Ican, or the like.	1		
IOTE: Once received by the BCA, your CCC application will be considered and either efused within 20 working days. Please note if any further information is requested this	issue s time	d or is	
uspended until that information is received. Refer to Selwyn District Council's guide to applying for a Code Compliance Certificate b			- 1

Netseal,

G:\Regulato\Accreditation\BCA Manual\SDC BCA Manual v1.0.2\Selwyn BCA Manual Section 3 - Standard Forms v1.0.2\Application Forms and

This application is accepted declined as all relevant information has I has not been supplied - signed:-

Checklists\BAM 006-C CCC checklist.doc

Solar Water

For BCA Use Only:-



	101-11		Inspections are	e to be booked by the	owner or builder.		M. Salta	
Name:	+C Be	n + tea	A W	liams	Consent No): O	71693	
No. of the Contract of the Con	ess/Rapid No:	South	field	dave	Officer:	22		
E		~ 1	Linco	Me	Name:	ter	Rober	toon
Type of b	uilding work:	Jomes'	HC D	welling		44.51		
On Building A	5 / Act 2004 [Section	222/230] and t	the Local Gov	at 10:12 vernment Act 2004	am / pm-th 4 [Section 174]. The	is site v ne purp	vas inspected pose of the insp	oursuant to the ection was:-
	a Siting	& Founds	h	Bond Beam			Other	
	b Slab		1	Blockfill	r F		Resource Cons	sent
1 2	c Pre W	ар	j	Heating unit	C		Complaint/inve	stigation
	d Post W	/rap	k	Sanitary drain	nage		Compliance So	chedule
	e Half he	ight veneer	1	Stormwater d	rainage s		WOF/ c/s audit	
	f Preline	/Plumbing	m	Pile/pole hole	s t	V	Final	Pass
	g Post li	ne bracing	n	Cladding	ι		Inspection	□ Fail
BUILDING	WORK	MAY PROCE	ED D N	MAY NOT PROCE	ED 🗆 RE	-INSPE	CTION YES	S NO D
INSPECT	ON NOTES:							
	Da		to = !	to bot	Anal 1	1510	schion	
6		1 0 1	100				S 17 1	1 1 1
0	Gas ce	This is			espure to			rical certain
(4) I	S4-from	enother	- (S) P	Sfrom So	lor heating	inst	aller (6)	Construction
TI	\ (1	1 1	111		L. F	11/2/201
Slat	ement t	rom e	verior	plastaring	cladding	sys	olem-(1)	mersear
stoot	ement t	ram app	licator					
				11				
S	make	alam	s inc	lace, a	ton M	نص	her val	wing
5 80	MANE IN	stran	to in	place to	Hotwa	ter	Culinda	- temporal
eco		1	10		7.07	1	7	
20	LETTO	ctor u	WITZ	wanne	y art th	2 9	me of	inspection
Sa	Jar Day	rele 1	no lace	e and	connected	d .	to H.L	J.C.
- C	all a	ass w	where	as requ	1 1/	0 1	andscar	p implace
	and a	()	1	KI			D	L'art man
a	+ time	91	rspeo	tion. al	1 work	28	ber 191	ulding
Ca	reent	plan's	15	S from	plaster	ha	5 0000	ide
	1.0.00	Till	1 - 0 -	1	VPC	17.00	1	1891-11
CON	phance	WIIN	Mape	ection !	1-0.			
						, Ui	TEDI	PM I
NOTE	A Contra Consultan	an Cartificate	Vanlination in		Quilding Act Conso	FN	711218	710
					Building Act Conse		111711111	
Owner/Bu	ilder/Contractor	confirms floor h	eight is as rec	commended by Env	vironment Canterbu	iry		
INSTRUC	TIONS						73 (0-1)	
All work in	spected is in acc	ordance with the	e Building Co	onsent		H		
Satisfacto	ry: Work may pro	ceed when mir	or items abov	ve have been atten	ded to	16 2		
Some wor	k is not satisfact	ory or is incomp	lete, as detail	led above, and rec	tification is required	d.		
A notice to	fix will be issue	1		SUMBALE !		, ,	,	/ 0
Notice to:	Contractor 💆	Owner	Agent 🗆	Occupier	Signed:	7	1.	1
By:	Telephone □	Fax 🗆	Posting	Left on Site □	///	11	lma	on-
-1.	. O.Op. Torro LD		9		///	1./	/ -	

EPALTO MACIN 2 months of AM + two 81 J.A montaded also MUGACIONAL DHAMMEG Does was the state of the loss of the loss of the contraction of the state of the contract of the state of the contract of the state of the contract of the co . Totolygo mind know totolo produce retain too the people in smale alone signic reducted the state of society extraction amore consistency of the test of society extraction of the state of the society extraction of the state of the society extraction of the state of the society explains of the society of the so

PRODUCER STATEMENT PS3 INSTALLATION OF SOLA WATER HEATING SYSTEM.

COUNCIL SELWYN DISTRICT
BUILDING CONSENT NO. 071693
PRODUCER STATEMENT ISSUED BY James, A. Palmer Ltd. (Suitably qualified sola water heating system installer)
ADDRESS OF INSTALLER 99 Clarence St. Riccarton
TELEPHONE NUMBER OF INSTALLER 03)3481-899
PRODUCT AND MODEL NUMBER Green-Glo 3005 2x Titan
SUPPLIER OF PRODUCT. Schar lech (Auckland) Hemium per
REGISTERED PLUMBER (IF APPLICABLE) W. LeBryn REGNO 14746
ADDRESS OF PROPERTY ON WHICH INSTALLED Lot 45/244 Southfield
LOCATION OF INSTALLATION NH FACING 1004 Drue
LOCATION OF INSTALLATION IN TUCH GIRLON ROOT
OWNER OF PROPERTY (ON WHICH INSTALLED). WITLIAMS / Beat PROPERTY DESCRIPTION: LOT. 45 DP. 244 Southfield chive
The system has been installed such that the requirements of New Zealand Building Code have been met. Plumbing work has been installed to meet the requirements of standard AS/NZS3500.4.
REGISTERED PLUMBER SIGNATURE W. January Date 25.8.08
The sola water heating system described above has been installed on a dwelling on the named property according to the Code of Practice for Manufacture and installation of Sola Water Heating Systems in New Zealand and the requirements of the building consents.
The system has been located as shown on the drawings provided with the Building Consent Application. A check has been made by a suitably qualified person to ensure that the system is located over suitably sound load bearing walls and strengthening of roof framing has been undertaken according to the guidelines provided by the system supplier and meets the requirements of Approved Document BI of the New Zealand Building Code.
formula and instructions from the Product Supplier who is a Sola industries

The installation has been undertaken in terms of manuals and instructions from the Product Supplier who is a Sola industries Association Accredited Supplier.

I certify that I have been appropriately trained in the installation of the named Product by the Product Supplier and operate under that Suppliers accreditation. As an inderpentant sola water heating system installer I am covered by a current Professional Indemnity Insurance Policy to a current value of \$.....

Installers signature W.J. Lun Date 25.8.08



Installation Certificate

Independent Franchisee of the Wet-seal Franchise System ("Wet-seal Franchisee"): Gallagher Waterproofing Limited

PO Box 609, Rangiora, North Canterbury Christchurch 7400

Invoice #:BE0294 Job Date: 05/08/08

Stonewood Homes PO BOX 11036 CHRISTCHURCH NZ Christ

Installation Address:

Lot 45 Southfield Drive Lincoln NZ 8152

THIS CERTIFICATE given by the Wet-seal Franchisee certifies that; (a) the installations scheduled below ("Work") have been carried out at the above premises ("Premises") using the appropriate Wet-seal system of waterproofing; (b) the Work has been undertaken by the Wet-seal Franchisee; (c) the Wet-seal system of waterproofing used in the Work (i) compiles with Australian/New Zealand Standard 4858; (ii) in respect of the Work carried out in Australia compiles with Building Code of Australia (BCA) as amended and complies with Australian Standard 3740; and (iii) in respect of the Work carried out in New Zealand complies with clause E2 (external moisture), clause E3 (internal moisture) of Compliance Document for New Zealand Building Code; (d) the Wet-seal system of waterproofing and the products used comprised in the Work have been (i) tested in respect of application and/or use in Australia by the Commonwealth Scientific and Industrial Research Organisations (CS1RO) as meeting the requirements of Australian Standard 4992; and (ii) appraised by BRANZ as appropriate for use in New Zealand.

For the Terms and Conditions, Special Conditions and Explanations please see the Wet-seal website www.wet-seal.ws. Any unauthorised alteration to this Certificate will invalidate it completely. 15 Years Workmanship Guarantee. Certificate will invalidate it completely.

Installations ("Work"):

Area:

Location:

Shower Type: Bath Type:

Notes:

BATHROOM

Ground Floor

FOOT

Bath OverFlashed

I understand this Producer Statement will be relied on by Council to confirm compliance with the Building Code and/or conditions of the Building Consent to which it relates.

Steen LA


Steven Gallagher - authorised signatory for and on behalf of Wet-seal Franchisee





Warranty - The Wet-seal Franchisee warrants that the Work has been completed in a proper and workmanlike manner. The franchisor ("Franchisor") of the Wet-seal system is not liable in any respect under this warranty and the Wet-seal Franchisee's liability is limited to the costs only of removing and replacing affected installations. In the event of any warranty claim being made the Wet-seal Franchisee has the right prior to being obliged to carry out any remedial work, to gray the Framises (together with inspectors and/or advisers including but not limited to the Franchisor) and to inspect the Work and to carry out such remedial work as it deems fit. This warranty does not cover damage to the Work caused by any third party.





GASFITTING CERTIFICATION CERTIFICATE

(Pursuant to the Gas Act 1992 and the Gas Regulations 1993 and amendments)

ENERGY WORK CERTIFICATE

(Pursuant to the Building Act 2004)

This certificate is not transferable

Level 9, 70 The Terrace

PO Box 10655, Wellington

Tel 04 494 2970, Fax 04 494 2975

www.pgdb.co.nz

Consumer:

Williams / Beat 244 Southfield Dr

Certificate Number:

619406 On Gas

Domestic

Test Results:

7 min Duration

7.00kPa test pressure

0kPa Loss / Gain

2.75kPa Working pressure

Lincoln

Type (Regulation 24(1)): NEW

LPG

Gas Type:

Category:

Gas Supplier:

Other Testing:

Test Date:

19 Aug 2008

Vehicle Registration: Vessel Registration:

Installation Address:

Certification Date:

27 Aug 2008

DESCRIPTION OF GASFITTING TO WHICH THIS CERTIFICATE APPLIES

Qty	Item Type	Item Location	Make/ Model	Input Rate	Flue Type	Flue Location	Vent Type	Vent Location
1	Freestanding cooker	Kitchen	DeLonghi	39.3mjh				

Registered Gasfitter / Supervised by certifier

Registration No:

Name:

Registration No:

Name:

Certificate Owner

Registration No: 01061

Name:

Smith, Greg J

Company:

I certify that:

- 1. I Certify that all appliances and fittings worked on by me or by persons working under my supervision are safe and that all work carried out was in accordance with all applicable requirements of the Gas Act 1992 and Gas Regulations 1993 as ammended.
- 2. I Certify that the Gasfitting to which this certificate applies does not make other parts of the installation unsafe or otherwise non-compliant with the Gas Act 1992 and Gas Regulations 1993 as ammended.
- 3. I Certify that the Gasfitting work to which this certificate applies does NOT include work on an appliance or fitting imported or manufactured for the consumers use.

Signed:

Certifier

Registration No: 01061

Name:

Smith, Greg J



Company Name:

ENVIRONMENTAL POLICY & APPROVALS UNT BUILDING CONTROL

CONSTRUCTION STATEMENT- PIPEWORK TESTING

Selwyn Dis	strict Council		
P.O Box 9	0, Rolleston		
Fax 03 347	2799		
Building Co	onsent Number:	071 693	
Issued by:		JAMES	COWLES ON BEHALF OR CLYNE & BENNIE LTD
(Registered Craft	sman Plumber)		
For:		NICKI W	VILLIAMS AND ANDREW BEAT
(Owner)			
In respect	of the testing of water	pipework	prior concealment
At:		244 SOL	JTHFIELD DRIVE
(address)			
I hereby state	e that I have personal	ly tested t	he water pipework installed in the building
20			nt by the method indicated hereunder:
			for a period of not less than 15 minutes for the hot and there are no leaks. (NZBC G12/AS1 7.5.1 (a), (b).)
By press	surising the upvc. Pipew	vork to 1.5	times the maximium working pressure for a period of at there are no leaks (NZBC G12/AS1 7.5.2, NZS 7643)
			for a period of not less than 5 minutes and checking to M1, AS3500: Part 1.2 1998)
For sanitary fi	xtures used for peronal	hygiene, I	confirm that the tempering valve has been set so as to
not exceed:			
	the programmer of the programmer and the programmer		ols, old people's homes, institutions for people with pitals. (G12/ASI 6.14.1 (a))
✓ 55°C fo	or all other buildings. (G12/ASI 6	6.14.1 (b))
And I believe	e on reasonable grour	nds that th	e pipework has passed that test.
	k complies with the NZ		
			cil in accepting this producer statement will be
			cate at the completion of the building work.
Signature of	Craftsman Plumber:		Janes Carles
Date:			01.06.08
	Pagistration No:		11827

Clyne & Bennie (1988) Ltd

99%

27-AUG-2008 10:02



Our Ref .: 286079

18 February 2008

Land Surveyors
Civil, Structural, Geotechnical &
Environmental Engineers
Resource Management Planners
Land Development Consultants
Hydrographic Surveyors

Level 5, 151 Kilmore Street PO Box 4597 Christchurch 8140 New Zealand Telephone (03) 379-4014 Fax (03) 365-2449 Email esp@eliotsinclair.co.nz www.eliotsinclair.co.nz

PRODUCER STATEMENT - CONSTRUCTION REVIEW Clause B1 Structure

To:

Selwyn District Council Private Bag 1 LEESTON 7656

FOUNDATION TRENCH FOR WILLIAMS AND BEAT HOUSE

244 (LOT 45) SOUTHFIELD DRIVE, LINCOLN

I, Richard HJ Wilson, an Engineer, Member of IPENZ, and an Associate with Eliot Sinclair & Partners Ltd., have been engaged by Stonewood Homes Ltd to confirm the adequacy of the perimeter foundation trench soil bearing conditions in respect of the requirements of Clause B1 of the Building Regulations 2004.

As an independent design professional covered by a current policy of Professional Indemnity Insurance to a minimum value of \$200,000.00, I confirm that personnel under my control have carried out periodic reviews of the work appropriate to the engagement. Based upon these reviews and information supplied by the contractor during the course of the works, it is my opinion that the work has been carried out in such a manner as to meet the relevant requirements of Clause B1 and to satisfy the intent of our design as detailed in our 'Producer Statement - Design' reference 286079 dated 10 October 2007.

Signature

Richard HJ Wilson

BE, MIPENZ

C.C.

Stonewood Homes Ltd PO Box 11036 Sockburn CHRISTCHURCH 8443

286079-006P-rhjw.doc

PRODUCER STATEMENT

20046

WORK COMPLETED BY: Contable of Brick & Blocklaying Add (Licensed Plaster Systems Contractor Name & Licence No.)
TO: Standwood Homes (Owner)
TO BE SUPPLIED TO: Selways District Carcil 011693 (Territory Authority)
IN RESPECT OF: Homm Insculcted Cavity System finished a space ready to pain (Description of cladding system installed)
CLADDING SYSTEM BRANZ APPRAISAL No.: 453 (Appraisal Certificate No.)
AT: 244 Southfield Deive (Address of site)
DATE OF COMPLETION OF WORK: 31 7 2008
The Plaster Systems Licensed Contractor certifies that this project has been completed with materials that meet Plaster Systems Limited specifications and that all the work has been carried out in accordance with Plaster Systems Limited installation instructions and current BRANZ Appraisal Certificate.
If the System is used and installed in accordance with the statements and conditions of the Systems Appraisal Certificate the following NZBC Clauses will be met: B1 Structure; B2 Durability; E2 External Moisture; E3 Internal Moisture; F2 Hazardous Building Materials; and H1 Energy Efficiency.
This Producer Statement does not cover the suitability or stability of the site or the products or systems applied by trades other than those of the Licensed Plaster Systems Contractor.
NAME: CBB Ud
SIGNED: Mbugui DATE: 31/7/2008





1173	A. C. B. S.	Ten a	Inspections are to	to be booked by the owner	or builder.		AND THE	100
me: A	- C Beat	+ NA I	Williams	<u> </u>	Consent No	0	7/693	
	ess/Rapid No: 5							A. T.
1000000			coln				1 Stars	
pe of bu	uilding work: D		200					F
	01 10	71	08 8				as inspected pose of the insp	
Га	Siting &	Founds	h	Bond Beam	0	1	Other	CONTRACT OF
b		Tourido	11	Blockfill	р		Resource Cons	sent
C		D		Heating unit	a		Complaint/inve	stigation
d		,	k	Sanitary drainage	r		Compliance Sc	
е		ght veneer	1.1	Stormwater drainage	s		WOF/ c/s audit	2-4-0-
f		Plumbing	m	Pile/pole holes	t		Final	□ Pass
0		bracing	n	Cladding	u	_	Inspection	□ Fail
LDING		MAY PROCEE		AY NOT PROCEED		NSDEC	CTION YES	S O NO E
	for files. Braceing markings	g pon	els his	in bathro	dicated	h	, flo	or
	Bracery	t con	els fi	pred as Ins	dicated	hy	, flo	or
OTE: A	Braceing markings	t Con	els from sent pu	ned as in	Act Consent	by war	, flo	or
OTE: A	Bracery markings Code Compliance Ider/Contractor co	t Con	els from sent pu	quired for 2004 Building	Act Consent	by war	, flo	or regune
OTE: Anner/Buill	Bracery markings Code Compliance Ider/Contractor co	t Con	els fransent pu	quired for 2004 Building	Act Consent	by war	, flo	or regune
OTE: Anner/Buill TRUCT	Bracetry markings Code Compliance Ider/Contractor corrions spected is in according to the contractor of the contractor	ce Certificate A	application is receight is as recor	quired for 2004 Building	Act Consent	by war	, flo	RED
OTE: Anner/BuillitTRUCT	Bracery markings Code Compliance Ider/Contractor cor rions spected is in accor y: Work may process	ce Certificate A confirms floor he ordance with the ceed when mine	application is receight is as recorder Building Consor items above	quired for 2004 Building mmerided by Environments	Act Consent	by war	, flo	regun
OTE: Anner/Buill STRUCT work insisfactory me work	Bracery markings Code Compliance Ider/Contractor cor rions spected is in accor y: Work may process	ce Certificate A confirms floor he ordance with the ceed when mine	application is receight is as recorder Building Consor items above	quired for 2004 Building mmended by Environmensent have been attended to	Act Consent	by war	, flo	or regume
OTE: Amer/Buill TRUCT work insersactory seasons work	Bracetry Markings Code Compliance Ider/Contractor cor IONS spected is in accor y: Work may process is not satisfactor	ce Certificate A confirms floor he ordance with the ceed when mine	application is receight is as recorder Building Consor items above lete, as detailed	quired for 2004 Building mmended by Environmensent have been attended to	Act Consentent Canterbur	by war	, flo	RED

MAPSCHOW HOTTICE

everture.

OBABITMB ENTERED



Building Consent Inspection Prompt Sheet Postline Inspection

(BAM 205)

	PROJECT DE	TAILS					
Building Consent No. 07/	693	Site Copy	Viewed:	/	Yes		No
Inspector's Name: Guff 54	'a-				****	1	
Time Arrived: /1-00 HM	Time Departed:			ate:	1-07	-08	

		ITEMS INSPECTED
Bra	cing	
1	Edge Nailing	V Fireline garge Right side was
- 1	Bracing Material Type	I Standard gib in Ballion + Enga
-	Ceiling Diaphragms	× No Fixing for hly

This is not an inspection record, it serves as a prompt and simply indicates that the items listed have been inspected. The Inspection Notice (BAM 130) provides the record of items inspected and decisions made with respect to progression of building work, together with reasons for these decisions as inspection notes.



-/12			Tau/a	Inspections are	e to be booked by the o	wner or builder.		Less		14-
Name:		Re	et l			Consent	No:		07/69	3.
Site Ad	dress/Ra		Sou	the Pelo	10	Officer:				
751		18 14		4-0	dn	Name:		1	300d	
Type of	building	work:	0	cellia			FL			
On Building	2 Act 200		6 / 222/230] and t	o8 the Local Gov	at ernment Act 2004				as inspected pose of the insp	
[a	Siting &	Founds	h	Bond Beam		0	1	Other 6	TELD
	b	Slab	CHE (Blockfill		р		Resource Cons	sent
	c Pre Wrap j Heating unit q Complaint/i							Complaint/inve	stigation	
	d	Post Wr	ар	k	Sanitary drainag	ge	r		Compliance Sc	hedule
	е	Half hei	ght veneer		Stormwater dra	inage	s		WOF/ c/s audit	
	f	Preline/l	Plumbing	m	Pile/pole holes		t		Final	□ Pass
100	g	Post line	bracing	n	Cladding		u		Inspection	☐ Fail
BUILDIN	NG WOF	RK N	MAY PROCE	ED D N	MAY NOT PROCEE	D D	RE-IN	ISPE	CTION YES	O NO D
7	POX Cellus SF)	Seed Sonc		from Join	barra	From rection 70>	es.	13	oh finbe	Shoot
•	700	loc.	- Re	and he	e pipes		P.	de	of as	to pla
- 1	-210	ile H	rend	bon	e e to	-e of		1-	speno	
F	-0-	ent	-	2057	concerto	~		3/0	Med-	
*	-sul	ere c	ceiling	done	- Con C	da	9	. ,	>11-0	5 000-
*Pr	35000000			+ + 0 =	cer to	- 66-	6	-	5	
	choice	- 120	0 kps	1031	7					
NOTE	: A Code				equired for 2004 Bui	ilding Act Con	sents	F	MTC	DEM
		Compliano	ce Certificate /	Application is r	equired for 2004 Bui			F	MTE	RED
Owner/B		Compliand	ce Certificate A	Application is recipit is as reci			rbury	F	INTE	PED.
Owner/B	Builder/Co	Compliand	onfirms floor h	Application is recipit is as reci	ommended by Enviro		rbury	1	ENTE.	DED.
Owner/B INSTRU All work	Builder/Consider/Cons	Compliand ontractor co	ce Certificate A	Application is recipitation is recipitation is as reconnected to the second control of t	ommended by Enviro	onment Cante	rbury	1	Ser -	PED.
Owner/B INSTRU All work Satisfact	Builder/Constitution inspecte tory: Wor	Compliance contractor co	onfirms floor hard with the	Application is recipitation is recipitation is as reconnected to the second control of t	ommerided by Environment of the commerce of th	onment Cante	rbury	1	Se -	-/
Owner/B INSTRU All work Satisfact Some wo	Builder/Co CCTIONS inspecte tory: Wor ork is not	Compliance ontractor co d is in acco k may process satisfactor	onfirms floor hard with the	Application is recipitation is recipitation is as reconnected to the second control of t	ommerided by Enviro	onment Cante	rbury	1	Ser -	6
Owner/B INSTRU All work Satisfact Some wo	Builder/Co CTIONS inspecte tory: Wor ork is not to fix will	Compliance contractor co	onfirms floor hard with the	Application is recipitation is recipitation is as reconnected to the second control of t	nsent e have been attended above, and rectific	onment Cante	rbury	1	Se -	6

arul 2

· Sind District Victorian And I State Committee Committe	
	aground the agreement
	and the second of the
MTGSS-	



			Inspections are	to be booked by the	owner or builder.	134	A Second Control	
Name: A	-c Beat	1 NA U	Villiamo		Consent	No: /	071693	
G-SOCAL BALLOCA		- 24 4	1 4	ie				
one Addre	33/14apid 140	,	oln				If Steven	rson
Type of bu	ilding work:	-	100	Miza				adire i E
On	16 10	06 10	8	at /-36	am-/ pm	this site	e was inspected p	oursuant to the
Building A	ct 2004 [Section 2	22/230] and t	ne Local Gov	ernment Act 2004	[Section 174]	The pu	irpose of the insp	ection was:-
а	Siting & I	Founds	h	Bond Beam		0	Other Poly	Batters.
b			i	Blockfill		р	Resource Cons	7/ 1
c Pre Wrap j Heating unit q Complaint/investigation								
d	Post Wra	р	k	Sanitary draina	age	r	Compliance So	chedule
е	Half heig	ht veneer	1	Stormwater dr	ainage	S	WOF/ c/s audit	t
f	Preline/F	lumbing	m	Pile/pole holes	3	t	Final	□ Pass
g	Post line	bracing	n	Cladding		u	Inspection	☐ Fail
BUILDING	WORK N	IAY PROCE	ED 🗷 N	IAY NOT PROCE	ED 🗆	RE-INS	PECTION YES	S D NO D
INSPECTION	ON NOTES:							
	Contracto	- 10	ensure	metal	Hashi	25	15 125+	alled
	4 11		/	1	. 11	1	1.41	
	To gas	pef	00 (0)	mung	with 1	oory	patters	
	Flashings	12	place ,	to wordow	5. Poly	bu,	Itens mo	sty in
				to boti				
	pine.	caving	01-1	10 2011	v m			
* V	Items	to be	checke	d from	last	(ns)	rector of	akd
-	11-0	1.	-111	not been		11	/ Ph.	. /
19								real
	John 1	Blanken	+ 10	It messag	ge on h	15	plone.	
				egiried				Conections
-								
-	to post	ord	5120 0	of holes	at i	base	of pos	t when
	they ka	ue bee	n comp	of holes	as pe	- 1	consent p	lans
							/	
-								
						E	MTPPM	FID
. 10						ICI	NIPR	
THE STATE OF THE S							10 11 12 11 17 1	S W
NOTE: A	Code Compliano	e Certificate /	Application is r	required for 2004 B	uilding Act Cor	sents		
Ourner/Puil	dar/Contractor of	nfirms floor h	pight is as roc	ommerided by Env	ironment Cante	rhury		
	Many Market	TIIIITIS 11001 TI	eight is as rec	ommended by Env	nominant oant	, ibuiy		
INSTRUCT			- " -					
	spected is in acco						7000	
Satisfactor	y: Work may proc	eed when mir	or items abov	e have been attend	ded to			
Some work	is not satisfactor	y or is incomp	lete, as detail	ed above, and rect	ification is requ	ired.	* Front	city.
A notice to	fix will be issued	,				^	1 3 3	
Notice to:	Contractor	Owner	Agent 🗹	Occupier	Signed:	1 10)	
By:	Telephone 🗹	Fax 🗆	Posting	Left on Site □		10	5.	

BOLTON MOTORING

ENTERED



	ISTATET C		Inspections are	to be booked by the	owner or builde	r.	-	1 11	
Name A	C Beat	+ 1/1	101100	•	Concor	at No:	A	71693	X TO T
(All the state of	The second secon					Officer: 23			
Site Addre	ss/Rapid No: 5			ive				- Steven	* C A
T ()-	ilding work:	Lincol		1112	Name	0-6	eff	- Still,	isin
				at 3-06	om / pr	n thic	cito w	rae inenected n	ireliant to the
Building A	ct 2004 [Section 2	22/230] and the	he Local Gov	ernment Act 2004	Section 174]. The	purp	ose of the inspe	ction was:-
a	Siting &	Founds	h	Bond Beam		0	~	Other pre 1	plaster.
t	Slab		i	Blockfill		р		Resource Conse	
C	Pre Wra)	j	Heating unit		q		Complaint/inves	tigation
C	Post Wra	ар	k	Sanitary drain	age	r	1	Compliance Sch	nedule
6	Half heig	ht veneer		Stormwater d	rainage	s		WOF/ c/s audit	Part of the
f	Preline/F	Plumbing	m	Pile/pole hole	S	t		Final	□ Pass
g	Post line	bracing	n	Cladding	W.	u		Inspection	☐ Fail
BUILDING	WORK M	AY PROCE	ED 🗆 N	MAY NOT PROCE	ED 🗹	RE-II	NSPE	CTION YES	□ NO □
	Polystypes PVC win	re cl	ladding t both pereba	fry for flash	l as lings in	reg p	lac	red. Seali	ing of
	Inspect	ion seg	Jured	instaled for co	over	bal	gas Kas	age d	
<u>پ</u>		or of	1	prver to system			9	Linea	cont
NOTE: A			Application is r	required for 2004 E	Building Act Co	nsents	5	PNTE	DICIN
				ommerided by Env					区区山
INSTRUC	TIONS								
All work in	spected is in acco	rdance with th	ne Building Co	nsent	A-7- 11-				9
Satisfactor	y: Work may proc	eed when min	or items abov	e have been atten	ded to			7 1.71	
	A CONTRACTOR OF THE CONTRACTOR			ed above, and rec		uired.			
	fix will be issued			ALL PROVED			- 1.5	0 6 4	
Notice to:	Contractor 🖫	Owner 🗆	Agent	Occupier	Signed:	<u> </u>		PH P. V	
By:	Telephone	Fax	Posting	Left on Site	75	of	1	a 35.0	

Tropy and the Same of the	chart with the stall is a
	THE RESERVE OF THE PERSON OF T
	the layer was a
asaes a	

Window installation to check ventilation, air seals, and glazing.

NOTE:- All drainage work must be inspected prior to backfilling.

Inspection and testing of sanitary sewer.

Connection to sewer lateral.

Stormwater disposal connection to street lateral.

Spouting including rain water heads, overflows and downpipes.

Check nailing off bracing panels before stopping work is carried out.

Inspection of fire rated construction including fixings and penetrations.

Inspection following application for Code Compliance Certificate. (The cost of the Code

Compliance Certificate is invoiced separately).

Domestic mechanical ventilation.

Hot water reticulation valving.

Check temperature of hot water.

Seismic restraints to hot water cylinder and storage tanks.

Smoke alarm installation.

Standard and

Non-Standard PIM Notes

None found

Inspections

Type I5 Inspection 5

Inspected NO

3rd cladding

Type I6 Inspection 6

Inspected NO

pre line

Type I8 Inspection 8

Inspected NO

pre stop wet areas

Type 19 Inspection 9

Inspected NO

final

Type SI SITING - C3 C03

Inspected 20/02/08
Officer Tim Bowyer

SITING

Siting only - As per consent plan. Contractor identified boundarys. Attached Engineers report.

Type SL SLAB - C6 C06

Inspected 28/02/08

Officer Christopher Westwood
Result Building Work May Proceed

Plans on site.

Fill rounds 200deep covered by DPM with D10 starter. No mesh, poly covering everywhere but garage. Shrinkage rods in place. All penetrations

sealed and lumber lock ties in place.

Looks ok.

Type SDS SANITARY DRAINAGE / STORMWATER - C14 C19 C14

Inspected 3/03/08

Officer Christopher Westwood Result Reinspection Required

DRAINAGE Not Ready!!!

Type PW PRE-WRAP - C61 C06

Inspected 9/04/08

Officer Peter Robertson

Result Building Work May Proceed

control joints valleys pre wrap

*1. SP1 straps to have 3.15x30 nails.
*2. Type C lintel straps to be fixed off with

3.15x30mm nails, see As built.

*3. CT200 to have 3.15x30mm nails internal only

see As built.

*4. 12 kn fixing require to firewall studs as per

winstone requirements.

*5. Roof strap bracing yet to be fitted.

All ply bracing as per bracing plan. all remaining top plate, lintel and truss connections in place.

Purlins fixed to high wind.

Items 1-5 to be completed by postwrap.

Type SDS SANITARY DRAINAGE / STORMWATER - C14 C19 C14

Inspected 5/05/08
Officer Daryl Fortuin

Result Building Work May Proceed

Drainlayer Daniel Piperite Reg No. 18538.

All pipes laid on chip.

All junctuons and inspection points in place as shown on as built plan provided by Drainlayer.

100mm dia. stormwater and 100mm dia. sewer lines.

Gradient: 1:80.

Venting: 1 x MV and 1 x AAV

Sewer to street lateral.

Stormwater to street lateral by means of a bubble

up sump. Test OK.

* Ensure lateral is clear.

Type PSTW POST WRAP C06

Inspected 19/05/08 Officer Todd Boyd

Result Reinspection Required

Building wrap - Tyvek.

Horozontal banding tape in place.

Aluband flashing tape to window, door openings as per requirements. Meterbox sealed to wrap. 2x heat pump penetrations through wrap in conduit

and sealed.

* No plumbing taps ensure sealed around when installed.

* Gable over front entrance, wrap yet to complete

and post to beam connections to do.

* Column and front entrance footings to be

inspected.

* WRAP TO FIRE WALL TO BE FIRE RETARDENT PRODUCT

AND BOTTOM PLATE FIXINGS TO COMPLETE.

* SOLID BLOCKING TO UNDERSIDE OF ROOF REQUIRED.

* PLY STRAPS TO DO.

* CONTRACTOR ADVISED OF ISSUES.

Type PSTW POST WRAP C06

Inspected

28/05/08

Officer

Geoff Stevenson

Result

Reinspection Required

* Doct fings to entry ten still

* Post fiings to entry top still to be completed
* Footings to posts front entry to be completed to

the details shown on plans sheet 11

* DPC to exterior joinery still to be installed a turn out at bottom required to form a drip edge * All future penetrations in wrap to be sealed * Solid blocking to be completed to soffit fire wall back of garage wrap to fire wall is now fire retardant. Bottom hold down fixings in place. Ply

straps completed

Have spoken to John Blanken Stonewood Homes

reinspection required.

Type

PSTW POST WRAP C06

Inspected

9/06/08

Officer

Geoff Stevenson

Result

Building Work May Proceed

POST WRAP

Items to be completed from inspection dated 19/05/08 & 28/05/08 have now been completed.

1. Except posts fixings top at front entry & footings to be inspected at batten inspection.

Type

OT OTHER Z

Inspected

12/06/08

Officer

Todd Boyd

Result

Reinspection Required

PIL/POLE HOLES / BATTENS

2 x pole holes for columns at front entrance 500 x

500mm as per plan.

Contractor to ensure depth required is maintained

prior to pour.

Battens for polystyrene and summit board yet to

install

Reinspection required for battens, flashings and

post fixings to beam front entrance.

Type

OT OTHER Z

Inspected

16/06/08

Officer

Geoff Stevenson

Result

Building Work May Proceed

POLY BATTENS

Contractor to ensure metal flashing is installed to gable before continuing with poly battens. Flashings in place to windows. Poly battens mostly

in place. Cavity open to bottom.

*1. Items to be checked from last inspection dated 9/06/08 have still not been completed. Phoned John

Blanken & left message on his phone. A reinspection is required to check Bomak Connections to post and size of holes at base of post when they have been completed as per consent

plans.

Print Summary

Standard and

Non-Standard CCC Conditions

None found

Work to be Stopped

and

Notice to Fix Conditions

None found

RM Certificate

None found

Letter 1 and

Letter 2 Paragraphs None found

Images

Napier Computer Systems Limited. Copyright © 1997-2008, all rights reserved.



Selwyn District Council **Building Consent Enquiry**

Prev Change, Inspection Load, Create Invoice, Print Forms, Print Letters, Search, Resource Consent Next Search (Change Log)

> PIM/Consent No. 071693 Related Pim/BC No.071693A Related Pim/BC No.071693P

The Building

Valuation No 2404002445

General Property Enquiry

Street Address

** SOUTHFIELD DRIVE, LINCOLN

Legal Description

LOT 45 DP 364100

Floor (m2)

202

Current Status

Special Note 23/05/08

AMENDMENT POSTED

Process Days

Taken To Issue

16

Zone

Lincoln Living 1

The Owner

Name

A C BEAT & N A WILLIAMS

Mailing Address

11 EPPING PLACE HUNTSBERRY

CHRISTCHURCH

Mobile Phone

021 886 693

Daytime Phone

341 4981

Fax

359 5952

E-mail

nicky.williams@tait.co.nz

The Agent

Name Contact STONEWOOD HOMES

MEGAN BREMNER

Mailing Address

PO BOX 11036

CHRISTCHURCH

Daytime Phone

3491 314

Fax

349 9039

E-mail

megan.bremner@stonewood.co.nz

Debtor

BC071693

Balance

\$ 0.00

Invoice

57013

Job Costing

BC071693

Building Work

Type of Work

DOMESTIC DWELLING

Intended use

4 Bedroom Domestic Dwelling with Study and attached Double Garage (202 sqm)

Intended life

INDEFINITE

Being stage

Stats code

1100 New (& prebuilt) House, Unit, Bach, Crib, Town House e

Estimated value

\$239,386

Pans

2

Edit Debtor

Resource Consent? Not Required

Dev Contrib Notice?

Sewer Location LINCOLN

Administration Fee \$627.08

\$22.50 Planning

Building Research Levy

\$240.00

\$472.80 **DBH Levy** \$1,138.32 9 Inspections \$10.00 **Producer Stmnt**

Water Connection

\$56.25

Charge

Total Charges \$2,566,95

Status history

Deadline 22/02/08 LODGED 10/01/08

FORMALLY 10/01/08 BC CIRC RECEIVED

CIRCULATED TO BUILDING

10/01/08 BC CIRC ASSIGNED TO LAURENCE MCCUTCHEON

FURTHER

INFORMATION 1/02/08 L1 Letter sent

REQUIRED

CIRCULATED TO 1/02/08 **PLANNING**

Signed Off Planner -Amy Pankhurst

1/02/08

CIRCULATED TO

BUILDING

1/02/08

FURTHER INFORMATION

IN LAURENCE'S ON HOLD SHELF 1/02/08 REQUIRED

Circulated to B/O -

Laurence 5/02/08 F/I FROM STONEWOOD HOMES

McCutcheon

FURTHER INFORMATION

11/02/08

REQUIRED

INFORMATION RECEIVED

15/02/08 phone

Document Produced 15/02/08

Signed Off B/O -

Laurence 18/02/08 bc ok to issue

McCutcheon

Circulated to B/A -18/02/08 Lance Faulkner

ISSUED/GRANTED 18/02/08

INVOICED 18/02/08 57013-ON AC-QUOTE DUE \$2,566.95 BC POSTED 19.02.08

AS BUILT TRUSS DESIGN RECEIVED

3/04/08 CIRCULATED TO LAURENCE FOR CHECKING

Signed Off B/O -

Laurence 3/04/08 truss ok circ admin

McCutcheon

Special Note

16/05/08 NO INSPECTION POSTWRAP UNTIL AMENDMENT HAS PASSED

Special Note

23/05/08 AMENDMENT POSTED

Contractors

None recorded.

Forms that should have been saved

Consent

Forms and Letters Actually Saved

071693bc.doc

071693fi.doc

071693fi2.doc

071693Ppim.doc

071693TRUSS.pdf

Notes

None found

Standard and Non-Standard Conditions

Note:- BN03 Note:- BN05 Note:- BN3

Fixing of Solar Panels, Connected to Cylinder Eliot Sinclair & Partners Ltd 10 October 2007

The Engineer or their nominated professional will carry out inspections as follows as confirmed on Contact directly to arrange these inspections.

Excavation for foundations including ground bearing capacity.

Reinforcing steel in foundation before concrete is poured.

The Engineer, or their representative will provide a Producer Statement Construction review on completion of the Project as confirmed on prior to the issue of the Code Compliance Certificate.

To check DPC, reinforcing/thickenings/waste pipes to floor slab before concrete is poured.

Structural framing and fixings prior to building wrap, soffit, and roofing installation.

Valley and secret gutter flashings prior to roofing installation.

Control joints and saw cuts to floor slab have been completed.

POLYSTYRENE CLADDING SYSTEM - The exterior plaster system will require inspections at the following stages:- a) Battons fixed in place to check building wrap and drained/ ventilated cavity. b) All fixings and flashings before plaster system is commenced. c) Render/Base coat and fibreglass reinforcing mesh fully completed prior to levelling coat (including sealant) in place.

POLYSTYRENE CLADDING SYSTEM - The exterior plaster system will require inspections at the following stages:- a) Battons fixed in place to check building wrap and drained/ ventilated cavity. b) All fixings and flashings before plaster system is commenced. c) Render/Base coat and fibreglass reinforcing mesh fully completed prior to levelling coat (including sealant) in place.

Cavity battens and flashings in place, prior to cladding being fixed.

POLYSTYRENE CLADDING SYSTEM - The exterior plaster system will require inspections at the following stages:- a) Battons fixed in place to check building wrap and drained/ ventilated cavity. b) All fixings and flashings before plaster system is commenced. c) Render/Base coat and fibreglass reinforcing mesh fully completed prior to levelling coat (including sealant) in place.

NOTE: A weathertight exterior is required before a preline inspection occurs.

Plumbing pipe work prior to fixing internal linings.

Preline moisture test and structural framing check including confirmation of treated timber where required.

Bracing elements prior to fixing of internal linings.

Completeness of insulation prior to fixing of internal linings.



		Me	ar 5		Consent No: _	07169	3.
Site Addre				Q D-			
		AND IN	-	Dlan Cold	Name:	1 300	d
Type of bi	uilding work:	0	ellie		A STATE OF THE STA		No. 11
On Building A		222/230] and t		at ernment Act 2004 [Sec	am / pm this s ction 174]. The	ite was inspected p purpose of the insp	oursuant to the ection was:-
Г	a Siting &	Founds	h	Bond Beam	0	Other 6	de s
1	Slab	No.	i	Blockfill	р	Resource Con	sent
	Pre Wra	р	j	Heating unit	q	Complaint/inve	estigation
	d Post Wra	ар	k	Sanitary drainage	r	Compliance So	chedule
(e Half heig	ght veneer		Stormwater drainag	e s	WOF/ c/s audi	t
	f Preline/F	Plumbing	m .	Pile/pole holes	t	Final	□ Pass
	Post line	bracing	n	Cladding	U	Inspection	□ Fail
BUILDING	WORK N	MAY PROCE	ED M	AY NOT PROCEED [RE-IN	SPECTION YE	S NO D
		MAN DANIELS SA	2000				
NSPECTI	ON NOTES:						
0			7 1	0			
7	- x 6	sole	Lok	5 to	Cole	302-2	
0	2	COTW	2000	500 :	-500		
0	box	0 1117		300	1300		
3	~	plan					
	10	4,100					
Co	Typeter	2 3	e e	-sure	elest		
~	pringe	15	~	einterned	pino	- 70 6	sour.
	٥						
	11 0						
7	des &		solyst	ree s	80	anit 6	Carca
3	des &	1	190	ree s	80	t 6	Cord
-B	Hes &	- 1	190	ree s	80	t b	Carda
- B	Hes &	1	190	ree 2	SC	ant b	Carda Carda
Je	Hes &	1	190	ree s	30		Carco
Te ye	thes of	1	190	d for	Scholle	s Rose	Cordo
To ye	Hes f	1	190	d for	Sc. balle	s Place	Ligs
Tg ye	ei spee	1	190	d for	Scholle.	s Phoe	Ligs
78	el spee	1	190	d for	Schools Per	5 Pho	Ligs
To ye	Hes &	1	190	d for	Sc balle	s Ass	Ligs
78	Hes f	1	190	d for	Schoolse Per	s Place	Ligs
78	et spee	1	190	d for	Sche Par	S Ass	Ligs
78	Hes &	no fixing	ell.	d for	balle Fee:	S Post	Ligs
NOTE: A	Hes &	no fixing	ell.	equired for 2004 Buildin	balle Fee:	S Pho	Ligs ce.
	The second secon	Fixing the Certificate A	Application is re	equired for 2004 Building	Par Consents	S Pool	L.5S
Owner/Bui	lder/Contractor co	Fixing the Certificate A	Application is re	d for	Par Consents	S Pool	Cords Ce.
Owner/Bui	lder/Contractor co	Paris	Application is receight is as reco	equired for 2004 Buildin	Par Consents	S Pse	Ce.
Owner/Bui	lder/Contractor co	the Certificate A	Application is receight is as reco	equired for 2004 Buildin	g Act Consents	S Rose	ce.
Owner/Bui NSTRUC All work in Satisfactor	rions spected is in accory: Work may proc	ce Certificate A	Application is receipt is as recone Building Cornor items above	equired for 2004 Building promisent to have been attended to the same of the s	g Act Consents	S Pho	ce.
Owner/Bui NSTRUC All work in Satisfactor	rions spected is in accory: Work may proc	ce Certificate A	Application is receipt is as recone Building Cornor items above	equired for 2004 Buildin	g Act Consents	S Pse	ce.
Owner/Bui NSTRUC All work in Satisfactor Some work	rions spected is in accory: Work may proc	ce Certificate A	Application is receipt is as recone Building Cornor items above	equired for 2004 Building promisent to have been attended to the same of the s	g Act Consents	S Pro	ce.
Owner/Bui INSTRUC All work in Satisfactor Some work	Ider/Contractor controls spected is in accong: Work may procedure.	ce Certificate A	Application is receipt is as recone Building Cornor items above	equired for 2004 Building promisent to have been attended to the same of the s	g Act Consents nent Canterbury on is required.	S Rose	ce.

BOITGH MOITOBASM

the state of the s



programme religion to the annual strate

The much of the second of

mounts, and assume the factor as a rest of the Bayes may be

TREADURANT TREATON TO ON AN THE HEAVIE THE WHEN BARE THE STATE OF THE

To and through Lagrance Letter Max but accommode to the



havel (1) (2KM)

INSPECTION NOTICE

			Inspections are	to be booked by the	owner or builder		Territoria.	1 1 4 1	
Name: A	+ C Beat	+ NA	Willia	ms	Consen	t No:	0716 93		
		South fre	11 11		000	05 22			
Ono riddre	oor tapte the	Lizcoln			Name:	Name: 6 eoff Stainson			
Type of bu	uilding work:	Donestic		129				independent of	
On d	29 1	06 1	08	at 9-06	am / pn 4 [Section 174	n this sit	e was inspected purpose of the insp	oursuant to the ection was:-	
						T			
a		& Founds	h	Bond Beam		0	Other Resource Cons	and .	
						р	Complaint/inve		
C			k	Heating unit Sanitary drain	2220	q	Compliance So		
1			K	Stormwater d		S	WOF/ c/s audit		
e		eight veneer		Pile/pole hole		t	Final	□ Pass	
		ne bracing	m n	Cladding	5	u	Inspection	□ Fail	
DIIII DING		MAY PROCE		MAY NOT PROCE	EDIT			S NO E	
BUILDING	WORK	WAT PROCE	ED-TI N	MAT NOT PROCE	EUU	KE-INS	PECTION TEX	S L NO L	
INSPECTION	ON NOTES:								
	TI	1	/	1 1	, ,			11,	
	Hen	s to	be	complexe	of por	- 12	a pection we been	dakd	
	19 -	08	end	18-5-08	have	210	u been	complete	
*	1 excep	t. posts	11212	do tob	at p	-ont	estry. +	footings	
	to &	re inspec	ekd o	et bat.	ton 1251	rech	on		
		1			/				
	-		-						
	1 +						-		
	ř		*		*				
-	_					_			
-							196		
					F	ME	PPDP		
					-				
						ח חח	PINP N		
337									
NOTE: A	Cada Camplia	nes Cartificate	Application in r	equired for 2004 E	Quilding Act Co.	nconto			
NOTE: A	Code Compila	nice Certificate /	Application is i	equired for 2004 E	building Act Co	iscilis	A THE STATE OF THE		
Owner/Buil	der/Contractor	confirms floor h	eight is as rec	ommerided by Env	vironment Cant	erbury			
INSTRUCT	TIONS INTO	ect them	1 at	balten	1xspech	in	dudi ba		
All work ins		cordance with the	ne Building Co		Tayeor				
J. Mario J. Children and C.		and the second second second	1000	e have been atten	ided to	*	13- F-16- F-	9	
				ed above, and rec			*		
	fix will be issue								
Notice to:	Contractor D	/	Agent 🗆	Occupier	Signed:	J.P.F.	The state of the	7 7 7 7	
	Total State of the	/		Left on Site	0.9.100.				
Ву:	Telephone 5	Fax 🗆	Posting	reit ou site in				and the state of the state of	

HARRED TON MOTICE

Nempy:

ENTERED



travel O

(2UM)

				Inspections are	to be booked by the owner	or builder.		
	A	Beat 1	+ NA I			Consent No:	07/693	
cito A		s/Rapid No: 5					011012	
nie A	Juless	Mapid No. 2	Lincol				y Starens	
vne c	of build	ding work:				realite. o con	9 0000-100	3045',4
On	2	8 10	5 10	8			e was inspected purpose of the insp	
	а	Siting &	Founds	h	Bond Beam	To	Other	
	b	Slab	i ounds	i	Blockfill	р	Resource Con:	sent
	c	Pre Wra	D	i	Heating unit	q	Complaint/inve	
	d	Post Wra		k	Sanitary drainage	r	Compliance So	
	е	Half heig	tht veneer	1	Stormwater drainage	s	WOF/ c/s audit	1
	f	Preline/F	26 10000	m	Pile/pole holes	t	Final	□ Pass
	g	Post line		n	Cladding	U	Inspection	☐ Fail
UILD	ING V		MAY PROCEE	ED M	AY NOT PROCEED E	RE-INS	SPECTION YES	SBNOD
	<u> </u>	to the DPC to	detail	s show	ont entry	sheet to	ll be insta	lled
<u>k</u>		Solid Wap 1	blocking to fre	etrations to be well is	completed to now free to ce. Ply stray	to be soffict	Ealed. Fire wall Boston pleased	back of g
NOTE Dwner/NSTR	E: A C Builde UCTIC k inspe	All fut Solid Wrap I down Have Sp Code Compliance Contractor coons ected is in acco	blocking by fre havings I havings I havings I havings I havings I have been been been been been been been be	ho he wall is a plant of the pl	completed the now free to the stray ERED ken arred. equired for 2004 Building	fo be so soffict defordants con so some son garage was a some son garage and consents and consents and contents and conten	Ealed. Fire wall Boston pleased	back of g
NOT! Dwner/ NSTR Mall work Satisfa	E: A C Builde UCTIC k inspectory:	All fut Solid Wap I down for Have Sp Gode Compliance ONS ected is in acco	blocking to fine the cell when min	Application is receight is as reco	conflected to now free to the stray of the s	fo be s b Seffect chardent so con Store was g Act Consents ent Canterbury	Ealed. Fire wall Boston pleased	back of g
NOTE Dwner/NSTR	E: A C Builde UCTIC k inspectory:	All fut Solid Wap I down for Have Sp Gode Compliance ONS ected is in acco	blocking to fine the cell when min	Application is receight is as reco	completed to now free to the strain of the s	fo be s b Seffect chardent so con Store was g Act Consents ent Canterbury	Fore wall Boston pleated d homes.	back of g
NOTE Dwner/NSTR	E: A C Builde UCTIO k inspectory: ' work is e to fix	All fut Solid Wap I down for Have Sp Code Compliance ONS exted is in acco Work may process not satisfactor	blocking to fine the cell when min	Application is receight is as reco	completed to now free to the strain of the s	fo he s b Soffict con dont store was Store was g Act Consents ent Canterbury	Fore wall Boston pleated d homes.	back of g

BOITON NOTICE

ENTERED



			Inspections are	to be booked by the own	ner or builder.		
Name:	-	<u>-</u> .	0		Consent No:	07165	13.
Site Addre	ss/Rapid No:	Style	Redel	0-	Officer:		
	77 1		1-cola	-3	Name:	, 50	d
Type of bu	ilding work:	0	elling	Wiles Harrison	1000		
On Building A		5 / 222/230] and the		at ernment Act 2004 [S	am / pm this s ection 174]. The	site was inspected p purpose of the insp	oursuant to the ection was:-
а	Siting &	Founds	h	Bond Beam	0	Other	Barrier I
b	102.00 90		i	Blockfill	р	Resource Cons	sent
C	Pre Wra	p	j	Heating unit	q	Complaint/inve	stigation
d	Post Wra	ар	k	Sanitary drainage	г	Compliance Sc	hedule
е	Half heig	ght veneer	1	Stormwater drain	age s	WOF/ c/s audit	
f	Preline/F	Plumbing	m	Pile/pole holes	t	Final	□ Pass
g	Post line	bracing	n	Cladding	1	Inspection	□ Fail
BUILDING	WORK N	MAY PROCEE	D N	AY NOT PROCEED	RE-IN	SPECTION YES	S NO NO
INSPECTION	ON NOTES:						
1	Zulch-	e -	wave	- 15	rete.		
		_					
H	erozona	2	oa al	2 gales	1	Volese.	
P	luland	Flo	Shire	depe	go of	an slav	,
0	los	ope		PS			erests.
				1			-
	-cle 6	DOX	seed	ed he	house	0.	
2	× He	J- r	0-0	Ce.	etvation s	s Ha	and
		·	1. 3		- 11		-3
-	not			S		Ë	(
40	10 CI	しっしい	e t	205	ersure	sedec	7
CON	evel.	مار		sided			Barrier .
4 6	,		P	1 .			
K	sek c	20	post	erman	ce,	not de	1 10
9 0	supple		Post	1 6	0000	CONCETIO	ns. tede
*	dem	7	for	entrans	e fo	ships be	Ce
1-	Spector						
1./.	spence	D.		-	D	ESTATE	0
+VC	y denn	o Fin	<u> </u>	se 10	ce tr	televe	den
· C	-odear	. 7	Cotto	m place 1	Fras	to com	ide.
NOTE: A	Codo Compliano	o Cortificato /	polication is r	required for 2004 Build	ling Act Consents		
	The country of the part of the country of		A. A				200
Owner/Buil	der/Contractor co	onfirms floor he	eight is as reco	ommended by Enviror	nment Canterbury	-	
INSTRUCT	IONS XX	stick 6	lodere	to vole	side o	at man	
All work ins	pected is in acco	rdance with th	e Building Co	nsent -ee-	red		
Satisfactor	y: Work may proc	eed when min	or items abov	e have been attended	to Ply d	mas be of	0 0
Some work	is not satisfactor	y or is incomp	lete, as detaile	ed above, and rectification	ation is required.		0
	fix will be issued,	1				L 1550	1 2s
Notice to:	Contractor 🗆	Owner □	Agent 🗆		gned:	1350	
			3		3		
By:	Telephone 🗆	Fax 🗆	Posting	Left on Site			

MBRECTION NOTICE

NOTES:

Sols	elwyn (1116	SPECTIO		OTICE
	2	nspections a	re to b	e booked by the owner or bu	ilder.	
lame:	ENT 4 /	1////	A		sent No:	07/693
Site Address/F	Rapid No: COT CO	1111	YY	W DALENAM		BARUL
ype of building	og wort	CINC	00	DWELCIA		9
On	51512		at	1632 am	pm this sit	te was inspected pursuant to the urpose of the inspection was:-
а	Siting & Founds	h		Bond Beam	0	Other
b	Slab	i		Blockfill	р	Resource Consent
С	Pre Wrap	j		Heating unit	q	Complaint/investigation
d	Post Wrap	k	L	Sanitary drainage	r	Compliance Schedule
е	Half height veneer	1	-	Stormwater drainage	S	WOF/ c/s audit
f	Preline/Plumbing	m		Pile/pole holes	t	Final Pass
g	Post line bracing	n		Cladding	u	Inspection
UILDING WO	ORK MAY PROCEE		MAY	NOT PROCEED □	RE-INS	SPECTION YES NOT
PROV	M FINCS PLACE M (18ED B	7	SOM	TID EN INSPEC WN ON DATINGA	CIPIO PA PER	N PONTS S BUILT PG
PROVINES.	MI FUNCI PLACE ME UDED B UDED B	juan	SUR	M. V 4	CIPI PIPA PER	N PENNTS S BUILT PO S 100 mp Ster
/	MI FUNCS PLACE ME IDED B MOTENT WITHER TO	juan	SUR	now La	CIPIO POPER	N PONTS S BUILT PL
/	MI FUNCI PLACE AS IDED B IDED	3 2 2 2 2 3 3	SUR	now La	CIPIO POR PERM	X A.A.V
/	MEANS	3 2 2 2 2 3 3	SUR	now La	CIPIO POR PERM TERM E	EN PONTS S BUILT PL S 100 mp Stew (X 1.A.V CASTERNAL P SLIMP.
SEN SEN SY	MEANS STATE ST	2 1 1 S	SUR	SARINGA BO M. V 4 LET CA BUBBLE	CIPIO POR PERM TERM E CO	POWTS SHILT PL
SEN SEN SY	MEANS	2 1 1 S	SUR	SARINGA BO M. V 4 LET CA BUBBLE	CIPIO POR PERM EAR	E 100 m/S Son
SEN SEN	MEANS STATE ST	Sewan English	SUR LINE	BO M. V G ELET CA STATE BUBBLE 13 CL		PONTS SBUILT PL
NES. GRAD SEN SEN NOTE: A COO	MENNS SURE LAT	S S S S S S S S S S S S S S S S S S S	SAN L	BO M. V GET CA STATE BY BY BY BY BY BY BY BY BY B	Consents	E 100 mg Ster
NOTE: A Cooperate	TO THE TO TO TO THE AND THE Contractor confirms floor height	S S S S S S S S S S S S S S S S S S S	SAN L	BO M. V GET CA STATE BY BY BY BY BY BY BY BY BY B	Consents	CASTAMI CASTAMI P SUMP.
NOTE: A COO	TO THE TO TO THE AND THE Contractor confirms floor heights	Solution is ight is as re	SAN L	BO M. V GET CA STATE BUBBLE 13 CL ired for 2004 Building Act nerided by Environment C	Consents	CASTAMI CASTAMI P SUMP.
NOTE: A Cooper/Builder/NSTRUCTION	TO THE TO TO THE MEAN S THE LAST CONTRACTOR CONTRACTOR CONFIRMS Floor heids THE CONTRACTOR CONTRACTOR WITH THE MEAN S THE CONTRACTOR CONTRACTOR CONTRACTOR CONFIRMS Floor heids THE CONTRACTOR CONTRACTOR WITH THE MEAN S THE CONTRACTOR CONTRACT	Solution is a special population is as real population is as real population is a special population in the special popu	Silver Si	BOM. V GET CASSING ACT OF THE PRINT OF THE P	Consents	CASTANT P SUMP.
NOTE: A Cool owner/Builder/WSTRUCTION II work inspectatisfactory: W	TO THE TO TO THE AND THE Contractor confirms floor heights	poplication is ight is as real ending to be ritems about the sale of the sale	Since	STATE BUSBLE 13 CL ired for 2004 Building Act nerided by Environment C	Consents	CASTANT P SUMP.


Left on Site □

Posting □

Fax


Telephone □

Ву:





		^	0 11	Inspections are	e to be bo	oked by the	owner or builde	er.		
Name:	Be	to	Will	rams.	X &		Conse	nt No:	071693	
Site Addre	ess/Rapi	id No:	Luce	h Re	96	SING	4 Officer	-	22	
THE P		1000		Linco	in		Name:	Pet	er Kobertsa	~
Type of bu	uilding w	rork:	Domes	tic D	eax	للسره	1	100	100	
On Building A	9 Act 2004		34/c 222/230] and t	he Local Gov	at 3	: 4-8 Act 200			was inspected pursuant	
	a	Siting &	Founds	h	Bor	nd Beam		ToT	Other	
	b	Şlab		i		ckfill	7.	р	Resource Consent	294
	cV	Pre Wra	р	j	He	ating unit		q	Complaint/investigation	C. 100 S.
0	d	Post Wra	ар	k	Sai	nitary drain	nage	r	Compliance Schedule	37
6	е	Half heig	ht veneer	1	Sto	rmwater d	rainage	S	WOF/ c/s audit	No.
	f	Preline/F	Plumbing	m	Pile	/pole hole	es	t	Final D P	ass
g	g	Post line	bracing	n	Cla	dding		u	Inspection F	ail
BUILDING	WORK	N	MAY PROCE	DAN	MAY NO	T PROCE	ED	RE-INSF	PECTION YES N	0 🗆
INSPECTI	ON NOT	ES:	State P	7/15/11	4.3	120	STARTE	-	TV S IT S	
					-	1				
	F (US	PI S	traps	40	hau	je 3.	15 x	30 nails.	1.0
	6	2) T	Line	CII	tos	5/ <	traps	10	be fixed	Weels
			ARC.	II .	ZALIE			1,9	10	41
1000		0	A C	MAN	2.1	> K D	Onn		see AS D	lelle,
	/ (3)(7 20	D to	s he	we	3:15,	230	m nails in	tona
A SELECTION OF THE PERSON OF T	W.		20/11	see	1	- B				
		1	21/0	. Sec	-	0 0	cult 0		11 1 1	
7=		4) 1	c Kn't	xing	regy	isre	to 481	4 W	all studs q	S
		0	or w	uston	e To	ence.	reauon	te		
	/	2/6	7	1-0		7		1,1	alm Alla	
-		0 1	NOOT	Stray	VOI V	aco	y se	A TO	o we muse	1-
							0			W. July
907 11 10	0	11	Plu	Oraci	~	as.	00	oraci	ng Dlam.	
*	0	11	1 my	- 1	7	us I	P.F.		3 prediti	
	a	0 11	encis	ug +	OP	PI	ate,	Linte	, and to	reer
	C	Onus	ection	inole	ce.	Do	ITUS	fixe	d to high	2
N. F.				- 1					U	
-	4	200	\'	- 1	,		1/	, ,		
	1	tems	5 / -	5 18	be	Co	uplet	er lo	y postwo	ep,
							/		1	'
100										
NOTE: A	A Code C	ompliand	e Certificate A	Application is r	required	for 2004 E	Building Act Co	onsents		
Owner/Bui	ilder/Con	tractor co	onfirms floor he	eight is as rec	ommend	ed by Env	vironment Can	terbury.	TEDEN	
INSTRUCT								Lang	IGNEU	- 4
		is in acco	rdance with th	e Building Co	nsent	7.117		and the tal	N TO THE REAL PROPERTY.	0
			eed when mir			een atten	ided to	L-S		W
-desired and accommendation	5,000	West Estimated and					tification is rec			
			y or is incomp	icie, as detall	eu above	, and rec	uncadon is rec	med.		
A notice to	_			V CONTRACTOR OF THE PARTY OF TH				1///		
Notice to:		ctor 🗾	Owner	Agent	Occupi		Signed:	//		
Ву:	Teleph	one 🗆	Fax 🗆	Posting	Left on	Site	* ///	11_		



PlaceMakers - Riccarton

MiTek 20/20™ TRUSS DESIGN PROGRAM

Producer Statement : Page 1

Job: Description

1098661

Building Consent No.: MiTek 20/20 - Engineering 4.4 Gamma1.6 (build 1597-10

Williams/Beat Residence

Client: Phone:

Stonewood Homes

Williams/Beat Residence 244 Southfield Drive Lincoln

LM

Phone:

Printed: 09:58:03:03 Apr 2008

PRODUCER STATEMENT

Certification of MiTek 20/20™ Truss Design Program

The MiTek 20/20™ truss design program has been developed by MiTek New Zealand Ltd for the design of GANG-NAIL timber roof, floor and attic trusses in New Zealand. The truss designs computed by this program are prepared using sound and widely accepted engineering principles, and in accordance with NZS 4203, NZS 3603 and NZS 3604 as verification methods and acceptable solutions of the approved documents of the New Zealand Building Code to satisfy the requirements of the Building Regulations 1992: Clause B1 - Structure. This computer design for the proposed building complies with the relevant provisions of the NZ Building Code. This is subject to all proprietary products meeting their performance specification requirements, the provision of adequate bracing, fixings and the correct input of design data carried out by suitably trained personnel.

Summary of MiTek 20/20™ Truss Design Data and Output

The MiTek 20/20™ computer design output for this job titled and located at the site identified on the top of this page is based on the following parameters entered into the program. The owner must ensure that the following job details below are current and relevant to the project before fabrication and erection of the GANG-NAIL trusses.

Job Details

Roof Truss

Timber Group: Roof

Material: Dead Load Restraints: Live Load:

Untreated Timber

Galy Iron .5mm -0.210 kPa 900 mm centres Qur = 0.250 kPa

Qc = 1.000 kN

Pitch:

Ceiling Material: 28.000 deg -

Gib Board 12mm Dead Load: 0.200 kPa Restraints: 600 mm centres

Std Overhang:

600 mm

Wind Area

Pressure Coeff:

High (44.0 m/s) Cpe = varies; Cpi = -0.30, 0.20

Snow

Location:

Christchurch at 100 m Open Ground Load: 0.550 kPa 0.440 kPa Basic Roof Load:

These trusses must be fabricated and erected in accordance with the GANG-NAIL manual. Proper erection bracing must be installed to hold the components true and plumb and in a safe condition until permanent bracing is fixed. All permanent bracing and fixing must be installed before any loads are applied. The specifications for timber shall be as shown on the output. The timber shall be standard gauged and treated to the requirements of NZS 3640:2003. Unless otherwise noted, this design assumes that the steel fixings and timber connectors are situated in a closed environment, as defined by NZS3604:1999 Section 4.

* = detail only, ? = input only, Txx = failed design, Unmarked trusses = designed successfully, LB = lateral bracing required Legend:

Truss	Qty	Span (mm)	Pitch (deg)	Spacing (mm)	Truss	Qty	Span (mm)	Pitch (deg)	Spacing (mm)	Truss	Qty	Span (mm)	Pitch (deg)	Spacing (mm)
TG01	1/1	9190	28.000	900	*HB11	1	5023	20.605	900	*R06	2	1217	28.000	900
TG02	1/1	9190	28,000	900	*HB12	1	1094	20.605	900	*R07	2	1034	28.000	900
T01	1/1	7393	28.000	900	J01	1	2773	28.000	900	*R07A	4	1030	28.000	900
T02	3/3	7393	28.000	787	J01A	1	2773	28.000	900	*R08	1	1096	28.000	900
CT01	1/1	9226	28.000	900	J01B	1	2773	28.000	900	*R09	1	1696	28.000	900
CTR01	1/1	9226	28.000	900	J02	1	3242	28.000	900	*R09A	1	1696	28.000	900
CTR02	1/1	9226	28.000	900	J02A	1	3242	28.000	900	*R10	2	913	28.000	900
CTG01	1/1	9226	28.000	900	J02B	1	3242	28.000	900	*R10	2	913	28.000	900
TO4A	1/1	3820	28,000	900	J03	1	2342	28.000	900	*R10A	1	913	28.000	900
T04	1/1	3820	28.000	900	J03A	1	2342	28.000	900	*R11	1	1096	28.000	900
T03	1/1	4620	28.000	900	J04	1	1442	28.000	900	*R12	1	313	28.000	900
T05B	1/1	4573	28.000	900	J04A	1	1442	28.000	900	*R13	1	1516	28.000	900
T05	1/1	4573	28.000	900	J05	1	1887	28.000	900	*R13A	1	1516	28.000	900
TC	1/1	4573	28.000	900	J05A	1	1887	28.000	900	*R14	1	913	28.000	900
c	1/1	4012	28.000	900	J05B	1	1887	28.000	900	*R14A	1	913	28,000	900
HTG01	1/1	4012	28.000	900	J06	1	2295	28.000	900	*R15	1	3997	20.605	900
T07A	1/2	4479	28.000	697	J07	2	2466	26.162	900	*R16	1	1178	28.000	900
T07	1/1	4479	28.000	697	J08	1	2743	28.000	900	*R17	1	851	28.000	900
T07A	1/2	4479	28.000	697	J08A	4	2743	28.000	900	*R18	1	901	28.000	900
T06	1/1	7570	28.000	900	J09	4	2232	28.000	900	*R19	1	1045	28.000	900
TG03	1/1	6310	28.000	900	J10	1	1332	28.000	900	*R20	1	1780	28.000	900
T12	1/3	2968	28.000	900	J10A	4	1332	28.000	900	*R21	1	913	28.000	900
V09	1/1	1845	28.000	900	J11	1	2967	28.000	900	*R21A	1	913	28,000	900
T12	2/3	2968	28.000	900	J11A	1	2967	28.000	900	*R22	2	3590	28.000	900
T11	1/1	5980	28.000	900	J12	1	2067	28.000	900	*R23	2	1652	28.000	900
T13	3/3	5980	28.000	878	J12A	1	2067	28.000	900	*R24	1	2546	20,605	900
EN01	1/1	5980	28.000	878	PS01	1	2743	28.000	900	*R25	1	828	28.000	900
CJ01	1	1983	28.000	900	PS02	1	2743	28.000	900	T08	1	2104	28.000	900
CJ02	1	2703	28.000	900	PTG01	1	1000	0.000	900	T09	1	2104	28,000	900
CJ03	1	1803	28.000	900	*R01	3	913	28.000	900	T10	1	2582	0.000	900
*HB01	1	2568	20.605	900	*R01	3	913	28.000	900	V01	1	1332	28.000	900
*HB02	1	2621	20.605	900	*R01	3	913	28.000	900	V02	1	986	28.000	900
*HB03	1	1907	20.605	900	*R01A	2	913	28.000	900	V03	1	1500	28.000	900
*HB04	1	5412	20.605	900	*R01A	2	913	28.000	900	V04	1	889	28.000	900
*HB05	2	3495	20.605	900	*R01B	1	913	28.000	900	V05	1	1452	28.000	900
*HB06	2	3631	20.605	900	*R01C	1	913	28.000	900	V07	1	1174	28.000	900
*HB07	1	2591	20.605	900	*R02	4	1155	28.000	900	V08	1	1043	28.000	900
*HB08	1	4649	20.605	900	*R03	1	1600	28.000	900	V10	- 1	945	28.000	900
*HB09	1	1945	20.605	900	*R04	1	1000	28.000	900	V10	-	040	20.000	000
	1	5256	20.605	900	*R05	1	313	28.000	17.17.17					
*HB10	75	3236	20.605	900	RUS	1	313	20.000	300					

Total quantity: 143

PlaceMakers - Riccarton

Producer Statement : Page 1

Job:

Description:

109866L

Williams/Beat Residence

Client:

Phone:


Company:

Williams/Beat Residence 244 Southfield Drive

Phone:

Printed: 09 58 03 03 Apr 2008

Building Consent No.: MITek 20/20 - Engineering 4.4 Gamma1.6 (build 1597-109) MiTek New Zealand Ltd. The computer design input has been carried out by: Materito Signed: .. Date: Name of Computer Operator: Malcolm Hart. Qualifications and Title: Truss Detailer. PlaceMakers - Riccarton Placemakers Frame & Truss Company: Verification / Acceptance of Input Data: I have checked the input data against the construction drawings and specifications and verify that they are correct and suitable for this job. Signed: Date:





FRAME AND TRUSS **MANUFACTURING**

Job Details

Pitch: 28//Iron Soffit Overhang:600 Wind Area: High

Trusses And Rafters At 900 Centres Unless Stated Otherwise

Fixings

=47x90 JH

=47x120 JH =47x190 JH

=95x165 JH

= pair CT200 (LH & RH)

=Multigrips =Nail On Plate

Wiredogs Fixing Per Drawing\Note Below

NOTE

Please contact PlaceMakers Riccarton Manufacturing if any on site remedial work s required. There will be no compensation for work done without PlaceMakers Riccarton Manufacturing written authority.

LONG HIP BOARDS TO BE SPLICED WITH 6T10 PLATES BOTH SIDES ON SITE BEFORE ERECTION

PlaceMakers Riccarton Christchurch

Ph (03) 348 2039

OB No


109866L Job Name:Stonewood Homes

Williams/Beat Residence Address:244 Southfield Drive Lincoln

Drawn By {L Santy}

Date: 05/02/2008


Note: Where Internal Load-Bearing Walls are shown on layout bearing required to all trusses



All truss to top plate fixings not indicated on the layout are to be fixed with 2/100 x 3.75 skewed nail + 2 wire dogs.



All Jack truss to truss fixings not indicated on the layout are to be fixed with a pair of 90mm nails.



J05A

R04

YB03

T03

R06

107

201

100

201

205

R06

303

R01

R05

TG01

000

J01A

J01

TG02

R01C Boy

R08

R10

R09

R10A

105

R01

R03

T04

T04A

J02


J02B

J₀₂A

J04A

J04 R01A





TURN OVER FOR DIMENSIONS




Name Beat + Williams Site Address/Rapid No: South Reld Drive Officer: Lincol Type of building work: Twelling Consent No: 071693 Officer: Name: Chris Westwood	
Site Address/Rapid No: South Reld Dride Officer: Lincol Name: Chris Westwood	
Type of building work: Type of building work: Twelfine	-
Type of building work:	
Type of building work.	
	1 t - th -
On 3 / 3 / 06 at 754 am / pm this site was inspected pursuan Building Act 2004 [Section 222/230] and the Local Government Act 2004 [Section 174]. The purpose of the inspection visiting and the Local Government Act 2004 [Section 174].	
a Siting & Founds h Bond Beam o Other	
b Slab i Blockfill p Resource Consent	1
c Pre Wrap j Heating unit q Complaint/investigation	1
d Post Wrap k Sanitary drainage r Compliance Schedule	
e Half height veneer I V Stormwater drainage s WOF/ c/s audit	
f Preline/Plumbing m Pile/pole holes t Final 🗆 F	Pass
g Post line bracing n Cladding u Inspection	Fail
BUILDING WORK MAY PROCEED ☐ MAY NOT PROCEED ☐ RE-INSPECTION YES ☑ N	10 🗆
Not Readly.	
NOTE: A Code Compliance Certificate Application is required for 2004 Building Act Consents	
NOTE: A Code Compliance Certificate Application is required for 2004 Building Act Consents Owner/Builder/Contractor confirms floor height is as recommended by Environment Canterbury	
Owner/Builder/Contractor confirms floor height is as recommended by Environment Canterbury	
Owner/Builder/Contractor confirms floor height is as recommended by Environment Canterbury INSTRUCTIONS	
Owner/Builder/Contractor confirms floor height is as recommended by Environment Canterbury INSTRUCTIONS All work inspected is in accordance with the Building Consent	
Owner/Builder/Contractor confirms floor height is as recommended by Environment Canterbury INSTRUCTIONS All work inspected is in accordance with the Building Consent Satisfactory: Work may proceed when minor items above have been attended to	
Owner/Builder/Contractor confirms floor height is as recommended by Environment Canterbury INSTRUCTIONS All work inspected is in accordance with the Building Consent	
Owner/Builder/Contractor confirms floor height is as recommended by Environment Canterbury INSTRUCTIONS All work inspected is in accordance with the Building Consent Satisfactory: Work may proceed when minor items above have been attended to Some work is not satisfactory or is incomplete, as detailed above, and rectification is required.	

					AT UNI		
		100)			
		1/10	t keech				
		1					
		3 0					
		7.5	Delline				
		1	vcoj-		(Marsh	esterned.	
		EDIT	- FIGHT DE				
wat of	off of	Hidra 2			W-CBH		
1							



	In	spections are	to be booked by the owner	r or builder.		100
Name:	Williams			Consent No: C	071693	
The state of the s	ess/Rapid No: South	Reld.	drive	Officer:		THE STATE OF STATE OF
		201-			18 West	20010
Type of bu	uilding work:					
On	2812 108		at 3.12	am / pm this sit	te was inspected p	oursuant to the
Building A	ct 2004 [Section 222/230] and the	Local Gove	ernment Act 2004 [Sec	ction 174]. The p	urpose of the insp	ection was:-
a	Siting & Founds	h	Bond Beam	0	Other	
b		i	Blockfill	р	Resource Con	sent
	Pre Wrap	1	Heating unit	q	Complaint/inve	stigation
d	Post Wrap	k	Sanitary drainage	г	Compliance So	
е	Half height veneer	1	Stormwater drainage	e s	WOF/ c/s audit	
f	Preline/Plumbing	m	Pile/pole holes	t	Final	□ Pass
g	Post line bracing	n	Cladding	u	Inspection	☐ Fail
BUILDING	WORK MAY PROCEED	M	AY NOT PROCEED D	RE-INS	SPECTION YES	S NO D
INSPECTION	ON NOTES:))		
	O, THO I E O.	1-10	insons	re		
0	ill Rounds	2000	1000 Caise	sed b	CA TOPIL	rice c
		41	14	1	2	Tank
1) 10 starter	No 1	Mesh C	xoly cou	ering e	very
6	ere but now	ace.	srinkas	se rod	151-10	lace
400	0.0 starter ere but gar Il penertra	+0	- I al	01	16	1
C	11 penertra	-	s sealer	+ lame	per lock	ties
	- place					
		1 1	1			
		1004	rs or.			
				[4]		
					ICMICIU	
					7	
		13.71	THE THE PERSON NAMED IN	1	11/2011 3-45	
				1		
WAR IN	THE STATE OF THE STATE OF			1771		
NOTE: A	Code Compliance Certificate App	olication is re	quired for 2004 Building	g Act Consents		
Owner/Buil	der/Contractor confirms floor heig	ht is as reco	mmended by Environm	ent Canterbury	607-11-11-11	
INSTRUCT		10 03 10001	onded by Environm	o.n. ounterbury		
		- 111	100	YOU WILL Y		
	spected is in accordance with the					0
Satisfactor	y: Work may proceed when minor	items above	have been attended to	Albert Mr.		
Some work	is not satisfactory or is incomplet	te, as detaile	d above, and rectification	on is required.		
A notice to	fix will be issued					
Notice to:		Agent 🗆	Occupier Sign	ed anti-		1 1 1 1 1 1 1
ACCOUNTS OF THE PARTY OF THE PA				V VIIII CO	1	
By:	Telephone Fax F	Posting	Left on Site III	HUMANA	7	

Military William San Company Company Looks ok all penertratumes scaled + laurber look tres were but youngs surkage nots 1- place Pill Rounds 200 deep covered by DPM with Plansanste the production of the state of the control of the control of the state when the prime Bout Rold No. of C7/C+73



Building Consent Inspection Prompt Sheet Concrete Floor Slabs

(BAM 202)

		PROJECT DEL	
Buil	Iding Consent No. 071 69	3	Site Copy Viewed: Yes No
Insp	pector's Name: Chry We	estwood	
Tim	e Arrived: 3.12.	Time Departed:	Date: 28/2/08
	9		
		ITEMS INSPEC	TED
Dar	np Proofing	Bas	se Course
V	DPM	V	Material Round's
V	Lapping and Sealing	V	Depth 200
V	Penetrations		Compaction
V	Edge Finishing	V	Vegetation Removed
Rei	nforcing	Ott	ner Items
. 1.	Mesh Size Wa		Brace Fixings
- 7	Lapping	The state of the s	Framing Fixings
2.46	Cover	1	Shrinkage Control
1	Shrinkage Rods		Heating
V	Chairs		Insulation
	Starter Lapping		Services
	Starter Tying		

This is not an inspection record, it serves as a prompt and simply indicates that the items listed have been inspected. The Inspection Notice (BAM 130) provides the record of items inspected and decisions made with respect to progression of building work, together with reasons for these decisions as inspection notes.



1 5 195	(4)			Inspections are	to be booked by the ow	ner or builder.		
Name:	FIAT	9 W	MAMS	()		Consent No:	071692	
Site Addr	ess/Rap	oid No:	50011-	FIRE O	12.	Officer:	2 "	
		1	LINCO	· ·		Name: 1/	- Ban	Jec.
Type of b	uilding	work:	Derecci	1~0				
On Building A	ct 200	2 / 4 [Section :	2 / c 222/230] and	the Local Gove	ernment Act 2004 [S	am pm this section 174]. The	site was inspected purpose of the insp	oursuant to the pection was:-
		Siting &	ounds	h	Bond Beam	0	Other	
		Slab		1	Blockfill	р	Resource Con	sent
		Pre Wra	р	j	Heating unit	q	Complaint/inve	estigation
	1	Post Wr	ар	k	Sanitary drainage	r	Compliance So	chedule
		Half heigh	ght veneer	1	Stormwater drain	age s	WOF/ c/s audi	t
	f	Preline/l	Plumbing	m	Pile/pole holes	t	Final	□ Pass
	3	Post line	bracing	n	Cladding	u	Inspection	☐ Fail
BUILDING	WOR	K N	MAY PROCE	ED M	AY NOT PROCEED	□ RE-IN	ISPECTION YE	S NO D
	ATTAC	CHRO	Poto	ninches	Raloxi			
Owner/Bui	Ider/Co	ntractor co	onfirms floor h		quired for 2004 Build mmended by Environ		TERED	
					have been attended	to		
Cathana and Cathana		-			d above, and rectification			
A notice to			/	piete, as detaile	above, and rectifica	adon is required.		
		-/		Ta., 1 5 T	0	1 11	11	
Notice to:		actor ☑ hone □	Owner Fax		Occupier Sig	gned:	1/4	

	In the state of th
the DE	
	TO MARK

ENTERED



Land Surveyors

Civil, Structural, Geotechnical & Environmental Engineers

Land Development Consultants

Hydrographic Surveyors

Advanced Computer Applications in Surveying and Engineering

Level 5
151 Kilmore Street
PO Box 4597
Christchurch, New Zealand
Telephone (03) 379-4014
Fax (03) 365-2449
Email esp@eliotsin.co.nz
www.eliotsinclair.co.nz

☐ Memo ☐ Site Report	Site Instruction Record of Discussion	Document TransferRecord of Phone Conversation
Attention: Angus From: Jeffrey F Subject: Foundation - Treach 300m - Probing confirm - Reinforce the in our report 2 x D/6 rods and Please ensure	Jening Trench Inspec wide by 400 m ed generally firm periorete found dated 10-0ctol 100 state fires at e all topsoil is res to power concrete	Reference: 286079 Project: 244 (Cot 45) Southfield Drive, Lincol Date: 18-Feb-2008 Page: 1 of 1 pages tion (site visit 12:30pm) to 500 m alepontoralual bearing conditions Soom as specified be - 2007. This being soom centres moved from the This formalition
Enclosures: Yes/NoCopies to:		Sent by: Sent by: Surface Mail Courier Hand Fax to No.

Comments of the Comments of th

gbin

THE NAME OF THE PARTY OF THE PA

Porte Montage is a first part of the best of the part of the second of the part of the second of the part of the second of the s

The part of the property of the part of th

Building Consent 071693

This building consent is granted subject to the conditions specified below.

The Engineer or their nominated professional will carry out inspections as follows as confirmed on 10-10-07
Contact Eliot Sinclair & Partners Ltd directly to arrange these inspections.

- Excavation for foundations including ground bearing capacity.
- Reinforcing steel in foundation before concrete is poured.

The Engineer or their representative will provide a Producer Statement Construction at the completion of the project as confirmed on 10-10-07

	Selwyn District Council Building Consent Authority Officers will carry out the following inspections:
/	To check DPC, reinforcing/thickenings/waste pipes to floor slab before concrete is poured.
/	Structural framing and fixings prior to building wrap, soffit, and roofing installation. Valley and secret gutter flashings prior to roofing installation. Control joints and saw cuts to floor slab have been completed.
v +	POLYSTYRENE CLADDING SYSTEM – The exterior plaster system will require inspections at the following stages:- a) Battens fixed in place to check building wrap and drained/ventilated cavity. Cavity battens and flashings in place, prior to cladding being fixed. (Linea)
	POLYSTYRENE CLADDING SYSTEM – The exterior plaster system will require inspections at the following stages:- b) All fixings and flashings before plaster system is commenced.
	□ Inspection 5 — PLODUCER STATEMENT From CANTENDARY DATE BROWNED LTC
	POLYSTYRENE CLADDING SYSTEM – The exterior plaster system will require inspections at the following stages:- c) Render/Base coat and fibreglass reinforcing mesh fully completed prior to levelling coat (including sealant) in place. As flowers from The exterior plaster system will require inspections at the following stages:- C) Render/Base coat and fibreglass reinforcing mesh fully completed prior to levelling coat (including sealant) in place.

Building Consent 071693

Inspection 6 29/06/08 | Good Stauman /T6/06/08 | Graff Stauman

NOTE: A weathertight exterior is required before a preline inspection occurs.

Plumbing pipe work prior to fixing of internal linings.

Preline moisture test and structural framing check including confirmation of treated timber where required.

Bracing elements prior to fixing of internal linings.

Completeness of insulation prior to fixing of internal linings.

Window installation to check ventilation, air seals, and glazing.

□ Inspection 7 25/05/08: DARYL FORTUN

NOTE:- All drainage work must be inspected prior to backfilling and a fully dimensioned 'as-built' drainage plan for Council records must be available when the Inspector visits the site.

Inspection and testing of sanitary sewer.

Connection to sewer lateral.

Stormwater disposal connection to street lateral.

Spouting including rain water heads, overflows and downpipes.

Inspection 8 CMS 1-07-08

Check nailing off of bracing panels before stopping work is carried out.

Inspection of fire rated construction including fixings and penetrations.

Inspection 9 05/09/08: WEIGH RAWISSAU

Inspection following application for Code Compliance Certificate. (The cost of the **Code** Compliance Certificate is invoiced separately).

Smoke alarm installation.

Hot water reticulation valving.

Check temperature of hot water.

Seismic restraints to hot water cylinder and storage tanks.

Domestic mechanical ventilation.

Fixing of solar panels and connection to cylinder

Building Notes

Note:-

An 'as built' truss layout, showing truss and top plate connectors, and a Producer Statement together with the lintel sizes outside the scope of NZS 3604 must be submitted to the Selwyn District Council Building Consent Authority for approval prior to the pre-wrap inspection.

Building Consent 071693

Note:-

A Construction Statement confirming the exterior plaster cladding system has been completed in accordance with the manufacturers specifications or where solid plastering has been used NZS4251, this should be supplied to the owner to submit with their documentation for Code Compliance Certificate application.

Note:-

A Producer Statement Construction (PS3) from an Approved Installer for the complete installation of the solar water heating system shall be forwarded to the Selwyn District Council with the application for Code Compliance Certificate upon completion of the work.



Compliance schedule

A compliance schedule is not required for this project.

Attachments

Code Compliance Certificate Application Form. Solar Water Heating PS3 Form.

1 9 FEB 2008

Signature

Date of Granting

Selwyn District Council Building Consent Authority Signatory

Position

On behalf of: Selwyn District Council

Issue Date: 15/02/08