

CASH SETTLED CLAIM(S)

The following information contains documents relating to claim(s) that were cash settled for the property.

If you require sign off or repair completion documents, they may be obtainable from the contractors who completed the substantive repairs at the property.

EOC 039 – Revised 07-09

Completed By: HAMISH CONNELL

Page 1 of 1

CLM 2010 1083383

Claimant Name:

HELEN ROACH.

Land	Building	Bridges/culverts	Retaining walls	Other
Lounge	Dining	Kitchen	Family Room	Bedroom
Office/Study	Rumpus	Hallway	Stairwell	Toilet
Laundry	Bathroom	Ensuite	Chimney	Foundations
Piling	Services	Kitchen Ovens	Hot Water Cylinders	Header Tanks
Glazing/windows	Fireplace/woodburner	Floor	External Walls	Roof
Outbuildings	Other			

DESCRIPTION: MINOR CRACKING IN SCOTIA JOINTS

REPAIR STRATEGY: RAKE OUT CRACKS, FILL, RE-PAINT.

[illegible]

Each, Sheet, Kilogram, Linear metre, Square metre, Cubic metre, Per Hour, Per Day, Per Week. Cubic metre calculations must include length, breadth and depth figures. Square metre calculations must include length and breadth figures.

Subtotal	273.00
----------	--------

+ P&G, Margin & GST Figure	81.60
----------------------------	-------

TOTAL	304.66
-------	--------

Completed By: HAMISH CONNELL.

Date: 25/10/10.

Page 1 of 1

CLM 2010 / 083383.

Claimant Name:

HELEN ROACH.

Land		Building		Bridges/culverts		Retaining walls		Other	
Lounge		Dining		Kitchen		Family Room		Bedroom	1
Office/Study		Rumpus		Hallway		Stairwell		Toilet	
Laundry		Bathroom		Ensuite		Chimney		Foundations	
Piling		Services		Kitchen Ovens		Hot Water Cylinders		Header Tanks	
Glazing/windows		Fireplace/woodburner		Floor		External Walls		Roof	
Outbuildings		Other							

DESCRIPTION: CRACKING IN SCOTIA IN BEDROOM AND WARDROBE.

REPAIR STRATEGY: RAKE OUT CRACKS, FILL RE-PAINT CEILING.

LINE ITEMS:

[illegible]

Each, Sheet, Kilogram, Linear metre, Square metre, Cubic metre, Per Hour, Per Day, Per Week. Cubic metre calculations must include length, breadth and depth figures. Square metre calculations must include length and breadth figures.

Subtotal	302.00
----------	--------

+ P&G, Margin & GST Figure	116.59
----------------------------	--------

TOTAL	412.59
-------	--------

Page 1 of 1

HELEN ROACH.

Land		Building		Bridges/culverts		Retaining walls		Other	
Lounge		Dining		Kitchen		Family Room		Bedroom	
Office/Study		Rumpus		Hallway		Stairwell		Toilet	
Laundry		Bathroom		Ensuite	X	Chimney		Foundations	
Piling		Services		Kitchen Ovens		Hot Water Cylinders		Header Tanks	
Glazing/windows		Fireplace/woodburner		Floor		External Walls		Roof	
Outbuildings		Other							

LINE ITEMS:

[illegible]

Each, Sheet, Kilogram, Linear metre, Square metre, Cubic metre, Per Hour, Per Day, Per Week. Cubic metre calculations must include length, breadth and depth figures. Square metre calculations must include length and breadth figures.

Subtotal	119.80
----------	--------

+ P&G, Margin & GST Figure	43.87
----------------------------	-------

TOTAL	163.67.
-------	---------

Completed By: HAMISH CONNELL.

Page 1 of 1

CLM 2010, 1083383.

Claimant Name:

HELEN ROACH.

Land	Building	Bridges/culverts	Retaining walls	Other
Lounge	Dining	Kitchen	Family Room	Bedroom
Office/Study	Rumpus	Hallway	Stairwell	Toilet
Laundry	Bathroom	Ensuite	Chimney	Foundations
Piling	Services	Kitchen Ovens	Hot Water Cylinders	Header Tanks
Glazing/windows	Fireplace/woodburner	Floor	External Walls	Roof
Outbuildings	Other			

DESCRIPTION: VANITY HAS COME AWAY FROM WALL, CRACKING IN SCOTIA.

REPAIR STRATEGY: RE-FIT VANITY, RAKE OUT CRACKS, FILL, RE-PAINT CEILING.

[illegible]

Subtotal	377.80
----------	--------

+ P&G, Margin & GST Figure	138.35
----------------------------	--------

TOTAL 516.15

Each, Sheet, Kilogram, Linear metre, Square metre, Cubic metre, Per Hour, Per Day, Per Week. Cubic metre calculations must include length, breadth and depth figures. Square metre calculations must include length and breadth figures.



Scope of Works

Completed By: HAMISH CONNELL.

Date: 25/10/10.

Page 1 of 1

CLM 2010 1083383.

Claimant Name:

HELEN ROACH.

Element Details:

Land	Building	Bridges/culverts	Retaining walls	Other	
Lounge	Dining	Kitchen	Family Room	Bedroom	
Office/Study	Rumpus	Hallway	Stairwell	Toilet	X
Laundry	Bathroom	Ensuite	Chimney	Foundations	
Piling	Services	Kitchen Ovens	Hot Water Cylinders	Header Tanks	
Glazing/windows	Fireplace/woodburner	Floor	External Walls	Roof	
Outbuildings	Other				

DESCRIPTION: MINOR CRACKING IN SCOCJA.

REPAIR STRATEGY: RAKE OUT CRACKS FILL AND RE-PAINT CEILING.

LINE ITEMS:

[illegible]

* Unit Categories to be used as follows:

Each, Sheet, Kilogram, Linear metre, Square metre, Cubic metre, Per Hour, Per Day, Per Week. Cubic metre calculations must include length, breadth and depth figures. Square metre calculations must include length and breadth figures.

Subtotal	89.20
----------	-------

+ P&G, Margin & GST Figure 32.66

TOTAL	121.86.
-------	---------



Scope of Works

Completed By: HAMISH CONNELL.

Date: 25/10/10.

Page 1 of 1

CLM 2010 / 083383

Claimant Name:

HELEN ROACH.

Element Details:

Land		Building		Bridges/culverts		Retaining walls		Other	
Lounge		Dining		Kitchen		Family Room		Bedroom	
Office/Study		Rumpus		Hallway		Stairwell		Toilet	
Laundry	X	Bathroom		Ensuite		Chimney		Foundations	
Piling		Services		Kitchen Ovens		Hot Water Cylinders		Header Tanks	
Glazing/windows		Fireplace/woodburner		Floor		External Walls		Roof	
Outbuildings		Other							

DESCRIPTION: MINOR CRACKING IN SCOTIA.

REPAIR STRATEGY: RAKE OUT CRACKS FILL, RE-PAINT CEILING.

LINE ITEMS:

[illegible]

* Unit Categories to be used as follows:

Each, Sheet, Kilogram, Linear metre, Square metre, Cubic metre, Per Hour, Per Day, Per Week. Cubic metre calculations must include length, breadth and depth figures. Square metre calculations must include length and breadth figures.

Subtotal	116.20
----------	--------

+ P&G, Margin & GST Figure	42.55
----------------------------	-------

TOTAL	158.75
-------	--------



EARTHQUAKE COMMISSION

Statement of Claim Checklist

Date: 25/10/10.Author: HAMISH CONNELL.Claim No.: 2010/083383Claimant: HELEN ROACH.Situation of Loss: 35 LANCEWOOD DRIVE.HALSWELL, CHRISTCHURCH.LA: CHRIS BROWNEstimator: HAMISH CONNELL.

Room	Damage	Walls	Ceiling	Floor	Description of Damage
	Y/N	✓	✓	✓	
Lounge	Y				CRACKING IN CORNICES. CURTAIN TRACK HAS DROPPED.
Dining Room	N.				
Kitchen	Y		/		MINOR CRACKING IN SCOTIA.
Family Room	N.				
Bedroom 1	Y		/		MINOR CRACKING SCOTIA IN BEDROOM AND WARDROBE.
En Suite	Y	/			MINOR CRACKING IN SCOTIA.
Bedroom 2	N.				
Bedroom 3	N.				
Bedroom 4	N/A				
Bathroom	Y	/	/		VAULT HAS COME AWAY FROM WALL, MINOR CRACKING IN SCOTIA. 1750 x 2950.
Toilet 1	Y		/		MINOR CRACKING IN SCOTIA. 1850 x 2500.
Toilet 2	N.				
Office/Study	N/A				
Rumpus	N/A				
Entry/Hall(s)	N.				
Stairwell	N/A				
Laundry	Y		/		MINOR CRACKING IN SCOTIA. 1750 x 1850.
Other/GGE	Y	✓			CRACKING IN GIB ABOVE WINDOW SOUTHERN WALL.

Item		Event Damage	Description of Damage	Appoint Engineer
		Y / N	Y / N	
Roof		N.		
External Walls	North	N.		
	South	N.		
	East	N.		
	West	N.		
Decks		N.		
Chimney N/A.	Base			
	Ceiling Cavity			
	Above Roof			
	Fireplace			
Foundations		N.		
Piling		N/A.		
Services		N.		
Other Dwelling Items		N/A.		
Outbuildings		N/A.		
Land & Retaining Walls		N.		
(Discuss with Supervisor)		N/A.		

I confirm the rooms and areas listed above have been inspected by an EQC representative.

Damage caused by the event has been noted and to my knowledge there are no other areas of damage resulting from the event.

Signature of Claimant:

[Handwritten Signature]

Dated:

25-10-2010