
## WDC LIM REPORT



021 793 822 | 021 387 345

ownrealestate.co.nz

POWERED BY OWNLY LTD. LICENSED REAA 2008



# LAND INFORMATION MEMORANDUM NO: LM2501254 Received: 06 Aug 2025 Issued: 12 Aug 2025 Section 44A, Local Government Official Information And Meetings Act 1987

**APPLICANT** 

S Maich 75 Forest View Road RD 1 Te Kamo 0185

#### SITE INFORMATION

Property ID: 172239

Street Address: 98 Kaurinui Crescent, One Tree Point 0118

Legal Description: LOT 270 DP 564989

This is a Land Information Memorandum only.

Full payment has been made for this Land Information Memorandum.



#### 1: PROPERTY DETAILS.

Property Map

Aerial Photo

Record of Title: 1009387

• Deposited Plan: DP 564989

This property is subject to a Consent Notice, information attached.

Interest Number 12201143.6 Dated – 03/11/2021

2: INFORMATION IDENTIFYING EACH (IF ANY) SPECIAL FEATURE OR CHARACTERISTIC OF THE LAND CONCERNED, INCLUDING BUT NOT LIMITED TO POTENTIAL EROSION, AVULSION, FALLING DEBRIS, SUBSIDENCE, SLIPPAGE, ALLUVION, OR INUNDATION, OR LIKELY PRESENCE OF HAZARDOUS CONTAMINANTS, BEING A FEATURE OR CHARACTERISTIC THAT IS KNOWN TO THE WHANGAREI DISTRICT COUNCIL.

Whangarei District Council holds indicative information on land stability hazard for Whangarei. Information on land stability, including an interactive web tool, can be found on the Council's website.

The Whangarei District Council may require site-specific investigations before granting future subdivision or building consent for the property, the level of investigation or assessment would depend on the level of stability risk of the area the property is in.

See map attached indicating this property is located within low zone and refer: <a href="https://www.wdc.govt.nz/Services/My-property-and-rates/Natural-hazards">https://www.wdc.govt.nz/Services/My-property-and-rates/Natural-hazards</a>

This property may be identified in a Northland Regional Council River Flood Hazard Zone.

For information refer:

https://www.nrc.govt.nz/environment/natural-hazards-portal/river-flooding/

Whangarei District Council notified Plan Change 1 - Natural Hazards (PC1) on the 31st of May 2023. The Plan Change introduces new provisions relating to natural hazards to the District Plan, including new hazard maps and rules for land use, development, and subdivision in hazard susceptible areas. As of 4 December 2024 the Decision Version PC1 rules have legal effect.

Refer to map attached and for more information on the proposed plan change please visit: <a href="https://www.wdc.govt.nz/Services/Planning/District-Plan-changes/Current-plan-changes">https://www.wdc.govt.nz/Services/Planning/District-Plan-changes/Current-plan-changes</a>



This property has been identified as having information available under Stormwater Catchment and Flood Management.

Any overland flow path shown provides an indicative understanding of routes where surface stormwater may flow during rainfall events.

Any depression storage area/surface depression ponding area shown provides an indicative extent of ponding that may form occur if the outlet to the ponding area is blocked or where the outlet capacity is exceeded eg a pipe is either blocked or the design capacity of the pipe is exceeded during a rainfall event.

Refer Water, Wastewater and Stormwater map attached and for further information please contact the Waste and Drainage Department on 09 430 4200.

This property is in an area that has been identified to contain:

Acid Sulphate Soil Risk

A copy of the Opus Acid Sulphate Soil guidance document dated August 2015 can be found on the Whangarei District Council website.

For information refer:

https://www.wdc.govt.nz/Council/Council-documents/Policies/Acid-Sulphate-Soil-Planning-Policy

Whangarei District Council holds information on the liquefaction vulnerability of the district.

The site is located within an area classified as Liquefaction vulnerability category:

possible.

The report was prepared by Tonkin & Taylor Ltd to provide WDC with a district wide liquefaction vulnerability assessment to help inform spatial planning and assessment of landuse, subdivision and building consents.

To view the report and access maps please use the following link: https://www.wdc.govt.nz/Services/My-property-and-rates/Natural-hazards

Please note: To view the liquefaction layer your map scale must be greater than 1:5000.

## 3: INFORMATION ON COUNCIL AND PRIVATE UTILITY (SEWERAGE, WATER & STORMWATER) SERVICES.

Information relating to Council Utility Services for this property is attached.

Water, Wastewater and Stormwater Map

As-Built Plan for this property from the building file is attached.

As Built Services Plan from BC2200646

For further information regarding Council Water Supply please refer: <a href="https://www.wdc.govt.nz/Services/Water-services/Water-Supply">https://www.wdc.govt.nz/Services/Water-services/Water-Supply</a>

This property is within the area of benefit of a pressure sewer system. See map attached and for the Homeowners guide and key requirements for maintaining the system please refer:

https://www.wdc.govt.nz/Services/Water-services/Wastewater/Pressure-Sewer-Systems



4: INFORMATION RELATING TO VALUATION, LAND, AND WATER RATES. INFORMATION FROM WHANGAREI DISTRICT COUNCIL RECORDS.

Information on Valuation, Rates and Water Meter location (if applicable) for the current financial year, is attached.

Outstanding water balance as at today's date is \$0.00. A final reading of the water meter will be required.

5: INFORMATION CONCERNING ANY PERMIT, CONSENT, CERTIFICATE, NOTICE ORDER, OR REQUISITION AFFECTING THE LAND OR ANY BUILDING ON THE LAND PREVIOUSLY ISSUED BY THE WHANGAREI DISTRICT COUNCIL OR BUILDING CERTIFIER (WHETHER UNDER THE BUILDING ACT 1991 AND/OR 2004 OR ANY OTHER ACT).

Copy of Building Consent and Code Compliance Certificate issued for this property is attached as listed below:

BC2200646 – New Dwelling
 Building Consent Issued – 21/04/2022
 Code Compliance Certificate Issued – 12/05/2023

Copy of Applications (e.g. Vehicle Crossing Permit and/or Public Utility Service) for this property are attached as listed below:

- PU221210 Pressure Sewer Connection Approved – 31/05/2022
- PU221265 Water Meter Only Approved – 17/06/2022
- VC220117 Vehicle Crossing Issued – 30/06/2022
- 6: INFORMATION RELATING TO THE USE TO WHICH THE LAND MAY BE PUT AND ANY CONDITIONS ATTACHED TO THAT USE.

This property is located in a General Residential Zone. See map attached and for more information search the property address on Councils ePlan here <a href="https://eplan.wdc.govt.nz/plan/">https://eplan.wdc.govt.nz/plan/</a>

7: INFORMATION WHICH IN TERMS OF ANY OTHER ACT HAS BEEN NOTIFIED TO THE WHANGAREI DISTRICT COUNCIL BY ANY STATUTORY ORGANISATION HAVING THE POWER TO CLASSIFY LAND OR BUILDINGS FOR ANY PURPOSE.

Whangarei District Council is not aware of any classification attached to the land or building/s.



8: OTHER INFORMATION CONCERNING THE LAND AS WHANGAREI DISTRICT COUNCIL CONSIDERS, AT COUNCILS DISCRETION, TO BE RELEVANT.

Whangarei District Council recommends that all Whangarei District residents visit the Northland Regional Council website, <a href="https://www.nrc.govt.nz/">https://www.nrc.govt.nz/</a> for information on Civil Defence hazard response. This information includes Tsunami evacuation zones, maps and community response plans for flooding and extreme weather events etc.

Copies of site plan, floor plan and elevations are attached for your information.

- A copy of a Suitability Report by RS Eng Ltd dated 28/04/2022 from BC2200646 is attached for your information.
- 9: INFORMATION RELATING TO ANY UTILITY SERVICE OTHER THAN COUNCILS SUCH AS TELEPHONE, ELECTRICITY, GAS AND REGIONAL COUNCIL WILL NEED TO BE OBTAINED FROM THE RELEVANT UTILITY OPERATOR.

Further information may be available from other authorities; Northpower; Spark; Vector Limited; etc.

#### **DISCLAIMER**

Land Information Memoranda (LIM) are prepared under the provisions of Section 44A of the Local Government Official Information and Meetings Act 1987. An inspection of the land or building(s) has not been completed for the purposes of preparing the LIM. It has been compiled from the records held by Whangarei District Council. The information contained in the LIM is correct at the date of issue.

A LIM is prepared for the use of the applicant and may not be able to be relied on by other parties.

Advice from an independent professional such as a lawyer or property advisor should be sought regarding the contents of this LIM.

Additional information regarding the land or buildings (such as resource consents and other permissions and restrictions) not contained in this LIM may be held by Northland Regional Council. For further information contact Northland Regional Council on (09) 470 1200, 0800 002 004 or www.nrc.govt.nz.

A LIM is not a suitable search of Council's records for the purposes of the National Environmental Standards (NES) for soil contamination of a potentially contaminated site.

Signed for and on behalf of Council:


P Luwes

**Property Information Officer** 

## Property Map

223 Certificate






The information displayed is schematic only and serves as a guide. It has been compiled from Whangarei District Council records and is made available in good faith but its accuracy or completeness is not guaranteed. Parcel Information is sourced from the Land Information New Zealand (LINZ) Data Service. CROWN COPYRIGHT RESERVED. © Copyright Whangarei District Council.

measurement is derived from the displayed geometry and is approximate. True accurate

boundary dimensions can be obtained from LINZ survey and title plans

## Aerial Photography





This map includes New Zealand's most current publicly owned aerial imagery and is sourced from the LINZ Data Service.

12 August 2025 Scale 1:500



The information displayed is schematic only and serves as a guide. It has been compiled from Whangarei District Council records and is made available in good faith but its accuracy or completeness is not guaranteed. Parcel Information is sourced from the Land Information New Zealand (LINZ) Data Service. CROWN COPYRIGHT RESERVED. © Copyright Whangarei District Council.



## RECORD OF TITLE UNDER LAND TRANSFER ACT 2017 FREEHOLD



Guaranteed Search Copy issued under Section 60 of the Land Transfer Act 2017

R.W. Muir Registrar-General of Land

Identifier 1009387

Land Registration District North Auckland

**Date Issued** 21 February 2022

**Prior References** 

237117

**Estate** Fee Simple

**Area** 602 square metres more or less **Legal Description** Lot 270 Deposited Plan 564989

**Registered Owners** 

Laurence White and Jill Yvonne White


#### **Interests**

12201143.6 Consent Notice pursuant to Section 221 Resource Management Act 1991 - 21.2.2022 at 4:16 pm

Land Covenant in Covenant Instrument 12201143.7 - 21.2.2022 at 4:16 pm

Land Covenant (in gross) in favour of WFH Properties Limited created by Covenant Instrument 12201143.7 - 21.2.2022 at 4:16 pm

Land Covenant in Covenant Instrument 12201143.8 - 21.2.2022 at 4:16 pm



IN THE MATTER

of the Resource Management Act

1991 ("the Act")

AND

IN THE MATTER

of a subdivision consent as evidenced

by Land Transfer Plan No. 564989

AND

IN THE MATTER

of a Consent Notice issued pursuant to Section 221 of the Act by

WHANGAREI DISTRICT COUNCIL

("the Council")

IT IS HEREBY CERTIFIED that the following conditions to be complied with on a continuing basis by the subdividing owner and subsequent owners was imposed by the Council as a condition of approval for the subdivision as effected by Land Transfer Plan No. 564989 ("the plan")

In relation to lots 265-270, 319 and 380-428.

- At the time of building consent provide suitable evidence/design to illustrate that stormwater attenuation will be provided for all impervious surfaces exceeding 45% of the lot size area, to ensure compliance with Council's Environmental Engineering Standards 2010 and to the satisfaction of the Whangarei District Council. The design shall be undertaken by a suitably qualified engineer or Council IQP.
- 2. Any development shall comply with the restrictions and recommendations identified in the Earthworks Completion Report by Cook Costello – The Landing Stages 4 and 5 – Project Number 14333-004 dated 21 October 2021, available from Council under file reference SD1800110, unless an alternative engineering report prepared by a Geotechnical or Chartered Professional Engineer is approved in writing by Council.
- At the time of building consent, the property owner shall arrange to supply and install (at its own cost) a pressure sewer system of an approved make, brand or type (including all its constituent components) to the satisfaction of Council. After approval by WDC Waste and Drainage Manager, and connection of the pressure sewer system to the Council's reticulated system, WDC shall own and maintain the pressure sewer system in accordance with the WDC Pressure Sewer Policy. The Owner shall continue to own and maintain the property's gravity drain to the pump chamber. The Owner shall be responsible for paying for the power consumption of the pumping unit in accordance with Council Pressure Sewer Policy.
- At the time of building consent, the owner shall construct the vehicle entrance crossing in accordance with Sheet 18 Residential Single Width Crossing also in

accordance with Sheets 22 & 23 of Council's Environmental Engineering Standards 2010 Edition unless an existing approved vehicle crossing to the site exist. Entrance crossings are to be designed and constructed in such a manner that will control stormwater run-off entering a property from the road, and that likewise prevent stormwater and detritus, including gravel, dirt and other materials, migrating onto the road reserve from a property.

DATED at Whangarei this 3rd day of November 2021.

SIGNED for WHANGAREI DISTRICT COUNCIL pursuant to the authority of the Council given pursuant to the Local Government Act 2002 and the Resource Management Act 1991

Authorised Signatory
Karen Toni Satherley
Post Approval RMA Officer



## The Landing Stage 4 & Stage 5 Earthworks Completion Report

WFH PROPERTIES LIMITED

One Tree Point

The Landing

Stage 4 & Stage 5



Project Number:

14333-004

Date:

21/10/2021



Originator:

Office of origin:

#### **COOK COSTELLO**

#### DOCUMENT CONTROL RECORD

Client: WFH PROPERTIES LIMITED

Project description: The Landing Stage 4 & 5 - Earthworks Completion Report

Document name: 14333 - Stage 4 & Stage 5 - Earthworks Completion

report\_saved.docx

Address: One Tree Point, Stage 4 & 5

Date of issue: Thursday, 21 October 2021

Status: For Issue

Shalle

Stefano Rotatori – Chartered Professional Engineer

(Geotechnical)

ME, IntPE (NZ), CMEngNZ, CPEng



Approved for issue: Philip Cook – Chartered Professional Engineer


BE(hons),Dip Ag, CPEng, CMEngNZ, IntPE(NZ),

MACENZ, MInstD



Whangarei

Version	Date	Comment	Ву	
1.0	14 September 2021	Review	P. Cook	
2.0	17 September 2021	Issue	S. Rotatori	
3.0	21 October 2021	Issue	S. Rotatori	




#### **Table of Contents**

1.	Lin	Limitations			
2.	Ex	Executive Summary			
3.					
4.	Sit	e D	escription	. 6	
5.			gy		
6.			ruction Methodology		
	6.1.		arthworks		
	6.2.		Roading		
7.			g & Inspection Methodology		
	7.1.	F	ill Testing	. 8	
	7.2.	L	Indercut Testing	. 9	
	7.3.	L	aboratory Testing	10	
8.	Fo	und	lation Design	10	
	8.1.	L	Iltimate Bearing Capacity	10	
	8.2.	S	Static Settlements	11	
	8.3.	S	Subsoil Class	11	
	8.4.	L	iquefaction Potential	11	
	8.4.1.		Previous Liquefaction Analysis	11	
	8.4.2.		CPT Investigations	12	
	8.4.3.		Peak Ground Acceleration	12	
	8.4.4.		Method of Analysis	13	
	8.4.5.		Liquefaction Severity Number (LSN)	13	
	8.4.6.		Ultimate Limit State	14	
	8.4.6.	1.	Liquefaction Severity Number	14	
	8.4.6.	2.	Liquefaction Induced Subsidence	14	
	8.4.6.	3.	Lateral Displacement	15	
	8.4.7.		Serviceability Limit State	15	
	8.4.7.	1.	Liquefaction Severity Number	15	
	8.4.7.	2.	Liquefaction Induced Subsidence	15	
	8.4.8.		Liquefaction Summary	15	
	8.5.	А	cid Sulphate Risk	15	



#### The Landing – Stage 4 & 5

8.5.1.	Acid Sulphate Testing Discussion
8.5.2.	Mitigation measure for Shallow Foundations
8.5.3.	Mitigation measure for Deep Foundations
8.5.3.1.	Concrete
8.5.3.2.	Steel
8.5.3.3.	Timber
8.6. Pi	oposed Building Foundations18
9. Conclu	sions
10. Limitat	ions22
Appendix 1	– Scheme Plan
Appendix 2	– Finished Contours Plan25
Appendix 3	– Site Testing Locations
Appendix 4	– Site Testing Results
Appendix 5	– Liquefaction Results
	Statement of Professional Opinion on Suitability of Land for Building Construction - Form     29
List of Fig	ures:
Figure 1: LS	SN results summary (ULS)
Figure 2: LS	N results summary (SLS)15
Figure 3: Da	amp-Proof Membrane Detail
List of Tabl	des:
Table 1: Bea	aring capacity summary for Stage 4 & Stage 5 of The Landing Subdivision11
Table 2: CP	T Investigation results
Table 3: Sei	smic parameters
Table 4: LS	N Ranges and damage classifications14



#### 1. Limitations

This report, and the stated or inferred professional opinions found within, relating to the suitability of the areas being ready for building development, shall not be construed as a guarantee.

This report, and the inferred professional opinions found within does not remove the necessity for site-specific geotechnical investigation, normal inspection and design of foundations for each lot, as would be made in natural ground and NZS3604 for standard residential building foundations.

#### 2. Executive Summary

Cook Costello was engaged by WFH Properties Ltd, to provide technical advice for earthworks and be the geo-professional for the Landing Stage 4 & 5 subdivision at One Tree Point, Northland. Cook Costello designed earthwork cuts and placement of controlled sand engineered fill, in order to enable construction of the building platforms within the proposed development.

A requirement of the consenting authority WDC (Whangarei District Council) is that a "Statement of Professional Opinion on Suitability of Land for Building Construction" (Statement of Suitability) is made by the geo-professional at the end of construction (prior to building developments). This process requires "WDC form EES-PO1" to be completed, and requires a geotechnical completion report. The completion report summarises the situation and is used to describe any departure from the standard foundation conditions expected by the building industry and outline any restrictions or recommendations if required. The purpose of this report is to provide the supporting details required for the Statement of Suitability.

The Statement of Professional Opinion on Suitability of Land for Building Construction - Form EES-PO1 has been attached to Appendix 6.



#### 3. Introduction

Cook Costello was engaged by WFH Properties Ltd, to provide technical advice for earthworks and be the geo-professional for the Landing Stage 4 & 5 subdivision at One Tree Point, Northland. Cook Costello designed earthwork cuts and placement of controlled sand engineered fill, in order to enable construction of the building platforms within the proposed development.

Previous reports and geotechnical information at the site comprise of:

- Ormiston Associates Ltd. Geotechnical Report (dated September 2005).
- Cook Costello Earthworks Specification (dated October 2018).

This report is for completion of the subdivision works in relation to the developed sections and covers the information required by the Whangarei District Council for preparing consent notices for the future property titles and provides geotechnical information to the future lot owners. It covers the requirements of the Whangarei District Council Engineering Standards (Issue 1, operative from 1 July 2010) for subdivision completion and is an addendum to the Form EES-PO1 certificate.

On completion of the works, the developer shall provide the following:

- Geotechnical reports and plans,
- All limitations on the development of the properties, including hazards, easement requirements etc.

This report relates to the lots in Stages 4 & 5 of the subdivision. The lot numbers for Stage 4 & 5 (as shown on the Scheme Plan appended to Appendix 1) covered by this report are:

#### Stage 4:

- 56 Residential Lots (lots 265 270; 319; 452; 380 428).
- Roads 4, 5, and 8.

#### Stage 5:

- 45 Residential Lots (lots 250 264; 447 452; 271 291; 316-318).
- Roads 6, 7, 10 and 19.

The subdivision has been designed and constructed to satisfy Whangarei District Council Environmental and Engineering Standards 2010.

#### 4. Site Description

The Landing subdivision is situated at One Tree Point, approximately 17 km southeast of Whangarei Central Business District. The subdivision consists of 9 stages, with Stage 1, Stage 2, Stage 3, Stage 4 and Stage 5 completed and Stage 6 and Stage 7 currently under construction. The scheme plan for Stages 4 & 5 can be seen in Appendix 1.



6

#### 5. Geology

The property is regionally placed as part of the Marsden Point Barrier Spit, a broad peninsula, comprised of coastal SAND dunes, estuarine and alluvial sediments, that partly encloses Whangarei Harbour. These are considered young soils.

The spit has been built up by a prograding (seaward advancing) foreshore depositional process in the vicinity of the harbour entrance with sequences of aeolian influenced coastal SAND dunes and alluvial and estuarine sediments.

The GNS Science online geology map defines the underlying geology of the site as comprised of Late Pleistocene stable dune deposits. Weakly cemented sand in fixed transverse dune ridges.

The soil type in the area is defined on NZMS290 Sheet Q06/07 Hukerenui - Whangarei (SOILS) as a combination of Ruakaka Loamy Peat, One Tree Point Peaty Sand and Tangitiki Sandy Loam and Sand (imperfectly to poorly drained).

The rock type in the area is defined on NZMS290 Q06/07 Hukerenui - Whangarei (ROCK TYPES) as Sand: felspathic with some quartz, minor dark minerals and clay forming fixed dunes, minor swamp deposits; unconsolidated to very soft. Unweathered or weathered to brown-stained very soft clayey sand to depths of 5m.

#### 6. Construction Methodology

The earthworks were carried out under Cook Costello as the supervising engineering consultants with Geocivil Ltd carrying out the physical testing. The general methodology consisted of a removal of organic material (peat and topsoil) stripped ground inspection, cut to fill, with fill being tested, and covering complete fill with organic topsoil peat.

A bulk earthworks plan showing the finished earthworks and contours is included in Appendix 2.

#### 6.1. Earthworks

A bulk earthworks operation was carried out over the site to improve the drainage and contour of the Lots. Earthworks were also carried out to establish reasonable building platforms. Stage 4 & 5 of the Landing used the following methodology:

- 1. The topsoil and the peat were stripped off using motor scrapers and 50 ton Moxy dump trucks (Cat 725) with 20 30 ton excavators (Cat 320).
- 2. Cut to fill in the old sand dune complex using Sand fill was undertaken to bring the lots up to finished level.
- Testing was undertaken to achieve a medium dense compacted sand with an allowable bearing capacity of greater than 100 kPa (Ultimate Bearing Capacity of 300kPa). This meets the requirements of the New Zealand Standard 4404 and the New Zealand Building Code.



7

- 4. Once the desired contours were achieved topsoil was spread from the temporary stockpile using Motor scrapers. This was track rolled with a D6 dozer and levelling bar.
- 5. Grassing of Stage 4 & 5 occurred very shortly after the top soiling process was completed.

#### 6.2. Roading

A standard industrial/commercial roading operation was undertaken on Stage 4 & 5. The roading has been achieved using the following methodology:

- 1. Trim subgrade sand layer to level using Motor Scrapers and graders.
- 2. Check the subgrade CBR by Scala Penetrometer analysis.
- 3. Place lay and spread AP65 subbase layer using a Grader and 10 ton dynamic and static rollers to achieve optimum density.
- 4. Prepared Kerb lines using a grader and a 4 ton Dynapac roller.
- 5. Place, Laid, and formed slip form kerb and channels.
- 6. Backfilled kerb & channel using 12 Ton excavator.
- 7. Place lay and spread AP40 basecourse layer using a grader and 10 ton dynamic and static rollers to achieve optimum density, using a 9 ton PTR to tighten the top layer ready for sealing.
- 8. Check the compaction of the basecourse layer by Nuclear Densometer Readings and Benkelman Beam testing.
- 9. Sweep / clean the road of loose material and debris ready for seal.
- 10. Seal the street with waterproofing seal coat and single coat chip seal (grade 5) using automatic pressurised bitumen sprayer 6-wheel trucks with chip spreading boxes on to spread both the bitumen and chip over the surface evenly.
- 11. Apply asphaltic concrete over waterproofing layer using paving machine and rollers. Asphaltic concrete to be DG10 or AC10 (refer to paving plan) to comply with NZTA M/10 Specification.

#### 7. Testing & Inspection Methodology

The relevant quality control testing for the bulk earthworks was undertaken by Cook Costello and Geocivil Ltd at the required intervals. Testing locations are appended in Appendix 3, results of the tests can be found in Appendix 4.

Supervision by the Engineers was required at key critical stages, and a series of hold points were identified and agreed with the Contractor.

#### 7.1. Fill Testing

The Cook Costello Earthworks Specification (dated October 2018) initially suggested testing consisting of Light Weight Deflectometer (LWD), Scala Penetrometers (DCP) and Nuclear Densometers (NDM).



However, during compaction of the material, it was discovered that there was a delay of approximately 4-5 weeks between compaction and achieving the desired compaction results. This is due to porepressure build up in the compacted fill material caused by the compaction process. The delay between testing and receiving results was unacceptable in terms of constructability.

As a result, it was decided to test the fill material using Static Plate Load Tests (PLT) where fill to undercut levels was deeper than 1.5m. This allowed the testing to be conducted at the finished level, speeding up the construction process. DCPs, NDMs and LWDs were conducted at the finished level after the excess pore pressure was allowed to dissipate where fill depth to undercut was less than 1.5m depth.

Frequency of testing has been set up to be not less than:

- 1 test per layer or 200 mm thickness per material type per 2500 m<sup>2</sup>; or
- 1 test per 500 m<sup>3</sup> distributed reasonably evenly throughout full depth and area; or
- 3 tests per visit; whichever requires the most tests.

As a result, the following testing has been carried out on the sand FILL areas:

- No. 103 Plate Load Tests
- No. 93 Scalas/NDMs/LWDs
- No. 5 CPTs

Locations of testing on the fill areas are shown on Drawing G01, appended to Appendix 3.

To be noted that the 300kPa ultimate bearing capacity has been calculated according to DIN 18134:2012-04 at 5mm vertical settlement (DIN 18134:2012-04: German Standard Soil Testing procedures and testing equipment – Plate load test, English translation of DIN 18134:2012-04).

#### 7.2. Undercut Testing

The Cook Costello Earthworks Specification (dated October 2018) suggested testing consisting of Light Weight Deflectometer (LWD), Scala Penetrometers (DCP) and Nuclear Densometers (NDM). Prior to fill placement, the area was stripped of vegetation and topsoil and inspected by Cook Costello and Geocivil Ltd. Site testing with DCPs was conducted to identify areas and depths that required further undercutting. Undercutting terminates on the consolidated sand layers (i.e. hard pan) and/or at the bottom of the peat or sandy peat layer.

Enabling works, undercut and benching to competent material were inspected and approved by the supervising Engineer prior to filling.

Approximately 100 Scala penetrometer tests were carried out to assess the suitability of the undercut areas.

Locations of testing on the undercut areas are shown in Drawing G02, appended to Appendix 3.



#### 7.3. Laboratory Testing

Laboratory testing was undertaken during construction to determine the following characteristics for the sand fill and for enabling site testing procedures. Laboratory testing is attached to Appendix 3. An Exhaustive list of laboratory testing is reported below:

- Determination of the Dry density/water content relationship New Zealand Standard Compaction - NZS 4402: 1986 Test 4.1.1
- Determination of the particle size distribution-Dry sieving method NZS 4407:2015 Test 3.8.2
- Determination of the Dry density/water content relationship New Zealand Heavy Compaction
   NZS 4402: 1986 Test 4.1.2
- Determination of Organic Content.
- Determination of PH(f) and PH(ox) in soil.

#### 8. Foundation Design

#### 8.1. Ultimate Bearing Capacity

Investigations have been carried out by or under the supervision of Geocivil Ltd or Cook Costello. The locations of tests are shown in Appendix 3. Test results are shown in Appendix 4.

In accordance with the Whangarei District Council Environmental Engineering Standards dated 2010 clause 2.7 The Councils Report on Completion of Construction undertook testing as the excavation or filling was carried out. The following testing was undertaken to support the statement of professional opinion as to the compliance of the filled/cut ground to the specification and the suitability of the land for Building Construction. (WDC Form EES-PO1). The testing undertaken in our view provides sufficient information to allow identification of any specific design requirements that necessitate the building foundation design to deviate from NZS 3604 and NZS 4229 and design parameters for detailed design of the foundations (such as bearing capacity, suitable founding depth etc).

The testing approach has been to test and demonstrate that the bearing capacity requirements of NZS3604 and NZS 4229 have been met or exceed the requirements of the definition of "Good Ground" where the tests were undertaken. It is assumed that the extent of testing represents that 300kPa ultimate bearing capacity is exceeded over the entire building platform even though not every piece of that ground/soil has been tested.

The existing depth of peat/peaty sand was determined by the Geotechnical Investigation Report carried out by Ormiston Associated Ltd for the residential subdivision (ref. # 1600/2114, dated September 2005). 51 CPTs, 25 Flight Augers, and 4 test pits were carried out on site. These tests showed a depth generally up to 5.5m of inferred organic peat, peaty sand and organic silts with good sand bearing below, over the majority of the site. Due to the ongoing long term settlement and shrinkage properties of the peat and organic soils, it was decided to remove this material as part of the bulk earthworks operations.



Scala Penetrometer and Plate Load testing were carried out to identify the compaction and ultimate bearing capacity of the sand fill layers. Scala Penetrometers were used to determine ultimate bearing capacity in cut areas. The bearing capacity results are summarised in Table 1. The provided ultimate bearing capacity of 300kPa is available below any topsoil that has been spread on site after the completion of the earthworks. To be noted that between 100 – 300 mm of topsoil has been spread throughout the site with an average of 200 mm.

Table 1: Bearing capacity summary for Stage 4 & Stage 5 of The Landing Subdivision,

Area	Depth (mbgl)	Ultimate Static Bearing Capacity (kPa)	Dependable Static Bearing Capacity (kPa)	
Stage 4 & 5 (All Lots)	0.1 - 0.3	300	150	

The Statement of Professional Opinion on Suitability of Land for Building Construction - Form EES-PO1 is included within Appendix 6.

#### 8.2. Static Settlements

Foundation design should limit the probable maximum differential settlement over a horizontal distance of 6 m to no more than 25 mm under serviceability limit state load combinations of AS/NZS 1170 Part 0, unless the structure is specifically designed to prevent damage under a greater settlement.

#### 8.3. Subsoil Class

Generally, across the entire site, the soils are consistent with site subsoil classification Class C – Shallow Soil sites as per NZS1170.5, based on estimated shear velocity (Vs) values from the CPTs presented within Ormiston Associated Ltd (ref. # 1600/2114, dated September 2005) and the calculated natural period of the site was less than 0.6 seconds.

#### 8.4. Liquefaction Potential

#### 8.4.1. Previous Liquefaction Analysis

As stated in the Geotechnical Investigation Report carried out by Ormiston Associated Ltd (ref. # 1600/2114, dated September 2005). The site presents a low risk for the development of liquefaction during an earthquake. The investigations at the property presented in the Ormiston Geotechnical report, in particular the CPT tests, indicates that the site is underlain by upper dense sands (qc varying from 8MPa to 20MPa) overlying a layer of loose to medium dense sands.

Groundwater is variable across the site, varying between 3.04m and 5.9m. Liquefaction does not occur above the groundwater table and this relatively deep groundwater decreases the potential of liquefaction within the shallow layers that have been cut up to the consolidated sands (hardpan) or filled using compacted sands.



In the sand-filled areas, where the unsuitable materials have been removed, sand fill has been compacted, increasing the relative density of the sands. Subsequently, further CPTs testing have been carried out to assess the liquefaction potential of the compacted sand fill. Liquefaction analysis is discussed in the next Section 1.1.1.

#### 8.4.2. CPT Investigations

Geocivil Ltd conducted three CPTs to a 20 m target depth on 10 June 2020 where the sand fill depths were more significant within Stage 4 and Stage 5 subdivisions. To be noted that between 100 – 300 mm of topsoil has been spread throughout the site. In fact, the top 300 mm layer encountered within the CPTs records show a cone resistance between 2 and 6 MPa as recorded within the topsoil layer. However, all the test results show Dense / Very Dense Sand below the topsoil with a cone resistance qc between 10 and 20 MPa.

CPT investigations carried out on site are summarised in Table 2. Detailed testing results are shown in Appendix 4, CPTs test locations are shown in Appendix 3.

Test ID	Depth (m)	Groundwater Table (m)	Depth (m)	qc (MPa) <sup>1</sup>	Interpreted Soil Description	
ODTE	1.36	Not Encountered	0 – 0.25	3	Silty SAND and Sandy SILT	
CPTF			0.25 – 1.36	18	SAND and Silty SAND	
CPTG	0.00	Not Encountered	0 – 0.45	5	SAND and Silty SAND	
CPTG	0.86		0.45 - 0.86	20	SAND	
CPT I	3.46	Not Encountered	0.0 - 0.35	4.5	Silty SAND and Sandy SILT	
			0.35 – 0.80	12	SAND and Silty SAND	
				0.80 - 1.70	16	SAND
				1.70 – 3.20	13	SAND and Silty SAND
			3.18 – 3.46	20	SAND	
CPTL	15.6	5.2	0.0 – 2.6	9.5 - 12	SAND and Silty SAND	
			2.6 – 3.0	5	Silty SAND and Sandy SILT	
			5.2	3.0 – 9.5	6 - 20	SAND and Silty SAND
			9.5 -	4 - 9	Silty SAND and Sandy SILT	

Table 2: CPT Investigation results.

#### 1. Cone tip resistance

#### 8.4.3. Peak Ground Acceleration

According to NZS 1170.5:2004, Importance Level 2 buildings are required to be designed to resist earthquake shaking with an annual probability of exceedance of 1/500 (i.e. a 500-year return period).



This is the ultimate limit state (ULS) design seismic loading. Structures are expected to retain their structural integrity during the ULS earthquake, and not collapse or endanger life.

Peak horizontal ground accelerations (PGA) have been calculated in accordance with MBIE/NZGS Module 1 (2016) using the following formula:

 $PGA = C_{0,1000} R f g / 1.3$ 

C<sub>0,1000</sub> = 0.13 for Whangarei (NZTA Bridge Manual Commentary (2018) Table C6)

R = 1.0 for a 500-year return period event (NZS 1170.5)

f = 1.33 for Class C

Thus, the PGA =  $0.13 \times 1.0 \times 1.33 \text{ g} / 1.3 = 0.13 \text{ g}$  for ULS.

SLS<sup>2</sup>

The seismic parameters are summarised in Table 3.

 Importance Level
 Limit State
 Peak Ground Acceleration, PGA or C(T)
 Effective Magnitude, Mw

 2
 ULS1
 0.13
 5.8

0.03

Table 3: Seismic parameters.

#### 8.4.4. Method of Analysis

CPT results have been analysed using CLiq software to assess the potential soil liquefaction and settlement. Boulanger & Idriss (2014) was used to evaluate the liquefaction potential (triggering) of the soil strata at the site, the method proposed by Zhang et al. (2002) was used for settlement calculations.

Liquefaction analysis results are attached in Appendix 5.

The assessment of liquefaction has been undertaken under ultimate limit state design (ULS) criteria and serviceability limit state design (SLS) criteria. The serviceability limit state is the point where a structure can no longer be used for its intended purpose but would still be structurally sound. The tolerances for serviceability depend on the intended use of the structure and can vary significantly (Section 2 of NZS 1170.5:2004).

A groundwater level of 3.0 mbgl was conservatively considered during earthquake events for the liquefaction analysis which is the shallowest recorded value within the Geotechnical Investigation Report carried out by Ormiston Associated Ltd.

#### 8.4.5. Liquefaction Severity Number (LSN)

The Liquefaction Severity Number (LSN) is a method developed by Van Ballegooy et al (2013) which provides an estimate of liquefaction damage manifesting at the ground surface. The LSN parameter



5.8

Ultimate Limit State

Serviceability Limit State

refines the calculated settlement by including a depth weighting function and can be used to differentiate the most severe damage land from the least affected land. Table 4 provides the LSN ranges and associated damage classifications.

Table 4: LSN Ranges and damage classifications

LSN Range	Damage Classification	
0 – 10	Little to No expression of liquefaction	
10 – 20	Minor expression of liquefaction	
20 – 30	Moderate expression of liquefaction	
30 – 40	Moderate to severe expression of liquefaction	
40 – 50	Major expression of liquefaction	
50+	Severe damage	

#### 8.4.6. Ultimate Limit State

A PGA value of 0.13 g and an earthquake magnitude (M<sub>w</sub>) of 5.8 have been used for liquefaction analysis in accordance with NZGS Module 1 and the NZTA Bridge Manual guidelines.

#### 8.4.6.1. Liquefaction Severity Number

The LSN for the ULS design case was 2.6 only for CPTL and nil for CPTF, G and I. This indicates *Little to no expression of liquefaction* according to Table 4. Refer to Figure 1 below.



Figure 1: LSN results summary (ULS).

#### 8.4.6.2. Liquefaction Induced Subsidence

up to 20 mm of settlement has been noted under the ULS design earthquake parameters for CPTL. Refer to the liquefaction results attached in Appendix 5.



#### 8.4.6.3. Lateral Displacement

Lateral displacement is not considered to be an issue on site due to the presence of relatively flat ground.

#### 8.4.7. Serviceability Limit State

A PGA value of 0.03 g and an earthquake magnitude (Mw) of 5.8 have been used for liquefaction analysis for the SLS case in accordance with NZGS Module 1 and the NZTA Bridge Manual guidelines.

#### 8.4.7.1. Liquefaction Severity Number

The LSN for the SLS design case was nil. This indicates *Little to no expression of liquefaction* according to Table 4. Refer to Figure 2 below.



Figure 2: LSN results summary (SLS).

#### 8.4.7.2. Liquefaction Induced Subsidence

No settlement has been noted under the SLS design earthquake parameter. Refer to the liquefaction results attached in Appendix 5.

#### 8.4.8. Liquefaction Summary

Liquefaction potential is considered to be low. Little to no expression of liquefaction is expected within Stages 4 & 5 subdivision. Liquefaction analysis results are attached in Appendix 5. Up to 20 mm of settlements could be expected under the ULS earthquake case that are within the tolerance of the building code that is 25 mm over 6 m according to Clause B1/VM1 for static settlements.

#### 8.5. Acid Sulphate Risk

#### 8.5.1. Acid Sulphate Testing Discussion

The Landing Stage 4 & 5 subdivision is mapped on the Whangarei District Council Map to be in the Acid Sulphate Risk Area. Acid Sulphate Soil Field PH Tests have been conducted on site following the Acid



Sulfate Soils Laboratory Methods Guidelines, Version 2.1, Section H, published by Department of Natural Resources, Mines and Energy, Indooroopilly, Queensland, Australia, June 2004. This Australian guide applies to soils below an RL of 5.0m.

Given the vicinity with Stage 3, no further testing was carried out for Stages 4 & 5. Outcomes of further testing would not have changed the conservative approach the mitigation measures for foundation design recommended in Sections 8.5.2 and 8.5.3.

Field pH (pH<sub>F</sub>) recording has been undertaken on site at the invert level (Test B) of proposed infrastructures (i.e. stormwater and sewer pipes) and 1 m above the invert level (Test A) in 10 different locations. Field testing is appended to Appendix 4.

For both Test A and Test B cases, field pH peroxide test (pHox) was performed on each of the 10 samples adding 30% of H2O2 (Hydrogen peroxide) to the 10 samples taken from the field in order to determine soil pH following complete oxidation.

After the reaction, the rate of the reaction indicates the level of sulfides present. The reaction is characterised by heat and gas evolution. A soil containing very little sulfides only rate an 'X' (Slight Reaction) however a soil containing high levels of sulfides is likely to rate an 'XXXX' (Very Vigorous Reaction). All the soil reaction of the pHox tests undertaken by Geocivil are characterised by an "X", therefore soils are likely to contain very little sulfides. Also, according to the ASS Sampling & Analysis Guidelines, 1998, a pHox value at least one unit below field pHr indicates potential presence of acid sulphate soils. The greater the difference between the two measurements, the more indicative the value is of a PASS (Potential Acid Sulphate Soils). The lower the final pHox value is, the better the indication of a positive result. The lab testing generally shows a pHox value less than one unit below field pH, therefore the presence of acid sulphate soils could be little. Another qualitative indication of little sulphides is that If the measured pHox < 3. The more the pHox drops below 3, the more positive the presence of sulfides is. There is one pHox value recorded below 3.

These results are consistent with local observations of good quality concrete that had been in the ground for a long time and has been excavated and shows no sulphate acid damage.

However, the PHF and pHox values are comprised between 2.92 and 5.22. According to NZS 3101:Part 1:2006 Section 3.4.3.2, an acidity represented by a PH of 5.0 to 5.5 may be considered as a practical limit of tolerance of high-quality concrete in contact with any acids. For pH lower than 5.0, the environment shall be assessed as exposure classification U. As per Section 3.8, NZS 3101, Exposure Classification U represents an exposure environment not specified in Table 3.1 of NZS 3101 for which the degree of severity should be assessed by the designer. Concrete in members subject to exposure classification U shall be specified to ensure durability under the particular exposure environment and for the chosen design life. Protective coatings may be taken into account in the assessment of concrete requirements.

Alternatively, as reported in the Acid Sulphate Soil Planning Policy Basic Guide prepared for WDC by Opus International Consultants, Australian Standard AS 2159 – 2009 Section 6 is relevant when



designing concrete and steel structures to withstand corrosive environments. This standard refers to piles, however the knowledge can be transferred to other structures.

#### 8.5.2. Mitigation measure for Shallow Foundations

Given the acid sulphate soils risk and low pH values recorded on site, it is recommended installing a waterproof membrane underneath any shallow foundations, the membrane should be extended up to the edge of the foundations. If the above recommendations are followed, concrete exposure class can be A1 according to NZS3101. A typical detail is shown in Figure 3 showing the damp-proof membrane for a typical foundation detail.




Figure 3: Damp-Proof Membrane Detail

#### 8.5.3. Mitigation measure for Deep Foundations

#### 8.5.3.1. Concrete

In case of deep concrete foundations were used on site, it is recommended referring to the Australian Standard AS 2159 – 2009 Section 6 when designing concrete and steel structures to withstand corrosive environments.

The exposure classification of concrete is *Very Severe* according to Table 6.4.2 (C) of AS 2159 – 2009, considering a pH less than 4 and soil Conditions A (high permeability soils). It is recommended to refer to Table 6.4.3 of AS 2159 – 2009 to select the minimum strength of concrete and concrete cover relevant for the *Very Severe* Exposure Classification and design life.

#### 8.5.3.2. Steel

If steel elements are used in the ground (i.e. driven H-steel piles, etc.), it Is recommended adopting the Severe Exposure Classification shown in Table 6.5.2 (C) of AS 2159 – 2009, considering a pH less than 3 and soil Conditions A (high permeability soils).

A uniform corrosion allowance of 0.04-0.1 mm/year should be adopted during the design of any underground steel structure.



#### 8.5.3.3. Timber

No precautions are required to be taken for timber piles. Timber is not susceptible to corrosion by acid.

#### 8.6. Proposed Building Foundations

The test results indicate that the sites (once the peat / topsoil layer is removed) are suitable for standard foundations for buildings.

If a shallow concrete strip footing or concrete slab on grade is to be used, any organic soil such as peat and topsoil in the building footprint is to be excavated and replaced with an engineered hard fill layer of compacted aggregate in accordance with NZS 4431 or AS 3798:2007.

The Sandy material for all lots in Stage 4 & 5 is consistent with a Class A site as defined by AS 2870:2011 indicating little to no ground movement from moisture changes is expected.

This means that the finished ground within the lots is suitable for the erection of buildings on "Good Ground" in terms of NZS 3604:2011 (Timber Framed Buildings) & NZS 4229:2013 (Concrete Masonry Buildings Not Requiring Specific Engineering Design) and related documents providing that:

- Standard check of excavated foundations is carried out at time of construction.
- Buildings subject to heavy loads or vibrations will require specific design.
- Buildings not meeting the criteria for NZS3604:2011 and NZS4229:2013 will require specific design.

This report and the inferred professional opinions found within does not remove the necessity for normal inspection and design of foundations, as would be made in natural ground.

For the additional investigation, test sites should be situated under the building areas for each site and should be selected to give adequate information about the soil over the entire plan area of the proposed building. There shall be a minimum of four test sites for a building up to 200 m<sup>2</sup>, with at least one additional test site for each additional 100 m<sup>2</sup> plan area of building as recommended by NZS3604.



#### 9. Conclusions

Cook Costello was engaged by WFH Properties Ltd, to provide technical advice for earthworks and be the geo-professional for the Landing Stage 4-5 subdivision at One Tree Point, Northland. Cook Costello designed earthwork cuts and placement of controlled sand engineered fill, in order to enable construction of the building platforms within the proposed development.

All lots have been subject to bulk earthworks to provide sites suitable for standard foundations for typical residential buildings. Any heavy structures or heavy industry users will require specific design and further investigations. A layer of topsoil was spread over the lots to ensure moisture is retained and grass will grow to prevent wind-blown erosion.

Based on our investigations we make the following conclusions and recommendations:

- The test results indicate that the sites (once the peat/topsoil layer is removed) are suitable for standard foundations for buildings.
- An ultimate bearing capacity of 300kPa is available below any peat / topsoil that has been spread on site after the completion of the earthworks. To be noted that between 100 300 mm of topsoil has been spread throughout the site with an average of 200 mm.
- The site is consistent with Subsoil Class C Shallow Soil sites as per NZS1170.5.
- Liquefaction potential is low. Little to no expression of liquefaction is expected within Stage 4 and Stage 5 subdivisions.
- Up to 20 mm of settlements could be expected under the ULS earthquake case that are within
  the tolerancy of the building code that is 25 mm over 6 m according to Clause B1/VM4 for static
  settlements.
- Foundation design should limit the probable maximum differential settlement over a horizontal distance of 6 m to no more than 25 mm under serviceability limit state load combinations of AS/NZS 1170 Part 0, unless the structure is specifically designed to prevent damage under a greater settlement.
- The Landing Stages 4 & 5 subdivisions are mapped on the Whangarei District Council Map to be in the Acid Sulphate Risk Area that is a well-known hazard in the area and well addressed with standard construction measures (i.e. waterproof membrane for shallow foundations).

Acid Sulphate Soil Field PH Tests have been conducted. Results of lab testing suggest that soils are likely to contain very little sulfides.


o However, the PHF and pHox values are comprised between 2.92 and 5.22. According to NZS 3101:Part 1:2006 Section 3.4.3.2, an acidity represented by a PH of 5.0 to 5.5 may be considered as a practical limit of tolerance of high-quality concrete in contact with any acids.



- For pH lower than 5.0, the environment shall be assessed as exposure classification U as per NZS 3101.
- Alternatively, as reported in the Acid Sulphate Soil Planning Policy Basic Guide prepared for WDC by Opus International Consultants, Australian Standard AS 2159 – 2009 Section 6 is relevant when designing concrete and steel structures to withstand corrosive environments.
- It is recommended installing a waterproof membrane underneath any shallow foundations, the membrane should be extended up to the edge of the foundations to mitigate the presence of corrosive environment. If the above recommendations are followed, concrete exposure class can be A1 according to NZS3101.
- In case of deep concrete foundations were used on site, it is recommended referring to the Australian Standard AS 2159 2009 Section 6 when designing concrete and steel structures to withstand corrosive environments. The exposure classification of concrete is *Very Severe* according to Table 6.4.2 (C) of AS 2159 2009, considering a pH less than 4 and soil Conditions A (high permeability soils). It is recommended to refer to Table 6.4.3 of AS 2159 2009 to select the minimum strength of concrete and concrete cover relevant for the *Very Severe* Exposure Classification and design life.
- If steel elements are used in the ground (i.e. driven H-steel piles, etc.), it Is recommended adopting the Severe Exposure Classification shown in Table 6.5.2 (C) of AS 2159 2009, considering a pH less than 3 and soil Conditions A (high permeability soils). A uniform corrosion allowance of 0.04-0.1 mm/year should be adopted during the design of any underground steel structure.
- No precautions are required to be taken for timber piles. Timber is not susceptible to corrosion by acid.
- If a shallow concrete strip footing or concrete slab on grade is to be used, any organic soil such as peat and topsoil in the building footprint is to be excavated and replaced with an engineered hard fill layer of compacted aggregate in accordance with NZS 4431 or AS 3798:2007.
- The Sandy material for all lots in Stage 4-5 is consistent with a Class A site as defined by AS 2870:2011 indicating little to no ground movement from moisture changes is expected.
- The finished ground within the lots is suitable for the erection of buildings on "Good Ground" in terms of NZS 3604:2011 (Timber Framed Buildings) & NZS 4229:2013 (Concrete Masonry Buildings Not Requiring Specific Engineering Design) and related documents providing that:
  - o Standard check of excavated foundations is carried out at time of construction.
  - Buildings subject to heavy loads or vibrations will require specific design.
  - Buildings not meeting the criteria for NZS3604:2011 and NZS4229:2013 will require specific design.



This report and the inferred professional opinions found within does not remove the necessity
for site-specific geotechnical investigation, normal inspection and design of foundations, as
would be made in natural ground.



#### 10. Limitations

This report has been prepared for the benefit of WFH Properties Limited as our client & The Whangarei District Council with respect to a geotechnical completion report for Stage 4 & 5 of The Landing Subdivision, One Tree Point. It shall not be relied upon for any other purpose. The reliance by other parties on the information or opinions contained in this report shall, without our prior review and agreement in writing, be at such parties' sole risk.

Opinions and judgments expressed herein are based on our understanding and interpretation of current regulatory standards and should not be construed as legal opinions. Where opinions or judgments are to be relied on they should be independently verified with appropriate legal advice. Any recommendations, opinions, or guidance provided by Cook Costello in this report are limited to technical engineering requirements and are not made under the Financial Advisers Act 2008.

Recommendations and opinions in this report are based on data from testing undertaken on site. The nature and continuity of subsoil conditions away from the tests are inferred and it must be appreciated that actual conditions could vary considerably from the assumed model.

During excavation and construction the site should be examined by a Cook Costello Engineer or Engineering Geologist to judge whether the exposed subsoil's are compatible with the inferred conditions on which the report has been based. It is possible that the nature of the exposed subsoil's may require further investigation and the modification of the design based on this report. In any event it is essential that the firm is notified if there is any variation in subsoil conditions from those described in the report as it may affect the design parameters recommended in the report.


Cook Costello have performed the services for this project in accordance with the standard agreement for consulting services and current professional standards for environmental site assessment. No guarantees are either expressed or implied.

There is no investigation which is thorough enough to preclude the presence of materials at the site which presently, or in the future, may be considered hazardous. Because regulatory evaluation criteria are constantly changing, concentrations of contaminants present and considered to be acceptable now may in the future become subject to different regulatory standards which cause them to become unacceptable and require further remediation for this site to be suitable for the existing or proposed land use activities.


This report is generally appropriate for engineering use for five years, however it should be considered that future seismic events may change soil parameters and as a result, a new assessment of the site may be necessitated. Local changes in groundwater tables may also necessitate a reassessment of the site. It is recommended that if an interpretive report is more than two years old, or the proposed building that the report originally applied to have changed significantly, (e.g., layout, height, weight of building materials, foundation loads etc.) and/or design loadings have changed (e.g., design PGA levels), then the report is reviewed by the geotechnical engineer for current applicability.



### Appendix 1 – Scheme Plan



24



Appendix 6 – Statement of Professional Opinion on Suitability of Land for Building Construction - Form EES-PO1



WHANGAREI DISTRICT COUNCIL Forum North
Private Bag 9023 Whangarei 0148 New Zealand Telephone (09) 430 4200
0800 WDC INFO 0800 932 463 Facsimile (09) 438 7632 Website http://www.wdc.govt.nz · E-mail mailroom@wdc.govt.nz



### Statement of Professional Opinion on Suitability of **Land for Building Construction** Form EES-PO1


Development	The Landing – Stage 4 and Stage 5, One Tree Point		
Developer	WFH POPERTIES LIMITED		
Location	One Tree Point		
I <i>(full name)</i>	name) Stefano Rotatori		
of (Name and address of firm)  Cook Costello Ltd, Norfolk House, 2 Norfolk Street, Whangarei, Northland		Cook Costello Ltd, Norfolk House, 2 Norfolk Street, Whangarei, Northland	
Hereby confirm	that		
1 I am a geo-p	rofessional as c	lefined in <b>Section 1.2</b> of the WDC EES and was retained by the developer as the geo-	

- professional on the above development
- 2 The extent of my preliminary investigations are described in my Report(s) number 14333-004 dated 21/10/2021 & the condusions and recommendations of that/those document(s) have been re-evaluated in the preparation of this report. The extent of my inspections during construction, & the results of all tests and/or re-evaluations carried out are as described in my geotechnical completion report dated 21/10/2021.
- 3 In my professional opinion, not to be construed as a guarantee, I consider that:
- a The earth fills shown on the attached Plan No AS EW 1D, AS EW 2D appended within Appendix 2 of the Completion Report dated 21/10/2021 have been placed in compliance with the requirements of Council & my specification
- b The completed works take into account land slope & foundation stability considerations, subject to the appended foundation recommendations and earthworks restrictions, (which should be read in conjunction with the appended final site contour plan AS EW 1D, AS EW 2D).
- c Subject to 3(a) and 3(b) above, the original ground not affected by filling satisfies the description of 'good ground' as described in NZS3604/NZS4229
- d Subject to 3(a) & 3(b) above, the filled ground satisfies the description of 'good ground' as described in NZS3604/NZS4229
- e The original ground not affected by filling & the filled ground are not subject to erosion, subsidence, or slippage in accordance with the provisions of section 106 of the Resource Management Act 1991provided that:
  - (i) Site-specific geotechnical investigation and design of foundations are to be carried out at the detailed design of buildings.
  - (ii) Standard inspection of excavated foundations is to be carried out at time of construction
  - (iii) Buildings subject to heavy loads or vibrations will require specific design.
- 4 This professional opinion is furnished to the TA & the developer for their purposes alone on the express condition that it will not be relied upon by any other person and does not remove the necessity for the normal inspection of foundation conditions at the time of erection of any building.
- 5 This certificate shall be read in conjunction with my geotechnical report referred to in clause 2 above & shall not be copied or reproduced except in conjunction with the full geotechnical completion report,

Signature Stylon Palla	Qualifications	Date	
	ME, IntPE (NZ), CMEngNZ, CPEng # 1027758	21/10/2021	

# Land Instability





Landslide Susceptibility Zone

High


Moderate

Scale 1:500 Whangārei District Council holds indicative information on land stability hazard for Whangārei. The Whangarei District Council may require site-specific investigations before granting future subdivision or building consent for the property, depending on the level of stability risk of the area the property is in: Tonkin + Taylor Ltd Landslide Susceptibility assessment report. https://www.wdc.govt.nz/files/assets/public/documents/council/ reports/hazard-reports/land-stability/landslide-susceptibility-technical-report.pdf

The information displayed is schematic only and serves as a guide. It has been compiled from Whangarei District Council records and is made available in good faith but its accuracy or completeness is not guaranteed. Parcel Information is sourced from the Land Information New Zealand (LINZ) Data Service. CROWN COPYRIGHT RESERVED. © Copyright Whangarei District Council.

# District Plan Change 1 - Natural Hazards Flooding





PC1 - Natural Hazards

Flood Hazard Area

10 Ye

10 Year Flood Hazard Area



100 Year Flood Hazard Area

Information provided on this map forms part of Plan Change 1 – Natural Hazards. To view the maps and see how the changes may affect the property please visit: https://www.wdc.govt.nz/Services/Planning/District-Plan-changes/Current-plan-changes.


The information displayed is schematic only and serves as a guide. It has been compiled from Whangarei District Council records and is made available in good faith but its accuracy or completeness is not guaranteed. Parcel Information is sourced from the Land Information New Zealand (LINZ) Data Service. CROWN COPYRIGHT RESERVED. © Copyright Whangarei District Council.


12 August 2025 Scale 1:500



# Acid Sulphate Soil (Risk/Confirmed)








These soils, where present, can generate acidic groundwater and may require consideration with regard to land drainage and selection of building materials for buried structures.

12 August 2025 Scale 1:500



# Water, Wastewater and Stormwater





This information is generalized and shows the approximate location of the Public pipeline services. For digging, the As-Built engineering drawings must be used to accurately locate the services. See WDC Customer Services.

12 August 2025 Scale 1:500




The information displayed is schematic only and serves as a guide. It has been compiled from Whangarei District Council records and is made available in good faith but its accuracy or completeness is not guaranteed. Parcel Information is sourced from the Land Information New Zealand (LINZ) Data Service. CROWN COPYRIGHT RESERVED. © Copyright Whangarei District Council.

# Water, Wastewater and Stormwater – Map Legend



Stormwater  Stormwater Point End Structure  WDC Private Fitting Node WDC Private GPT	Stormwater Catchment and Flood Management  Overland Flow Paths 2021  Modelled Catchment Flowpaths 2021  0.2 ha to 0.4 ha  0.4 ha to 1.0 ha  1.0 ha to 3.0 ha  3.0 ha to 100.0 ha  100.0 ha and above  Surface Depression Ponding Areas 2021	Wastewater Wastewater Point Backflow Device WDC Private End Structure WDC Private Fitting Node WDC
Private  Manhole  WDC  Private  Pump  WDC	0.200000 - 0.600000 m  0.600001 - 1.200000 m  1.200001 - 2.000000 m  2.000001 - 4.000000 m  4.000001 - 9.910000 m  Overland Flow Paths 2017  Catchment Area 2017	Private  Manhole  WDC  Private  Meter  WDC  Private  Motor Control Centre
Stormwater Inlet WDC Private  Valve WDC Private	O.2 - 1.0 Ha 1.0 - 2.0 Ha 2.0 - 5.0 Ha > 5.0 Ha Depression Storage Areas 2017 Depression Storage Areas	WDC Private  Pump WDC Private  Valve WDC Private  Valve Private
Stormwater Line Abandoned Pipe  Culvert  WDC Private  Drainage WDC Private  Main WDC		Wastewater Line Abandoned Pipe  Main Rising Main (Pressure Sewer Gravity Main Private Other Process Pipework WDC Private
Service Line WDC Private Surface Drain WDC Private Stormwater Area Basin WDC Private Chamber WDC Private		Service Line WDC Private  Wastewater Area Chamber WDC Private  Pressure Sewer System Public Private
	Stormwater Point End Structure WDC Private Fitting Node WDC Private GPT WDC Private Manhole WDC Private Pump WDC Private Stormwater Inlet WDC Private Valve WDC Private Valve WDC Private  Stormwater Line Abandoned Pipe Culvert WDC Private  Stormwater Line Abandoned Pipe Culvert WDC Private Stormwater Line Abandoned Pipe  Culvert WDC Private Stormwater Line Abandoned Pipe  Stormwater Line Abandoned Pipe  Culvert WDC Private Stormwater Area Basin WDC Private Stormwater Area Basin WDC Private Stormwater Area Basin WDC Private Chamber WDC Private Chamber	Stormwater Point End Structure  WDC Private Fitting Node WDC Private Fitting Node Private Publication Publication Private Publication Private Publication Private Publication Publication Publ



# G.J. Gardner. HOMES

G.J. GARDNER HOMES - NEW ZEALAND Whangarei / Kaipara 09) 437 5666 14 Percy St, Whangarei www.gjgardner.co.nz

NEW HOME FOR:

Developments

SITE ADDRESS Te Piriti Road One Tree Point

**PURCHASER SIGNATURE** Owner

Owner

**BUILDER SIGNATURE** 

Date

SITE INFORMATION

Lot Number 270

Wind Zone Site Area 602m<sup>2</sup> Corrosion Zone

Planning Zone General Residential

Territorial Authority

WDC

High

DPS Number

JOB INFOMATION

GJG Job Number

Job Last Published Wednesday, 20 April 2022

390129

DRAWING VERSION

CAD Technician/Designer

M Grew

ED A208



Whangarei District Council Private Bag 9023, Te Mai Whangarei 0143 Ph:0-9-430 4200

Email: mailroom@wdc.govt.nz

### **Rates LIM Report**

As at: Tuesday, 12 August, 2025

**Property Number** 172239

Legal Description LOT 270 DP 564989

Assessment Number 0029002137

Address 98 Kaurinui Crescent One Tree Point 0118

Record of Title(s) 1009387 Land Value \$330,000 Capital Value \$975,000 Date of Valuation 01-July-2024

Effective Date (used for rating purposes) 01-July-2025

Meter Location 7m from LHB, 4m behind kerb #98

### Rates Breakdown (up to 30 June 2026)

Rates Charge	Charge Total
General Residential	\$962.71
Sewage Disposal - Residential	\$966.00
Stormwater	\$79.00
Uniform Annual General Charge	\$901.00
Regional Council Services	\$229.89
Regional Economic Development	\$10.03
Regional Emergency & Hazard Management	\$67.31
Regional Flood Infrastructure	\$41.66
Regional Land and Freshwater Management	\$99.86
Regional Pest Management	\$109.47
Regional Rescue Services	\$8.87
Regional Sporting Facilities	\$16.09
Regional Transport Rate	\$30.40
Annual Charge Total	\$3,522.29

### Opening Balance as at 01/07/2025

\$0.00

Rates Instalments	Total
20/07/2025 Instalment	\$882.29
20/10/2025 Instalment	\$880.00
20/01/2026 Instalment	\$880.00
20/04/2026 Instalment	\$880.00
Rates Total	\$3,522.29

Balance to Clear \$2,717.29



# Form 5 Building Consent - BC2200646

Section 51, Building Act 2004

The Building

Forum North, Private Bag 9023 Whangarei 0148, New Zealand P +64 430 4200

E mailroom@wdc.govt.nz
www.wdc.govt.nz

Street address of building:

98 Kaurinui Crescent
One Tree Point 0118

One free Fount Office

Legal description of land where building is located: LOT 270 DP 564989

Building name: N/A
Location of building within site/block number: N/A
Level/unit number: N/A

### The Owner

Name of owner: RJK Development Limited

Contact person: Derek Hulse
Mailing address: 132 Kara Road

RD 9

Whangarei 0179

Street address/registered office: N/A

Phone number: Landline: N/A Mobile: 0212708282

Daytime: N/A
After hours: N/A
Facsimile number: N/A
Email address: N/A
Website: N/A

First point of contact for communications with the building consent authority:

Sudfelt Construction Limited T/A GJ Gardner Homes; Mailing Address: 14 Percy Street

Kensington

Whangarei 0112; Phone: 094375666; Email: whangarei@gjgardner.co.nz

### **Building Work**

The following building work is authorised by this building consent:

**New Dwelling** 

This building consent is issued under section 51 of the Building Act 2004. This building consent does not relieve the owner of the building (or proposed building) of any duty or responsibility under any other Act relating to or affecting the building (or proposed building). This building consent also does not permit the

construction, alteration, demolition, or removal of the building (or proposed building) if that construction, alteration, demolition, or removal would be in breach of any other Act.

### **Conditions**

This building consent is subject to the following conditions:

**Section 90 - Inspections by Building Consent Authorities:** (1) Every building consent is subject to the condition that agents authorised by the building consent authority for the purposes of this section are entitled, at all times during normal working hours or while building work is being done, to inspect-

- (a) land on which building work is being or is proposed to be carried out; and
- (b) building work that has been or is being carried out on or off the building site; and
- (c) any building.
- (2) The provisions (if any) that are endorsed on a building consent in relation to inspection during the carrying out of building work must be taken to include the provisions of this section.
- (3) In this section, inspection means the taking of all reasonable steps to ensure that building work is being carried out in accordance with a building consent.

### Inspections

The following inspections are required:

- Prepour
- Floor Slab
- · Post Wrap / Cavity
- Preline Plumbing
- Post Line
- Drainage

- Wastepipes
- · Framing / Pre-wrap
- Half High Brick
- Preline Building
- Internal Membrane
- Final

### **Documents Required**

Wastepipes

• G13: Underslab plumbing as-built & plumbers details

Framing / Pre-wrap

• B1: Truss certification

Preline Building

Form 5 - BC2200646 Page 2 of 5

• G12: Pipework pressure test documentation

### Internal Membrane

• E3: Internal Waterproofing Membrane Installer Verification

### Drainage

- E1: Stormwater drain leakage test and as-built plans
- G13: As-builts, drainlayer details, pipework test

### Final

· G9: Energy works certificate

### **Compliance Schedule**

A compliance schedule is not required for this building.

### **Attachments**

Copies of the following documents are attached to this building consent: Information page: Now you have your Building Consent

· Advice notes


Signature: Jamie Nikora

Position: Building Control Officer

On behalf of: Whangarei District Council

Issue Date: 21 June 2022

Form 5 - BC2200646 Page 3 of 5



- All ground and floor levels to be checked on site before excavation commences

- Supply and install a stable, site fence solution to secure building site to achive safe working environments and a high level of protection of public safety. Provide a system that is robust restricting access of children/if specific hazard arises, installed with bracing and opening gates.

ALL SITE INFO TBC ON RECEIPT OF TITLE AND IS SUBJECT TO CHANGE.

### **SEA SPRAY ZONE ALL EXPOSED FIXINGS TYPE 304 SS**



G.J. Gardner. HOMES

G.J. GARDNER HOMES - NEW ZEALAND Whangarei / Kaipara 09) 437 5666 14 Percy St, Whangarei www.gjgardner.co.nz

### NEW HOME FOR:

### RJK

### Developments

SITE ADDRESS Te Piriti Road **One Tree Point** Whangarei

PURCHASER SIGNATURE

Owner

Date

**BUILDER SIGNATURE** 

Date

SITE INFORMATION

Lot Number **DPS Number** 270 Site Area 602m<sup>2</sup>

Planning Zone

**General Residential** 

Territorial Authority WDC

TBC

High

34%

35%

54.2%

Wind Zone

Corrosion Zone

MAX COVERAGE MAX IMPERMEABLE Site Area 602m2 Site Area 60% 40% Max 241m² Max 361.2m<sup>2</sup>

SITE COVERAGE

Area Over Frame 202

Area Over Foundation SITE IMPERMEABLE

Roof Coverage 244.2 40.6% 13.6%

Concrete Areas: Trowel Finished with

5kg/m³ Black Oxide

113.7m<sup>2</sup>

13m²

326.0

Covered Areas

TOTAL

TOTAL 126.7m<sup>2</sup>

JOB INFOMATION

GJG Job Number 390129 Job Last Published Thursday, 28 April 2022


DRAWING VERSION


Contract

CAD Technician/Designer M Grew

1:200, 1:500

ED A201







G.J. GARDNER HOMES - NEW ZEALAND Whangarei / Kaipara 09) 437 5666 14 Percy St, Whangarei www.gjgardner.co.nz

NEW HOME FOR:

RJK

### Developments

SITE ADDRESS Te Piriti Road

One Tree Point Whangarei

PURCHASER SIGNATURE

Owner

Date

**BUILDER SIGNATURE** 

Date

SITE INFORMATION

Lot Number DPS Number 270 TBC Wind Zone Site Area

602m<sup>2</sup> High Corrosion Zone Planning Zone

**General Residential** 

Territorial Authority WDC

NOTE:

- All dimensions for setout are to Foundation

JOB INFOMATION

GJG Job Number 390129

Job Last Published Wednesday, 20 April 2022

DRAWING VERSION Contract

CAD Technician/Designer

M Grew Scale 1:200

A202<sup>ED</sup>

# Approved

### **FLOOR PLAN NOTES**

### **Timber grades & treatments:**

- 90 x 45mm SG8 studs, h1.2 treated
- 90 x 45mm SG8 bottom plates, h1.2 treated
- 90 x 45mm SG8 top plates, h1.2 treated
- All lintels SG8, H1.2 treated unless marked
- All trusses SG8 H1.2, treated
- 150 x 25 rough sawn valleyboards, h3.2 treated
- All external posts to be h5 treated
- Setout to meet nzs3604:2011

### D1: Slip Resistance

-All Access route materials shall comply with minimuim slip resistance for walking surface -Refer D1/AS1 Table 2 Slip resistance for walking surfaces

-Access route only to main entrance is assumed to be wet

- 2.475m stud height EXTERNALLY

### **SEA SPRAY ZONE ALL EXPOSED FIXINGS TYPE 304 SS**



- 2.133111 exterior willdow and door trill flead fleight
- 2.475m stud height INTERNAL WALLS
- All window and exterior door dimensions are given as trim size
- Full length window and door units to exclude timber sill section
- All exterior windows and glass doors are to be double glazed
- All interior door panels to be 1980mm high other heights
as marked on plan
- Roof pitch is <b>25</b> °
- Soffit o/hang <b>600mm</b> from frame
- Gable o/hang <b>450mm</b> from frame
- Vanities are to be wall hung

- 2.4m External & Internal load bearing studs 90x45 @ **600** ctrs

- 2.4m Internal non-load bearing studs 90x45 @600crs


### Nogs:

Brick - 800mm ctrs Linea - 800mm ctrs Tiles - 400mm ctrs

-Kitchen design is diagrammatic only. Refer to Joinery design for details of layout

### **Cupboard Shelving**

Wardrobes & Cupboards with 300 wide ventilated wire shelves.




### Floor Covering Key

Scandia Vinyl Flooring (Supply Entry Door Fixing Tab Loose)

Carpet from Builders Range

Tiled Area

Original Concrete Slab



<)



Main Distribution Board

**Fittings** 

Heated Towel Rail

Plumbing

Bath Mixer

Bath Spout

Exterior Tap

09) 437 5666 14 Percy St, Whangarei www.gjgardner.co.nz NEW HOME FOR: RJK Developments SITE ADDRESS Te Piriti Road One Tree Point Whangarei **PURCHASER SIGNATURE** Owner Date **BUILDER SIGNATURE** 

G.J. GARDNER HOMES - NEW ZEALAND Whangarei / Kaipara

SITE INFORMATION Lot Number

General Residential

Date

270 TBC Wind Zone Site Area High 602m<sup>2</sup> Corrosion Zone Planning Zone

Territorial Authority

**DPS Number** 

WDC

Floor Areas Area over Frame 202 Area over Foundation 209 Area over Roof 244

### JOB INFOMATION

Job Last Published Wednesday, 20 April 2022 GJG Job Number

390129


### DRAWING VERSION Contract

CAD Technician/Designer M Grew

Scale 1:100 A203



Combination Colorsteel Fascia Selected Powder Coated Aluminium Joinery, and Gutter System and Round-All Glass Windows and Doors are to be PVC Downpipes Double Glazed, All Glass to meet NZS;4223 Safety Glass. Support Bars to sit 5mm up from Sill. Sill Bars not required for Windows less than 600mm Wide and less than Selected 70mm Clay brick on 50mm 1500mm High Drained and vented cavity over selected underlay (N35 for High/Very High WZ)




Pg 16 of 31

BC2200646

Approved Building Consent Document





Whangarei / Kaipara 09) 437 5666 14 Percy St, Whangarei www.gjgardner.co.nz

NEW HOME FOR:

### RJK

### Developments

SITE ADDRESS Te Piriti Road One Tree Point Whangarei

PURCHASER SIGNATURE

Owner Owner

Date

**BUILDER SIGNATURE** 

Date

### SITE INFORMATION

Lot Number 270

Site Area 602m<sup>2</sup>

Planning Zone

**General Residential** 

**DPS Number** TBC

Wind Zone High Corrosion Zone D

Territorial Authority WDC

JOB INFOMATION

GJG Job Number

Job Last Published
Thursday, 28 April 2022

390129

### DRAWING VERSION

Contract

CAD Technician/Designer M Grew

<u>Scale</u> 1:100

ED A301



## **SUITABILITY REPORT**

**Continui Crescent One Tree Point**(Lot 270 DP 564989)



### **SUITABILITY REPORT**

### **Kaurinui Crescent**

### **One Tree Point**

(Lot 270 DP 564989)

**Report prepared for:** GJ Gardner Homes - RJK Developments

**Report prepared by:** Codie Hay

**Report reviewed by:** Steve Turner

**Report reference:** 18221

**Date:** 28 April 2022



Issue	Details	Date
1	Draft	15 February 2022
2	Building Consent Issue	28 April 2022



### **Contents**

1.0	Introduction	1
2.0	Site Description	1
3.0	Desk Study	2
3.1	Referenced/Reviewed Documents	2
3.2	Site Geology	2
3.3	Subdivision Report	2
3.4	Natural Hazard	3
4.0	Field Investigation	3
5.0	Subsoil Conditions	4
6.0	Geotechnical Assessment	4
6.1	Slope Stability	4
6.2	Liquefaction	4
6.3	Expansive Soils	4
6.4	Acid Sulphate Soils	5
7.0	Stormwater Assessment	5
8.0	Engineering Recommendations	7
8.1	Site Subsoil Class	7
8.2	Earthworks	8
8.3	Shallow Foundations	8
9.0	Construction Monitoring and Producer Statements	8
10.0	Conclusions	9
11.0	Limitations	10

# **Appendices**

- A Drawings
- B Subsurface Investigations
- C Stormwater Attenuation Design and Details



File: 18221 28 April 2022

Issue: 1

### SUITABILITY REPORT

### **Kaurinui Crescent, One Tree Point**

(Lot 270 DP 564989)

### 1.0 Introduction

RS Eng Ltd (RS Eng) has been engaged by GJ Gardner Homes, on behalf of their client, to investigate the suitability of their property (Lot 270 DP 564989) for residential construction. The purpose of this report is to assess the suitability of the building site making foundation, earthworks, and stormwater recommendations.

The client proposes to construct a four-bedroom single level dwelling founded on a RibRaft concrete slab.

### 2.0 Site Description

This property is located on the northern side of Kaurinui Crescent, on the western corner between Kaurinui Crescent and Te Piriti Road. The site has been developed as part of 'The Landing at Marsden: Stage 4' subdivision. The property is near level with ground coverage consisting of patchy grass.



Figure 1: View of property, Northern direction



### 3.0 Desk Study

### 3.1 Referenced/Reviewed Documents

The following documents have been referenced in this report:

- GNS Geology of The Whangarei Area Edbrooke & Brook 2009.
- Cook Costello "The Landing Stage 4 & 5 Earthworks Completion Report" dated 14 October 2021.
- Consent Notice "12201143.6."

### 3.2 Site Geology

The GNS 1:250,000 scale New Zealand Geology Web Map indicates that the property is located within an area that is underlain by Karioitahi Group, described as follows: "Weakly cemented sand in fixed transverse dune ridges."

### 3.3 Subdivision Report

The underlying subdivision was reported on by Cook Costello in a report entitled "The Landing Stage 4 & 5 Earthworks Completion Report" dated 14 October 2021. The following recommendations were made in relation to the property in question:

- "The test results indicate that the sites (once the peat / topsoil layer is removed) are suitable for standard foundations for buildings.
- If a shallow concrete strip footing or concrete slab on grade is to be used, any organic soil such as peat and topsoil in the building footprint is to be excavated and replaced with an engineered hard fill layer of compacted aggregate in accordance with NZS 4431 or AS 3798:2007.
- The Sandy material for all lots in Stage 4 & 5 is consistent with a Class A site as defined by AS 2870:2011 indicating little to no ground movement from moisture changes is expected.
- This means that the finished ground within the lots is suitable for the erection of buildings on "Good Ground" in terms of NZS 3604:2011 (Timber Framed Buildings) & NZS 4229:2013 (Concrete Masonry Buildings Not Requiring Specific Engineering Design) and related documents providing that:
  - o Standard check of excavated foundations is carried out at time of construction.
  - o Buildings subject to heavy loads or vibrations will require specific design.
  - Buildings not meeting the criteria for NZS3604:2011 and NZS4229:2013 will require specific design.
- An ultimate bearing capacity of 300kPa is available below any peat / topsoil that has been spread on site after the completion of the earthworks. To be noted that between 100 – 300 mm of topsoil has been spread throughout the site with an average of 200 mm.
- The site is consistent with Subsoil Class C Shallow Soil sites as per NZS1170.5.
- Liquefaction potential is considered to be low. Little to no expression of liquefaction is expected within Stages 4 & 5 subdivision. Liquefaction analysis results are attached in Appendix 5. Up

to 20 mm of settlements could be expected under the ULS earthquake case that are within the tolerance of the building code that is 25 mm over 6 m according to Clause B1/VM1 for static settlements."

### 3.4 Natural Hazard

The Whangarei District Council has not designated an instability hazard zone on this property. Given the underlying geology and low slope angle we consider that the building area is subject to a low instability hazard, defined as follows: "Erosion or landslide morphology is not apparent. Not considered to be at risk of instability. May, however, be at risk as a result of natural events, or development. Steeper slopes may be subject to soil creep."

### 4.0 Field Investigation

A technician from this office visited the property on 2 February 2022 to undertake a walkover inspection and subsoil investigations including two Scala Penetrometer tests and two hand augers. The walkover inspection did not observe any signs of concern at the building site in relation to the proposal.

Two hand augers were excavated to depths of 2.0m and 1.2m below ground level (BGL). The subsoils generally consisted of a shallow depth of topsoil overlying dense to very dense sand with some silt at a tested depth of 2.0m. Groundwater was not encountered in the investigations.

The Scala Penetrometer tests were performed around the building area. The tests recorded 7 to 20 blows per 100mm, generally increasing in blow counts per 100mm with depth to a maximum depth of 1.0m BGL.

### 5.0 Subsoil Conditions

Interpretation of subsurface conditions are based on the investigations shown on the drawings in Appendix A. The conditions are summarised below;

- Topsoil was encountered to an approximate depth of 0.2m.
- Subsoils consisted of dense to very dense sand with minor silt to a tested depth of 2.0m.
- Groundwater was not encountered in the investigations to a tested depth of 2.0m. RS Eng assess groundwater not likely to be within 5m below ground level.
- The underlying sand at the building platform can be classified as 'good ground' in terms of the NZS3604 definition.

### 6.0 Geotechnical Assessment

### 6.1 Slope Stability

The property and surrounding area are located on near level topography with subsoil investigations encountering dense sand at the building area. On this basis, RS Eng Ltd considers the risk of slope instability on the property as a result of the proposed works to be low provided the recommendations within this report are adhered to.

### 6.2 Liquefaction

Cook Costello have stated that "Liquefaction potential is considered to be low. Little to no expression of liquefaction is expected within Stages 4 & 5 subdivision. Liquefaction analysis results are attached in Appendix 5. Up to 20 mm of settlements could be expected under the ULS earthquake case that are within the tolerance of the building code that is 25 mm over 6 m according to Clause B1/VM1 for static settlements." On this basis RS Eng consider the risk of liquefaction to be low.

### 6.3 Expansive Soils

The sand encountered on-site is determined to be non-expansive. Cook Costello have stated "The sandy material for all lots in Stage 4 & 5 is consistent with a Class A site as defined by AS2870:2011 indicating little to no ground movement from moisture changes is expected", RS Eng Ltd conclude that the soils are considered to be Class A as per AS2870.

### 6.4 Acid Sulphate Soils

The WDC have zoned this property to be within an area at risk of acid sulphate soils. Sulphates have been deposited in these areas during the last significant sea level rise. When reacted with oxygen under the right conditions (generally areas with high groundwater tables), the sulphates can become acidic, which in turn can cause problems with the concrete components of structures beneath ground level.

The following paragraph has been extracted from a report completed by Opus International Consultants Ltd 2016, entitled: "Waipu – Nova Scotia Acid Sulphate Soil Management Plan." This summary is considered an accurate representation of most sites subject to potential acidic soils.

"If footings are excavated in acid sulphate soils, then a small amount of acid may be generated in the soil around those footings. Once the concrete is poured in, the alkalinity in the concrete would be likely to react with the acidity in the soil and neutralise it (generally resulting in a negligible unnoticeable amount of concrete corrosion in the process). Once the footings and slab are in place, the soil is then cut off from further oxygen supply."

We concur with the above statement. Additionally, the proposed raft slab will essentially be founded atop existing ground level which will not likely ever come into contact with potentially acidic soils which can only occur within the range of seasonal groundwater fluctuation. Given that groundwater was not encountered within 2.0m below ground level in the investigations, RS Eng therefore consider the risk of damage to foundations as a result of acid sulphate soils to be low.

### 7.0 Stormwater Assessment

The stormwater attenuation system designed for the subdivision development incorporates attenuation ponds which restrict outflow to the Whangarei Harbour by storing runoff volumes and releasing flows at a controlled rate to offset peak discharge flows through the existing pipe reticulation networks.

This stage of the Landing subdivision has allowed for a total of 45% impervious site coverage on each residential property when designing the attenuation ponds and any additional impervious areas exceeding 45% required attenuation in line with the Whangarei District Council (WDC) Environmental Engineering Standards (EES).

The proposed dwelling is to have impervious roof and drive areas of 244.2m<sup>2</sup> and 81.8m<sup>2</sup>, respectively. This equates to a total impervious area of 326m<sup>2</sup> (54.2%), exceeding the allowable 45% impervious area by 54m<sup>2</sup> (9%).

The Whangarei District Council (WDC) Environmental Engineering Standards (EES) requires attenuation of stormwater runoff from any increase in impervious areas so that post development peak flows are less than 80% of pre-development. The WDC EES specifies that the flows be attenuated for the 20% and 1% Annual Exceedance Probability (AEP) events.

It is proposed to direct stormwater runoff from part of the roof (allowing for 54m²) of the new dwelling into a stormwater storage pit with restricted outlets which reduce the peak flows to predevelopment levels. The overflow from the stormwater storage pit shall be piped to the WDC connection at the property. All remaining roof area (not including the 54m² portion) and driveway shall be collected where possible and piped directly to the WDC connection.

The pre-development and post-development runoff was modelled with HydroCAD. The United States Department of Agriculture Technical Release 55 (TR55) Type 1A method was adopted for calculating the run-off flow, using rainfall flows from HIRDS 4 (High Intensity Rainfall Design System, NIWA) and allowing for 20% climate change as required by WDC EES. The subsoils have been determined as sand, designated as Group B soils with poor grass cover, from WDC EES. Table 1 includes a summary of the stormwater modelling. Refer to Appendix C for further details.

Table 1: Summary of HydroCAD Calculations

Stormwater Attenuation Design Summary				
	Pre-deve	elopment	Post-development	
Permeable Area (m²)				
Grassed	5	4	0	
Impervious Area (m²)				
Roof	(	)	54	
Peak flow I/s	20% AEP	1% AEP	20% AEP	1% AEP
			+20%	+20%
From surfaces	0.31	0.70	0.57	1.03
80% (design flows reqd.)	0.25	0.56		
Total attenuated flows			0.25	0.54
Tank storage required			1.1m³	2.1m <sup>3</sup>
	Attenuation St	torage Pit Sum	mary	
Material	65 – 40 Washed Graded Chip			
	Base	Area	De	epth
Pit Dimensions	4.0m x 2.0m		0.	8m
	Diameter		Height from To	op of Storage Pit
Primary Orifice	14mm		0.	8m
Secondary Orifice	13mm		0.4	13m

Confirmation of the connection depth shall be sought from a drainlayer prior to the storage pit construction, this may dictate the size of the storage pit.

### 8.0 Engineering Recommendations

### 8.1 Site Subsoil Class

In accordance with NZS 1170.5:2004, Section 3.12.3 the site has been assessed for its Site Subsoil Class. Based on the observation listed above RS Eng considers the site soils lie within Site Class C "Shallow Soil Site."

### 8.2 Earthworks

To form access to and create a level building platform for the dwelling minor earthworks are proposed. To suitably develop the building area, we recommend as follows:

- The building area and driveway should be shaped to assist in stormwater runoff and avoid ponding of surface water.
- Topsoil will need to be removed from the building area before replacement with a minimum
   100mm compacted granular hardfill layer extending 0.5m beyond the building envelope.
- Cut and fill batters should be sloped at angles less than 1V to 3H.
- Site works shall generally be completed in accordance with NZS4431.

### 8.3 Shallow Foundations

It is proposed to construct a timber framed type dwelling on a RibRaft floor slab. To suitably found the proposed dwelling the following is recommended;

- A standard RibRaft slab can be used provided it is placed on a minimum of 100mm compacted granular hardfill extending 0.5m beyond the building envelope.
- Isolated NZS 3604 type pile foundations should be extended a minimum of 0.5m below cleared ground level.

Notwithstanding the recommendations of this report, for specific design of shallow foundations RS Eng has assessed the following:

- 300kPa Ultimate Bearing Capacity (Geotechnical Ultimate)
- 150kPa Dependable Bearing Capacity (Ultimate Limit State)
- 100kPa Allowable Bearing Capacity (Serviceability Limit State)

### 9.0 Construction Monitoring and Producer Statements

RS Eng recommend a suitably experienced Chartered Professional Engineer monitor the construction of the following works:

- Stripped site once all topsoil and unsuitable material has been removed.
- Hardfill compaction where depth exceeds 300mm.

Any works not inspected will be excluded from future producer statements (PS4) to be issued by RS Eng. In any event, where doubt exists regarding inspections, this office should be contacted for advice, and provided with reasonable notice of inspections.

### 10.0 Conclusions

It is the conclusion of RS Eng Ltd that the building area is suitable for the proposal provided the recommendations and limitations stated within this report are adhered to.

RS Eng Ltd also concludes that subject to the recommendations of this report, in terms of Section 72 of the Building Act 2004;

- (a) the building work to which an application for a building consent relates will not accelerate, worsen, or result in slippage or subsidence on the land on which the building work is to be carried out or any other property; and
- (b) the land is neither subject to nor likely to be subject to slippage or subsidence.

### 11.0 Limitations

This report has been prepared solely for the benefit of our client and the Whangarei District Council. The purpose is to determine the engineering suitability of the proposed dwelling, in relation to the material covered by the report. The reliance by other parties on the information, opinions or recommendations contained therein shall, without our prior review and agreement in writing, do so at their own risk.

Recommendations and opinions in this report are based on data obtained as previously detailed. The nature and continuity of subsoil conditions away from the test locations are inferred and it should be appreciated that actual conditions could vary from those assumed. If during the construction process, conditions are encountered that differ from the inferred conditions on which the report has been based, RS Eng should be contacted immediately.

Construction site safety is the responsibility of the builder/contractor. The recommendations included herein should not be construed as direction of the contractor's methods, construction sequencing or procedures. RS Eng can provide recommendations if specifically engaged to, upon request.

This report does not address matters relating to the National Environmental Standard for Contaminated Sites, and if applicable separate advice should be sought on this matter from a suitably qualified person.

RS Eng advise our clients that it is Whangarei District Council policy to not accept engineering report, dated more than two years prior to the application date.

Prepared by:

**Codie Hay** 

**Engineering Technician** 

**RS Eng Ltd** 

Reviewed by:


Steve Turner

Director

BE(Civil), CPEng, IntPE(NZ), CMEngNZ

# Appendix A

**Drawings** 



- Approved Building Consent Document - BC2200646 - Pg 15 of 56 - 21/06/2022 - NZBTC

### NOTES:

- If any part of these documents are unclear, please contact RSEng Ltd.
- This plan is copyright to RSEng Ltd and should not be reproduced without prior permission.



### **KEY**

- X Hand Auger Location
- Scala Penetrometer Location



SITE PLAN



# Form 7 Code Compliance Certificate

Section 95, Building Act 2004

Forum North, Private Bag 9023 Whangarei 0148, New Zealand P +64 430 4200

*E* mailroom@wdc.govt.nz *www.wdc.govt.nz* 

The Building

Street address of building: 98 Kaurinui Crescent, One Tree Point 0118

Legal description of land where building is located: LOT 270 DP 564989

Building name: N/A
Location of building within site/block number: N/A
Level/unit number: N/A

Current, lawfully established, use: 2.0 Housing: 2.0.2 Detached Dwelling with 4

occupants

Year first constructed: 2022

The Owner

Name of owner: RJK Development Limited

Contact person: Derek Hulse

Mailing address: 132 Kara Road, RD 9, Whangarei

Street address/registered office: N/A

Phone number: Landline: N/A Mobile: 0212708282

Daytime: Landline: N/A Mobile: 0212708282

After hours: Landline: N/A Mobile: 0212708282

Facsimile number: N/A Email address: N/A

First point of contact for communications with the council/building consent authority: Sudfelt Construction Limited T/A GJ Gardner Homes; Mailing Address: 14 Percy Street

Kensington

Whangarei 0112; Phone: 094375666; Email: whangarei@gjgardner.co.nz

**Building Work** 

Building consent number: BC2200646
Description: New Dwelling

Issued by: Whangarei District Council

### **Code Compliance**

The building consent authority named below is satisfied, on reasonable grounds, that - the building work complies with the building consent.

Signature: Aaron Brown

Position: Senior Building Control Officer On behalf of: Whangarei District Council

Date: 12 May 2023

Form 7 - BC2200646 Page 2 of 2



In reply please quote

PU221210

Or ask for

PU221210 - appointment

1 June 2022

Sudfelt Construction Limited – GJ Gardner Homes Whangarei P O Box 8046
Kensington
Whangarei 0145

Dear Sir/Madam

### Public Utility Service Application No. PU221210

Site Address: 10 Te Piriti Road, One Tree Point - Lot 270

The application at the above address has been approved as at 31/05/2022.

### **Conditions:**

- The work shall be undertaken by **certified drainlayer approved to install and commission the pressure sewer product** by an approved pressure sewer product supplier.
- The pumping unit to be installed shall be an approved pressure sewer product suplied by an approved supplier. This includes the tank, pump and the alarm panel.
- The pumping unit shall be commissioned by the technology supplier or their agent.
- Installation shall be in accordance with the Environmental Engineering Standards
- Consent from the Waste and Drainage Engineering Officer is required to use compression couplings.

The following information shall be supplied to Council within one month after the commissioning of the new pressure sewer pumping unit.

- Final As-built plans. The as built plan will have to comply with the Council's Environmental Engineering Standards.
- Technology supplier's commissioning checklist.
- Proof of warranty for pump equipment (minimum 24 months warranty period).
- Information for installation testing e.g pump chamber waterproof test.

The applicant must arrange for the Waste and Drainage Engineering Officer to carry out an inspection prior to backfilling the new drainage and pump unit a minimum of 48 hours ahead of time required. To arrange for an inspection please contact us on Council's main number 09 430 4200 to ensure that the request reaches the appropriate person.


Final sign off for the Public Utility consent will occur after the passing of Council's inspection, and provision of approved as built plans provided that:

Engineering Standards and any Special Conditions are complied with as noted above.

Please keep this letter and the approved plans on site, as the contractor and the inspector will require verification of Council's approval. Thank you.

Yours faithfully

Infrastructure and Services Support Assistant



G.J. Gardner. HOMES

G.J. GARDNER HOMES - NEW ZEALAND Whangarei / Kaipara 09) 437 5666 14 Percy St. Whangarel www.gjgardner.co.nz

NEW HOME FOR: RJK

Developments

SITE ADDRESS Te Piriti Road One Tree Point Whangarei

**PURCHASER SIGNATURE** Owner

Date

**BUILDER SIGNATURE** 

Date

SITE INFORMATION

Lot Number DPS Number 270 TBC Site Area Wind Zone High 602m<sup>2</sup> Corrosion Zone Planning Zone **General Residential** 

Territorial Authority

MAX COVERAGE MAX IMPERMEABLE Site Area 602m2 Max 241m<sup>2</sup> Max 361.2m<sup>2</sup> SITE COVERAGE Areas % Area Over Frame 202 34% Area Over Foundation 35% SITE IMPERMEABLE Areas Roof Coverage 244.2 40.6% 81.8 13.6% TOTAL 326.0 54.2%

Concrete Areas: Trowel Finished with 5kg/m3 Black Oxide Uncovered Areas 113.7m<sup>2</sup> 13m²

TOTAL

JOB INFOMATION

Job Last Published

126.7m<sup>2</sup>

390129 DRAWING VERSION

GJG Job Number

Contract

1:200, 1:500

CAD Technician/Designer Sheet M Grew

EDA201



### FORUM NORTH PRIVATE BAG 9023, WHANGAREI, NEW ZEALAND TELEPHONE 09 430 4200 FAX 09 438 7632

### **Issue Document**

VEHICLE CROSSING PERMIT APPLICATION NO: VC220117 Whangarei District Council Public Places ByLaw Received: 26 May 2022 Issued: 30 June 2022

### **Applicant**

**RJK Developments Limited** 132 Kara Road RD9 Whangarei 0179

### **Agent**

### **Sudfelt Construction Limited – GJ Gardner Homes Whangarei**

### **Site Information**

Property ID: 172239

Street Address: 98 Kaurinui Crescent

One Tree Point 0118

Legal Description: LOT 270 DP 564989

### **Project Information**

THIS IS A VEHICLE CROSSING PERMIT APPLICATION ONLY

### **Fees**

COUNCIL'S TOTAL CHARGES FOR THIS VEHICLE CROSSING PERMIT

ARE: \$428.00

PAYMENTS RECEIVED TO DATE: 30/06/2022 AMOUNT: \$428.00

### NEW HOME FOR: RJK

### Developments

SITE ADDRESS Te Piriti Road One Tree Point Whangarei

### PURCHASER SIGNATURE

Owner

Date

**BUILDER SIGNATURE** 

### Date

### SITE INFORMATION Lot Number 270

Site Area 602m<sup>2</sup> Planning Zone

**General Residential** 

Corrosion Zone

Territorial Authority WDC

**DPS Number** 

Wind Zone

TBC

High

34%

35%

MAX COVERAGE MAX IMPERMEABLE Site Area 602m2 Site Area 60% 40% Max 241m² Max 361.2m<sup>2</sup>

SITE COVERAGE

Area Over Frame 202 Area Over Foundation

SITE IMPERMEABLE Areas Roof Coverage

244.2 40.6% 13.6% TOTAL 326.0 54.2%

Concrete Areas: Trowel Finished with

5kg/m³ Black Oxide

Covered Areas

TOTAL 126.7m<sup>2</sup>

JOB INFOMATION

Job Last Published Friday, 3 June 2022 GJG Job Number

390129

### DRAWING VERSION

Contract

CAD Technician/Designer M Grew


1:200, 1:500

**A201** 

113.7m<sup>2</sup>

13m<sup>2</sup>

These drawings are copyrighted. Under no circumstances may these drawing be reproduced in any form without the written permission of G.J. Gardner Homes.



CUSTOMER

Water meter is 500 mm away from the crossing.



Private Bag 9023, Whangarei 0148, New Zealand P +64 9 430 4200 | 0800 WDC INFO | 0800 932 463 E mailroom@wdc.govt.nz www.wdc.govt.nz

# Fast Track - Public Utility Service Application 20mm Water Meter Only (DOMESTIC ONLY)

PU221265

### General Guidance

- All other connection types require a 'standard' public utility works application
- All fields must be completed or N/A as appropriate
- The applicant must be the owner of the land, or the lease holder, or a person who has agreed to unconditionally purchase or lease the land
- If a Backflow Preventer is required with the water meter (see application requirements), please complete a 'standard' public utility works application.

Owner / Applicant	
Full Name RX Development Lta	
Postal address 132 Kara Rd, Whan	Post code
Phone 021 270 8282	Mobile
Email derek@drainsunlimited.co	.nz
Agent Authorisation (If required) As the agent you accept responsibility to pass all Coun appropriate. If fees are not paid by the agent, charges	
Full Name/ Company Name Sudfelt Construction Lin	nited - GJ Gardner Homes Whangarei
Position/ Title	
Contact Details	
Postal address P O Box 8046, Kensington, Whangarei	
Phone 09 437 5666	Mobile
Email whangarei@gjgardner.co.nz	
Signature	Date
Site Address 98	Kaurinui Crescent
Street/Road Number Street/Road Name	TE PRITE ROOK, ONE WEE ROW
Town or Area	Lot 270 DP 564989
Office Use Only	
Office Use Only	
Property ID: <u>172239</u>	13/06/2022
LLP number: <u>132680</u>	Date:
Related Consents: BC2200646	

NEW HOME FOR:

RJK

SITE ADDRESS Te Piriti Road One Tree Point Whangarei

**PURCHASER SIGNATURE** Owner Owner

Date

**BUILDER SIGNATURE** 

Date

SITE INFORMATION DPS Number Lot Number 270 Site Area Wind Zone 602m<sup>2</sup>

Planning Zone **General Residential** 

Corrosion Zone

TBC

High

13.6%

54.2%

Territorial Authority

MAX COVERAGE MAX IMPERMEABLE Site Area 602m2 Site Area Max 241m<sup>2</sup> Max 361,2m<sup>2</sup> SITE COVERAGE Area Over Frame 202 34% 35% Area Over Foundation 209 SITE IMPERMEABLE 244.2 40.6%

Concrete Areas: Trowel Finished with 5kg/m³ Black Oxide 113.7m<sup>2</sup> 13m² Covered Areas

TOTAL 126.7m<sup>2</sup>

JOB INFOMATION

GJG Job Number 390129 Job Last Published Friday, 3 June 2022

81.8

326.0

DRAWING VERSION

Contract

TOTAL

CAD Technician/Designer Sheet M Grew

1:200, 1:500


A201





# Operative District Plan - Area Specific Matters





The information displayed is schematic only and serves as a guide. It has been compiled from Whangarei District Council records and is made available in good faith but its accuracy or completeness is not guaranteed.

12 August 2025 Scale 1:500



# Operative District Plan - Map Legend



**Area Specific Matters** 

### **District-Wide Matters**

### Energy, Infrastructure and **Historical and Cultural** Designation Transport Values Precinct Airport Runway Notable Tree Overlay Development Area ---- Indicative Road Heritage Item Overlay Heritage Area Overlay National Road Sites of Significance Regional Road **Residential Zones Industrial Zones** Arterial Road Areas of Significance Large Lot Light Industrial **Primary Collector** to Maori Residential Zone Road Low Density Heavy Industrial Secondary Collector Residential Zone Zone Road **Natural Environment** General Residential Values Low Volume Road Access Road Esplanade Priority Medium Density Residential Zone Open Space and Strategic Road Coastal Marine Area Recreation Zones Protection Area (CMA) boundary Strategic Railway Natural Open Space **Goat Control Areas** Protection Line Zone Rural Zones **Outstanding Natural** National Grid Tower Open Space Zone Feature **Rural Production** Northpower Tower Sport and Active **Outstanding Natural** Zone CEL-Cat1 Recreation Zone Landscape Rural Lifestyle Zone National Grid Line Settlement Zone Northpower Overhead Residential Sub-Critical Line Cel-Cat1 General District-Wide Zone Special Purpose Zones Northpower Critical Settlement Zone Overhead Lines CEL ····· Air Noise Boundary Airport Zone Centre Sub-Zone Northpower Critical Outer Control Settlement Zone Future Urban Zone Underground Lines Boundary Industry Sub-Zone Fonterra Kauri Milk Helicopter Hovering Processing SRIZ -Area Ancillary Irrigation Noise Control Farms Commercial and **Boundary Overlay** Mixed Use Zones Hospital Zone Rail noise alert area Hazards and Risks Port Zone Local Centre Zone Rail vibration alert Coastal Erosion area Neighbourhood Ruakaka Equine Hazard 1 Centre Zone Zone **QRA Quarrying** Coastal Erosion Resource Area Shopping Centre Commercial Zone Hazard 2 **QRA Mining Area** Mixed Use Zone Flood Susceptible Strategic Rural Areas **QRA Buffer Area** Town Centre Zone Industries Zone Mining Hazard Area 1 QRA 500m Indicative City Centre Zone Waterfront Zone Setback Mining Hazard Area 2 Coastal Environment Mining Hazard Area 3 Overlay Outstanding Natural Character Area High Natural

The information displayed is schematic only and serves as a guide.

It has been compiled from Whangarei District Council records and is made available in good faith, but its accuracy or completeness is not guaranteed.

The Whangarei District Council district plan GIS data was created at a specific point in time.

Character Area

Land parcel Information is sourced from the Land Information New Zealand (LINZ) Data Service. The LINZ land parcel information may be updated by LINZ at any time from that time, which may result in misalignments with Whangarei District Council information.

STATEMENT OF PASSING OVER			
This document has been supplied in good faith. OWN Real Estate (Powered by Ownly Limited, Licensed REAA 2008) is merely passing over this information as supplied to us. We cannot guarantee its accuracy as we have not checked, audited, or reviewed the information and all intending purchasers are advised to seek your own advice as to the information contained in this document. To the maximum extent permitted by law we do not accept any responsibility to any party for the accuracy or use of the information herein.			