



-KĀPITI-

**WOOD FIRES**

# Certificate of Chimney Sweep & Service

## Fireplace details

**Name:** [REDACTED]  
**Address:** 42 Harry Shaw Way, Raumati South, New Zealand  
**Make & Model:** Masport  
**Serial Number:**  
**Date Completed:** 19/08/2025

## Condition report

**External Firebox:** 4. Good condition  
**Internal Firebox:** 4. Good condition  
**Door seals & glass:** 4. Good condition  
**Flue:** 4. Good condition  
**Roof & Flashing:** 4. Good condition

## Technicians notes

1= Beyond repair | 2 = Needs repair | 3 = May require repair soon | Good condition | 5 = Perfect

**126 Rimu Rd, Paraparaumu | 04-212-5509 | [sales@kapitiwoodfires.co.nz](mailto:sales@kapitiwoodfires.co.nz)**

**[www.kapitiwoodfires.co.nz](http://www.kapitiwoodfires.co.nz)**