

## Statement of claim

Claim Number	CLM/2011/112457	Damage Location	1/7A MEDBURY TERRACE, FENDALTON, CHRISTCHURCH 8041
Claimant	G MASON	Reviewed by	(not reviewed)
Main Contact	G MASON	Contact Address	1/ 7A MEDBURY TERRACE, FENDALTON, CHRISTCHURCH
SOW Status	Approved	Reviewed on	
		Edited by	

## Elements included in settlement

<u>Location of damage</u>		<u>Damaged Feature</u>	<u>Damage</u>
Main Access		Main Access	Damaged surface
Elevation	Main Building - South wall	Wall Cladding	Cracking
			Cracking
			Cracking
Lounge	Ground Floor Main Building -	Ceiling	Cosmetic Damage
		Floor	Cosmetic damage
			Cosmetic damage
		Door (Internal)	Cosmetic damage
Dining Room	Ground Floor Main Building -	Ceiling	Cosmetic Damage
		Floor	Cosmetic damage
			Cosmetic damage
		Wall covering	Cosmetic damage
			Cosmetic damage
Internal Garage	Ground Floor Main Building -	Ceiling	Cosmetic Damage
		Floor	Cosmetic damage
		Wall covering	Cosmetic damage
		Wall covering	Cosmetic damage
Kitchen	Ground Floor Main Building -	Ceiling	Cosmetic Damage
			Cosmetic Damage
		Wall covering	Cosmetic damage
		Window	Cosmetic damage
		Water Supply	Structural damage
Hallway	Ground Floor Main Building -	Ceiling	Cosmetic Damage
			Cosmetic Damage
		Wall covering	Cosmetic damage
			Cosmetic damage
Bedroom	Ground Floor Main Building - SW corner	Ceiling	Cosmetic Damage

			Wall covering	Cosmetic damage
				Cosmetic damage
Bedroom	Ground Floor Main Building - NW corner	Ceiling		Cosmetic Damage
		Wall covering		Cosmetic damage
		Door (Internal)		Cosmetic damage
		Door (External)		Cosmetic damage
		Built in wardrobe		Cosmetic damage
Bathroom	Ground Floor Main Building -	Wall covering		Cosmetic damage
				Cosmetic damage
		Window		Cosmetic damage

**Ends**