

GRIFFIOEN.

HEALTHY HOMES REPORT

Statement of Passing Over: This Healthy Homes Report has been supplied by the vendor in good faith. GRIFFIOEN. (Powered by Ownly Limited, Licensed REAA 2008) is merely passing over this information as supplied to us.

We cannot guarantee its accuracy as we have not checked, audited, or reviewed the information and all intending purchasers are advised to seek your own advice as to the information contained in this document.

Prospective purchasers are advised to seek their own independent advice as to the condition of the property either prior to, or as a condition of, purchasing the property.

To the maximum extent permitted by law we do not accept any responsibility to any party for the accuracy or use of the information herein.



RED LBP HEALTHY HOMES REPORT

- ✓ Completed by a trade professional
- ✓ Healthy Homes assessment report detailing heating, insulation, ventilation, moisture ingress, drainage, and draught stopping
- ✓ Follows Healthy Home Standards
- ✓ Rental property compliant
- ✓ Recommendations for any identified issues



REDLBP.



0800 113 191 • REDLBP.CO.NZ

HEALTHY HOMES





7/24 Whitmore Street, Edgeware, Christchurch 8013, New Zealand

Date of inspection

8/2/2026

Time of inspection

8.00 - 8.30 am

Client Name

Jonathan Booth & Aurora Lin

People present

Inspector

Weather

Sunny

Temperature

18 degrees

Inspectors name

Jamie Chapman

Company name, trading as RedLBP

JBC Builders Limited

Booking Number

SR024640

House occupied

No

Decade home built

2000s



RESULT OVERVIEW

The healthy homes standards became law on 1 July 2019.

The healthy homes standards introduce specific and minimum standards for heating, insulation, ventilation, moisture ingress and drainage, and draught stopping in rental properties.

Heating	Pass
Insulation	Pass
Ventilation	Pass
Draught Stopping	Pass
Moisture Barrier	Pass
Moisture and Drainage	Pass
Smoke Alarms	Pass

SUMMARY

HEALTHY HOMES ASSESSMENT COMPLIANCE CERTIFICATE

This property has had the following items checked and tested
to see if they comply with the current Residential Tenancies
(Healthy Home Standards) Regulations 2019.

Address 7/24 Whitmore Street, Edgeware, Christchurch
8013, New Zealand

Date of inspection 8/2/2026

Certificate number SR024640

Heating



Insulation



Ventilation



Draught stopping



Moisture and Drainage



Smoke alarms



Additional comments

Text

Inspector



Inspector Name: Jamie Chapman

Red LBP Location: Christchurch North

All noted items have been given the Red LBP tick of compliance.



HEATING

Landlords must provide one or more fixed heaters that can directly heat the main living room. The heater(s) must be acceptable types, and must meet the minimum heating capacity required for your main living room.

Options available for heating are, wood burners, pellet fires, heat pumps, electric with thermostat, flued gas with thermostat. Open fires are not acceptable.

Main living area	Living room
Main heating source	Heatpump
KW requirement	3.1kw
Current KW	6.1kw
Additional heaters	No
Does property have exemptions?	No
Top up heating required	No
Comments	Pass

SUMMARY





INSULATION

Ceiling and underfloor insulation has been compulsory in all rental homes since 1 July 2019.

The healthy homes insulation standard builds on the current regulations and some existing insulation will need to be topped up or replaced.

CEILING

Results Pass

Comments Not visible due to this dwelling having a skillion roof and there being no roof space access available. Being built in the 2000s, this dwelling will likely have a 3.3rating.

UNDERFLOOR

Comments N/A, as this dwelling has a concrete floor.

SUMMARY



VENTILATION AND DRAUGHT STOPPING

Rental homes must have openable windows in the living room, dining room, kitchen, and bedrooms. Kitchens and bathrooms must have extractor fans vented to the outdoors.

Mould and dampness caused by poor ventilation is harmful for tenants' health as well as landlords' property. The ventilation standard targets mould and dampness in rental homes. Kitchen vent ducting must be minimum of 150mm. Bathroom vent ducting must be minimum of 120mm.

Landlords must make sure the property does not have unreasonable gaps or holes in walls, ceilings, windows, skylights, floors, and doors which cause noticeable draughts. All unused open fireplaces closed off or their chimneys must be blocked to prevent draughts.

Draughts increase the likelihood of lower temperatures in houses, and can make it more expensive for a tenant to heat their home.

LOUNGE

Windows openable	2
Stay open	Pass
Any unreasonable gaps	No
Comments	Pass

KITCHEN

Windows openable	1
Mechanical ventilation	Yes
Vented to the exterior	Yes
Any unreasonable gaps	No
Comments	Pass

BATHROOM 1

Windows openable	0
Mechanical ventilation	Yes



Vented to the exterior	Yes
-------------------------------	-----

Any unreasonable gaps	No
------------------------------	----

Comments	Pass
-----------------	------

BEDROOM 1

Windows openable	2
-------------------------	---

Stay open	Yes
------------------	-----

Any unreasonable gaps	No
------------------------------	----

Comments	Pass
-----------------	------

BEDROOM 2

Windows openable	1
-------------------------	---

Stay open	Yes
------------------	-----

Any unreasonable gaps	No
------------------------------	----

Comments	Pass
-----------------	------

BEDROOM 3

Windows openable	2
-------------------------	---

Stay open	Yes
------------------	-----

Any unreasonable gaps	No
------------------------------	----

Comments	Pass
-----------------	------

SUMMARY



Photo of the kitchen and bathroom ventilation



MOISTURE AND DRAINAGE

Rental properties must have efficient drainage for the removal of storm water, surface water and ground water. Rental properties with an enclosed sub-floor space must have a ground moisture barrier.

Moisture can be a large source of dampness in a home. This dampness can lead to poor health outcomes for tenants and can be destructive to the quality of a house.

GROUND MOISTURE BARRIER

Comments	N/A, as this dwelling has a concrete floor.
-----------------	---

RAINWATER SPOUTING

Installed and not damaged	Yes
Damaged – needs repair	No
Spouting clear	Yes
Spouting connected to downpipes	Yes
Downpipes connected to drains	Yes
Comments	Pass

GROUND WATER

Land profile	Flat
Land condition	acceptable
Drainage	No significant water ponding visible
Comments	Pass

SUMMARY



SMOKE ALARMS

Working smoke alarms are compulsory in all rental homes.

New smoke alarms must be photoelectric and have long battery life, or be hard wired.

Smoke alarms in correct areas	Yes, within 3m of the bedrooms
Action required	No
Comments	Smoke alarms are located in the upstairs living area and the downstairs hallway. Regular checks of the smoke alarms are recommended.





LANDLORD DOCUMENTS TO BE KEPT

Residential Tenancies (Healthy Homes Standards) Regulations 2019

Documents to be retained by landlords

- (1) For the purposes of section 123A(1)(ca) of the Act, a landlord must retain sufficient relevant records or documents as reasonably provide evidence of the landlord's compliance with the healthy homes standards in relation to the tenancy.
- (2) However, subclause (1)—
 - (a) only requires the landlord to retain records or documents that the landlord has possession of at the commencement of the tenancy or acquires possession of during the tenancy; and
 - (b) does not require the landlord to create or obtain a record or document merely for the purpose of retaining it for the purposes of section 123A(1)(ca).

Report Scope and Warranties

- This report has been created to assess the status of the property against the Healthy Homes Standards.
- The report is completed based on visual, non-invasive inspection on one particular day. Nothing was moved.
- No warranty is provided for damage or defect that was not visible at the time of the inspection.
- This report is in no way a warranty as to the future performance or condition of the items inspected.
- There are circumstances beyond our control that can change the result reported at the time of assessment. As an example, Tenancy Services publish this regarding Moisture Ingress and Drainage:

The functionality of guttering, downpipes and drainage can be difficult to visually assess during dry weather or light rain. Checking the system visually from ground level during times of moderate rainfall can be helpful.

Where specific and required information cannot be ascertained, that item will be marked accordingly, and further information will be required from the client to enable the report to be completed. An example could be the KW rating of a wood burner with no label.

- Where possible we identify items that may require attention / maintenance that are not included in the Healthy Home Requirements.
- No warranty is provided from this report, inspection, or service provider, that items assessed will not fail at some stage in the future.
- This report is, in no way, a representation of compliance to any building codes or legislation requirements other than the Healthy Homes Standards and other items specifically named in the report, such as smoke alarms.

Confidentiality

This report is, in no way, a representation of compliance to any building codes or legislation requirements other than the Healthy Homes Standards and other items specifically named in the report, such as smoke alarms.