

SWP20454342 Swimming pool fencing Inspection
Inspection checklist outcome statement 12-03-2025

Inspection Address : 120 Walter Strevens Drive Conifer Grove
Auckland 2112



Important Note: The following inspection checklist must be read in conjunction with the Auckland Council Inspection Code of Practice where individual line items have been defined to support reasons for decisions. N/A means Not Applicable (not part of this inspection)

* Indicates a photo has been taken in relation to a particular line item

Inspection Details	
Inspection Type Code	Swimming pool fencing(SWP)
Date of Inspection	12-03-2025
Start time	17:02:00
Does the checklist need to be completed?	Yes


Checklist Item	Result	Comment
Choose method of determining compliance	FOSPA	
FOSPA- type of pool as per Council records	N/A	
Type of pool	In ground	*
Pool fencing area as per previous inspection/ plans and defines the immediate pool area	N/A	
Immediate pool area free from non-pool associated activities	Pass	
Pool fencing minimum 1.2m height above and away from (in an arc) ground level or any permanent projections	Pass	
Fencing horizontal rails and climbable features are at least 900mm apart (i.e barrier has 900mm no climb zone)	Pass	
Gaps under or through the fence < 100mm dia sphere	Pass	
Steel wire mesh max openings 13mm. If openings 13-35mm height to be 1.8m. No openings greater than 35mm	N/A	
Boundary fence min height and no climb zone	Pass	
Balcony / deck > 2.4m above pool area- barrier 1m min height. < 2.4m- barrier 1.2m min height.	N/A	
Returns/solid barriers installed to prevent climb arounds	N/A	
Gate swings away from pool, self closes and self latches from 150mm open	Pass	
Gate swings clear of anything that may prevent the gate from closing	Pass	
Latch 1.5m above ground/permanent projection.Or only accessible by reaching at least 1.2m and over or through the gate	Pass	
Doors self latch and self-close with latch at 1500mm height?	Pass	
Doors self latches and fitted with an audible warning device	N/A	
Doors fitted with a top bolt or latch at 1500m if approved before 2017	Pass	
"SWIMMING POOL - CLOSE DOOR" sticker displayed between 1200mm and 1500mm	Pass	
Window less than 2.4m above pool area	Pass	
Fencing subject to FOSPA section 6 "exemption" or F9 modification	N/A	

LBP Name (if applicable)	LBP Number	LBP Class
Not applicable to this inspection.		

Documents required	Comment
Not applicable to this inspection.	

Minor Variation Description (if applicable)	Outcome	Outcome reason / Comment
Not applicable to this inspection.		

Inspection Summary	
Fail Comments	Not applicable to this inspection.
Additional Comments	Your pool fencing inspection has passed. Please continue to maintain the safety and compliance of your pool barrier until your next 3 yearly inspection. Contact details - (09) 353 9143; https://www.aucklandcouncil.govt.nz and search "pools"
Inspection Outcome	Pass
Person on site (name)	MP Rutherford Tr & BE Webster Tr -
Outcome statement recipient email	Office@safetsleep.com
Outcome statement recipient email	sales@safetsleep.com
Inspector's name	Shane Readhead
Inspector's email	SHANE.READHEAD@AUCKLANDCOUNCIL.GOVT.NZ
Inspector's phone number	+64 27 2332272
Inspection duration (minutes) Note- Time may be added for travel and additional processing (eg minor variations)	45

Photos	
Type of pool - Tall steel framed front gate	


Type of pool - upper locks - typical



Type of pool - view of house frontage



Type of pool - window stay




Type of pool - door locks



Type of pool - self-closing door



Type of pool - window stay



Type of pool - window lock



Type of pool - view from gate end

