INSPECTION REPORT

Name:	**Stuart Gibson**	Consent No: **BC130058**
Address:	**135 Bensemann Road, Upper Moutere**	Inspected by: Bevan Barker

On **16/10/2014** at **5:03 p.m.** this site was inspected pursuant to the Building Act 2004 (section 222/230) and the Local Government Act 2004 (Section 174). The purpose of the inspection was:

17 DRAINAGE/SEWER/STORMWATER: ALL IN-ROUND SEWER & STORM-WATER PIPES, CONNECTIONS ETC BEFORE COVERING UP.

Notes Summary: Foul water only. Pipes between tank locations only, adequate fall, primer used, 3 Ip's, Asbuilts to come. Balance to be inspected at On Site Effluent inspection

Next Inspection:

☒ **Failed Inspection Points**

As per the approved consented plan
Changes made to the locations of the pipe, also the field is to be located in the reserve area. All to be confrimed by asbuilts and Designer/Engineer

As-built received
To come