




Restoration Design

Reach Characteristics

- Stage 2
- Riparian vegetation
- Paleo channel on river left
- Signs of old beaver dams







- Deep water cover
- Deposition
- Bank erosion
- Raise water table
- Lower water velocity





Adaptive Management



success!

