
# Pataha Creek - Recap






## DOE 2016 Funding BDAs and Trial Planting




## Monitoring Design



Plant large diameter willow across 4 km section of Pataha Creek


Evidence for an incision story?





## DOE 2016 Funding BDAs and Trial Planting





# Evidence beavers are helping



Willow abundant and shading out some reed canary

# Evidence beavers are helping



Dams held in 2016 and caused deposition



## Biological Evidence

