

PROPERTY LOCATED AT: 30 Pleasant St, Lisbon, ME 04252**PROPERTY DISCLOSURE**

Under Maine Law, certain information must be made available to buyers prior to or during preparation of an offer. This statement has been prepared to assist prospective buyers in evaluating this property. This disclosure is not a warranty of the condition of the property and is not part of any contract between Seller and any Buyer. Seller authorizes the disclosure of the information in this statement to real estate licensees and to prospective buyers of this property. The Seller agrees to provide prompt notice of any changes in the information and this form will be appropriately changed with an amendment date. Inspections are highly recommended.

DO NOT LEAVE ANY QUESTIONS BLANK. STRIKE, WRITE N/A OR UNKNOWN IF NEEDED.**SECTION I – WATER SUPPLY**

TYPE OF SYSTEM: ☒ Public ☐ Private ☐ Seasonal _____ ☐ Unknown
☐ Drilled ☐ Dug ☐ Other _____

MALFUNCTIONS: Are you aware of or have you experienced any malfunctions with the
 (public/private/other) water system?

Pump (if any): ☐ N/A ☐ Yes ☒ No ☐ Unknown

Quantity: ☐ Yes ☒ No ☐ Unknown

Quality: ☐ Yes ☒ No ☐ Unknown

If Yes to any question, please explain in the comment section below or with attachment.

WATER TEST: Have you had the water tested? ☐ Yes ☒ No

If Yes, Date of most recent test: _____ Are test results available? .. ☐ Yes ☐ No

To your knowledge, have any test results ever been reported as unsatisfactory
 or satisfactory with notation? ☐ Yes ☒ No

If Yes, are test results available? ☐ Yes ☐ No

What steps were taken to remedy the problem? N/A

~~IF PRIVATE: (Strike Section if Not Applicable):~~

~~INSTALLATION: Location. _____~~

~~Installed by: _____~~

~~Date of Installation. _____~~

~~USE: Number of persons currently using system: _____~~

~~Does system supply water for more than one household? ☐ Yes ☐ No ☐ Unknown~~

Comments: None

Source of Section I information: Seller

Buyer Initials _____

Page 1 of 7

Seller Initials

BL

KC

PROPERTY LOCATED AT: 30 Pleasant St, Lisbon, ME 04252**SECTION II — WASTE WATER DISPOSAL**TYPE OF SYSTEM: ☒ Public ☐ Private ☐ Quasi-Public _____ ☐ Unknown

IF PUBLIC OR QUASI-PUBLIC (Strike Section if Not Applicable):

Have you had the sewer line inspected?..... ☐ Yes ☒ No

If Yes, what results: _____

Have you experienced any problems such as line or other malfunctions? ☐ Yes ☒ No

What steps were taken to remedy the problem? _____

~~IF PRIVATE (Strike Section if Not Applicable):~~~~Tank: ☐ Septic Tank ☐ Holding Tank ☐ Cesspool ☐ Other: _____~~~~Tank Size: ☐ 500 Gallon ☐ 1000 Gallon ☐ Unknown ☐ Other: _____~~~~Tank Type: ☐ Concrete ☐ Metal ☐ Unknown ☐ Other: _____~~~~Location: _____ OR ☐ Unknown~~~~Date installed: _____ Date last pumped: _____ Name of pumping company: _____~~~~Have you experienced any malfunctions? ☐ Yes ☐ No~~~~If Yes, give the date and describe the problem: _____~~~~Date of last servicing of tank: _____ Name of company servicing tank: _____~~~~Leach Field: _____ ☐ Yes ☐ No ☐ Unknown~~~~If Yes, Location: _____~~~~Date of installation of leach field: _____ Installed by: _____~~~~Date of last servicing of leach field: _____ Company servicing leach field: _____~~~~Have you experienced any malfunctions? ☐ Yes ☐ No~~~~If Yes, give the date and describe the problem and what steps were taken to remedy: _____~~~~Do you have records of the design indicating the # of bedrooms the system was designed for? ☐ Yes ☐ No~~~~If Yes, are they available? ☐ Yes ☐ No~~~~Is System located in a Shoreland Zone? ☐ Yes ☐ No ☐ Unknown~~Comments: **None**Source of Section II information: **Seller**

Buyer Initials _____

Page 2 of 7

Seller Initials  

PROPERTY LOCATED AT: 30 Pleasant St, Lisbon, ME 04252**SECTION III – HEATING SYSTEM(S)/HEATING SOURCE(S)**

Heating System(s) or Source(s)	SYSTEM 1	SYSTEM 2	SYSTEM 3	SYSTEM 4
TYPE(S) of System	FHWBB			
Age of system(s) or source(s)	2003			
TYPE(S) of Fuel	Oil			
Annual consumption per system or source (i.e., gallons, kilowatt hours, cords)	Est. 600 gal			
Name of company that services system(s) or source(s)	DeadRiver			
Date of most recent service call	2023			
Malfunctions per system(s) or source(s) within past 2 years	Replaced Aquastat 2023			
Other pertinent information	Consumption includes yearly domestic hot water			

Are there fuel supply lines? ☒ Yes ☐ No ☐ UnknownAre any buried? ☐ Yes ☒ No ☐ UnknownAre all sleeved? ☐ Yes ☒ No ☐ UnknownChimney(s): ☒ Yes ☐ NoIf Yes, are they lined: ☒ Yes ☐ No ☐ UnknownIs more than one heat source vented through one flue? ☐ Yes ☒ No ☐ UnknownHad a chimney fire: ☐ Yes ☒ No ☐ UnknownHas chimney(s) been inspected? ☐ Yes ☐ No ☒ UnknownIf Yes, date: N/ADate chimney(s) last cleaned: N/ADirect/Power Vent(s): ☐ Yes ☒ No ☐ UnknownHas vent(s) been inspected? ☐ Yes ☒ No ☐ UnknownIf Yes, date: N/AComments: NoneSource of Section III information: Seller**SECTION IV – HAZARDOUS MATERIAL**

The licensee is disclosing that the Seller is making representations contained herein.

A. UNDERGROUND STORAGE TANKS - Are there now, or have there ever been, any underground storage tanks on the property? ☐ Yes ☒ No ☐ UnknownIf Yes, are tanks in current use? ☐ Yes ☒ No ☐ UnknownIf no longer in use, how long have they been out of service? N/AIf tanks are no longer in use, have tanks been abandoned according to DEP? ☐ Yes ☒ No ☐ UnknownAre tanks registered with DEP? ☐ Yes ☒ No ☐ UnknownAge of tank(s): N/A Size of tank(s): N/ALocation: N/A

Buyer Initials _____

Page 3 of 7

Seller Initials 

PROPERTY LOCATED AT: **30 Pleasant St, Lisbon, ME 04252**What materials are, or were, stored in the tank(s)? **N/A**Have you experienced any problems such as leakage: ☐ Yes ☒ No ☐ UnknownComments: **N/A**Source of information: **Seller, Previous Disclosures****B. ASBESTOS** — Is there now or has there been asbestos:As insulation on the heating system pipes or duct work? ☐ Yes ☒ No ☐ UnknownIn the ceilings? ☐ Yes ☒ No ☐ UnknownIn the siding? ☐ Yes ☒ No ☐ UnknownIn the roofing shingles? ☐ Yes ☒ No ☐ UnknownIn flooring tiles? ☐ Yes ☒ No ☐ UnknownOther: ☐ Yes ☒ No ☐ UnknownComments: **Seller is unaware of any asbestos existing on the property.**Source of information: **Seller, Previous Disclosures****C. RADON/AIR** - Current or previously existing:Has the property been tested? ☐ Yes ☒ No ☐ UnknownIf Yes: Date: **N/A** By: **N/A**Results: **N/A**If applicable, what remedial steps were taken? **N/A**Has the property been tested since remedial steps? ☐ Yes ☒ No ☐ UnknownAre test results available? ☐ Yes ☒ NoResults/Comments: **Seller has not tested for Radon**Source of information: **Seller, Previous Disclosures****D. RADON/WATER** - Current or previously existing:Has the property been tested? ☐ Yes ☒ No ☐ UnknownIf Yes: Date: **N/A** By: **N/A**Results: **N/A**If applicable, what remedial steps were taken? **N/A**Has the property been tested since remedial steps? ☐ Yes ☒ No ☐ UnknownAre test results available? ☐ Yes ☒ NoResults/Comments: **Public Water**Source of information: **Seller****E. METHAMPHETAMINE** - Current or previously existing:☐ Yes ☒ No ☐ UnknownComments: **None**Source of information: **Seller, Previous Disclosures**

Buyer Initials _____

Page 4 of 7

Seller Initials 

PROPERTY LOCATED AT: 30 Pleasant St, Lisbon, ME 04252**F. LEAD-BASED PAINT/PAINT HAZARDS** — (Note: Lead-based paint is most commonly found in homes constructed prior to 1978)Is there now or has there ever been lead-based paint and/or lead-based paint hazards on the property?
..... ☐ Yes ☐ No ☐ Unknown ☒ Unknown (but possible due to age)If Yes, describe location and basis for determination: N/ADo you know of any records/reports pertaining to such lead-based paint/lead-based paint hazards: ☐ Yes ☒ NoIf Yes, describe: N/AAre you aware of any cracking, peeling or flaking paint? ☒ Yes ☐ NoComments: On garage. Home is vinyl siding.Source of information: Seller, Previous Disclosures**G. OTHER HAZARDOUS MATERIALS** - Current or previously existing:TOXIC MATERIAL: ☐ Yes ☒ No ☐ UnknownLAND FILL: ☐ Yes ☒ No ☐ UnknownRADIOACTIVE MATERIAL: ☐ Yes ☒ No ☐ UnknownOther: N/ASource of information: Seller, Previous Disclosures**Buyers are encouraged to seek information from professionals regarding any specific issue or concern.****SECTION V — GENERAL INFORMATION**Is the property subject to or have the benefit of any encroachments, easements, rights-of-way, leases, rights of first refusal, life estates, private ways, trails, homeowner associations (including condominiums and PUD's) or restrictive covenants? ☐ Yes ☒ No ☐ UnknownIf Yes, explain: N/ASource of information: Seller, Public RecordIs access by means of a way owned and maintained by the State, a county, or a municipality over which the public has a right to pass? ☒ Yes ☐ No ☐ UnknownIf No, who is responsible for maintenance? N/ARoad Association Name (if known): N/A

Buyer Initials _____

Page 5 of 7

Seller Initials BLKC

PROPERTY LOCATED AT: **30 Pleasant St, Lisbon, ME 04252**

Are there any tax exemptions or reductions for this property for any reason including but not limited to:

Tree Growth, Open Space and Farmland, Veteran's, Homestead Exemption, Blind, Working Waterfront?.....

..... ☐ Yes ☒ No ☐ Unknown

If Yes, explain: **N/A**

Is a Forest Management and Harvest Plan available?..... ☐ Yes ☒ No ☐ Unknown

Is house now covered by flood insurance policy (not a determination of flood zone) ☐ Yes ☒ No ☐ Unknown

Equipment leased or not owned (including but not limited to, propane tank, hot water heater, satellite dish, water filtration system, photovoltaics, wind turbines): Type: **N/A**

Year Principal Structure Built: **1968**

What year did Seller acquire property? **2012**

Roof: Year Shingles/Other Installed: **Home - 2021, Garage -Unknown**

Water, moisture or leakage: **None**

Comments: **None**

Foundation/Basement:

Is there a Sump Pump? ☐ Yes ☒ No ☐ Unknown

Water, moisture or leakage since you owned the property: ☐ Yes ☒ No ☐ Unknown

Prior water, moisture or leakage? ☐ Yes ☐ No ☒ Unknown

Comments: **None**

Mold: Has the property ever been tested for mold? ☐ Yes ☒ No ☐ Unknown

If Yes, are test results available? ☐ Yes ☒ No

Comments: **Seller has never tested for mold**

Electrical: ☐ Fuses ☒ Circuit Breaker ☐ Other: _____ ☐ Unknown

Comments: **100 Amp Service**

Has all or a portion of the property been surveyed? ☐ Yes ☒ No ☐ Unknown

If Yes, is the survey available? ☐ Yes ☒ No ☐ Unknown

Manufactured Housing – Is the residence a:

Mobile Home ☐ Yes ☒ No ☐ Unknown

Modular ☐ Yes ☒ No ☐ Unknown

Known defects or hazardous materials caused by insect or animal infestation inside or on the residential structure
..... ☐ Yes ☒ No ☐ Unknown

Comments: **None**

KNOWN MATERIAL DEFECTS about Physical Condition and/or value of Property, including those that may have an adverse impact on health/safety: **None**

Comments: **None**

Source of Section V information: **Seller, Previous Disclosures**

Buyer Initials _____

Page 6 of 7

Seller Initials 



PROPERTY LOCATED AT: 30 Pleasant St, Lisbon, ME 04252

SECTION VI – ADDITIONAL INFORMATION

ATTACHMENTS EXPLAINING CURRENT PROBLEMS, PAST REPAIRS OR ADDITIONAL INFORMATION IN ANY SECTION IN DISCLOSURE: ☐ Yes ☒ No

Seller shall be responsible and liable for any failure to provide known information regarding known material defects to the Buyer.

Neither Seller nor any Broker makes any representations as to the applicability of, or compliance with, any codes of any sort, whether state, municipal, federal or any other, including but not limited to fire, life safety, building, electrical or plumbing.

As Sellers, we have provided the above information and represent that all information is correct. To the best of our knowledge, all systems and equipment, unless otherwise noted on this form, are in operational condition.

DocuSigned by:
Brad Charest 3/11/2024
SELLER DATE
Brad Charest

DocuSigned by:
Katlyn Charest 3/11/2024
SELLER DATE
Katlyn Charest

SELLER DATE

SELLER DATE

I/We have read and received a copy of this disclosure, the arsenic in wood fact sheet, the arsenic in water brochure, and understand that I/we should seek information from qualified professionals if I/we have questions or concerns.

BUYER DATE

BUYER DATE

BUYER DATE

BUYER DATE

