

PROPERTY LOCATED AT: 1092 Main Road, Phippsburg, ME**PROPERTY DISCLOSURE**

Under Maine Law, certain information must be made available to buyers prior to or during preparation of an offer. This statement has been prepared to assist prospective buyers in evaluating this property. This disclosure is not a warranty of the condition of the property and is not part of any contract between Seller and any Buyer. Seller authorizes the disclosure of the information in this statement to real estate licensees and to prospective buyers of this property. The Seller agrees to provide prompt notice of any changes in the information and this form will be appropriately changed with an amendment date. Inspections are highly recommended.

DO NOT LEAVE ANY QUESTIONS BLANK. STRIKE, WRITE N/A OR UNKNOWN IF NEEDED.**SECTION I – WATER SUPPLY**

TYPE OF SYSTEM: ☒ Public ☐ Private ☐ Seasonal _____ ☐ Unknown
☒ Drilled ☐ Dug ☐ Other _____

MALFUNCTIONS: Are you aware of or have you experienced any malfunctions with the
 (public/private/other) water system?

Pump (if any): ☐ N/A ☐ Yes ☒ No ☐ Unknown

Quantity: ☐ Yes ☒ No ☐ Unknown

Quality: ☐ Yes ☒ No ☐ Unknown

If Yes to any question, please explain in the comment section below or with attachment.

WATER TEST: Have you had the water tested? ☐ Yes ☒ No

If Yes, Date of most recent test: N/A Are test results available? .. ☐ Yes ☒ No

To your knowledge, have any test results ever been reported as unsatisfactory
 or satisfactory with notation? ☐ Yes ☒ No

If Yes, are test results available? ☐ Yes ☐ No

What steps were taken to remedy the problem? N/A

IF PRIVATE: (Strike Section if Not Applicable):

INSTALLATION: Location: Front of home

Installed by: Unknown

Date of Installation: Unknown

USE: Number of persons currently using system: Most recently, 1

Does system supply water for more than one household? ☐ Yes ☒ No ☐ Unknown
 New well pump installed May 2024. water softener was removed.

Comments: N/A

System is configured for easy re-installation

Source of Section I information: Personal Representative of Estate

Buyer Initials _____

Page 1 of 7

Seller Initials DS _____

PROPERTY LOCATED AT: 1092 Main Road, Phippsburg, ME**SECTION II — WASTE WATER DISPOSAL**TYPE OF SYSTEM: ☐ Public ☒ Private ☐ Quasi-Public _____ ☐ Unknown~~IF PUBLIC OR QUASI PUBLIC (Strike Section if Not Applicable):~~~~Have you had the sewer line inspected? _____ ☐ Yes ☐ No~~~~If Yes, what results: _____~~~~Have you experienced any problems such as line or other malfunctions? _____ ☐ Yes ☐ No~~~~What steps were taken to remedy the problem? _____~~

IF PRIVATE (Strike Section if Not Applicable):

Tank: ☒ Septic Tank ☐ Holding Tank ☐ Cesspool ☐ Other: _____Tank Size: ☐ 500 Gallon ☒ 1000 Gallon ☐ Unknown ☐ Other: _____Tank Type: ☐ Concrete ☐ Metal ☒ Unknown ☐ Other: _____Location: **Behind Home** OR ☐ UnknownDate installed: **Est 1993** Date last pumped: **2021** Name of pumping company: **Unknown**Have you experienced any malfunctions? _____ ☐ Yes ☒ NoIf Yes, give the date and describe the problem: **N/A**Date of last servicing of tank: **Unknown** Name of company servicing tank: **Unknown**Leach Field: _____ ☒ Yes ☐ No ☐ UnknownIf Yes, Location: **Behind Home**Date of installation of leach field: **Est 1993** Installed by: **Unknown**Date of last servicing of leach field: **Unknown** Company servicing leach field: **Unknown**Have you experienced any malfunctions? _____ ☐ Yes ☒ NoIf Yes, give the date and describe the problem and what steps were taken to remedy: **N/A**Do you have records of the design indicating the # of bedrooms the system was designed for? ☒ Yes ☐ NoIf Yes, are they available? _____ ☒ Yes ☐ NoIs System located in a Shoreland Zone? _____ ☐ Yes ☒ No ☐ UnknownComments: **N/A**Source of Section II information: **Personal Representative of the Estate, HHE200**

Buyer Initials _____

Page 2 of 7

Seller Initials  _____

PROPERTY LOCATED AT: 1092 Main Road, Phippsburg, ME**SECTION III – HEATING SYSTEM(S)/HEATING SOURCE(S)**

Heating System(s) or Source(s)	SYSTEM 1	SYSTEM 2	SYSTEM 3	SYSTEM 4
TYPE(S) of System	FHWBB - Oil	Rinnai Space Heaters (2)	Electric Baseboard	
Age of system(s) or source(s)	2014, per note on Furnace	Unknown	Unknown	
TYPE(S) of Fuel	Oil	LP Gas	N/A	
Annual consumption per system or source (i.e., gallons, kilowatt hours, cords)	Unknown	Unknown	Unknown	
Name of company that services system(s) or source(s)	Unknown	Unknown	Unknown	
Date of most recent service call	Unknown	Unknown	Unknown	
Malfunctions per system(s) or source(s) within past 2 years	Unknown	Unknown	Unknown	
Other pertinent information	N/A	N/A	N/A	

Are there fuel supply lines? ☒ Yes ☐ No ☐ UnknownAre any buried? ☐ Yes ☒ No ☐ UnknownAre all sleeved? ☐ Yes ☒ No ☐ UnknownChimney(s): ☒ Yes ☐ NoIf Yes, are they lined: ☐ Yes ☐ No ☒ UnknownIs more than one heat source vented through one flue? ☐ Yes ☐ No ☒ UnknownHad a chimney fire: ☐ Yes ☐ No ☒ UnknownHas chimney(s) been inspected? ☐ Yes ☐ No ☒ UnknownIf Yes, date: N/ADate chimney(s) last cleaned: UnknownDirect/Power Vent(s): ☒ Yes ☐ No ☐ UnknownHas vent(s) been inspected? ☐ Yes ☐ No ☒ UnknownIf Yes, date: N/AComments: Rinnai Units are direct ventsSource of Section III information: Personal Representative of the Estate, Broker Observation**SECTION IV – HAZARDOUS MATERIAL**

The licensee is disclosing that the Seller is making representations contained herein.

A. UNDERGROUND STORAGE TANKS - Are there now, or have there ever been, any underground storage tanks on the property? ☐ Yes ☐ No ☒ UnknownIf Yes, are tanks in current use? ☐ Yes ☐ No ☐ UnknownIf no longer in use, how long have they been out of service? N/AIf tanks are no longer in use, have tanks been abandoned according to DEP? ☐ Yes ☐ No ☐ UnknownAre tanks registered with DEP? ☐ Yes ☐ No ☐ UnknownAge of tank(s): N/A Size of tank(s): N/ALocation: N/A

Buyer Initials _____

Page 3 of 7

Seller Initials  _____

PROPERTY LOCATED AT: 1092 Main Road, Phippsburg, ME

What materials are, or were, stored in the tank(s)? N/A

Have you experienced any problems such as leakage: ☐ Yes ☐ No ☐ Unknown

Comments: Personal Representative of the Estate has no knowledge of underground storage tanks on the property.

Source of information: Personal Representative of the Estate

B. ASBESTOS — Is there now or has there been asbestos:

As insulation on the heating system pipes or duct work? ☐ Yes ☐ No ☒ Unknown

In the ceilings? ☐ Yes ☐ No ☒ Unknown

In the siding? ☐ Yes ☐ No ☒ Unknown

In the roofing shingles? ☐ Yes ☐ No ☒ Unknown

In flooring tiles? ☐ Yes ☐ No ☒ Unknown

Other: ☐ Yes ☐ No ☒ Unknown

Comments: None

Source of information: Personal Representative of the Estate

C. RADON/AIR - Current or previously existing:

Has the property been tested? ☐ Yes ☐ No ☒ Unknown

If Yes: Date: N/A By: N/A

Results: N/A

If applicable, what remedial steps were taken? N/A

Has the property been tested since remedial steps? ☐ Yes ☐ No ☒ Unknown

Are test results available? ☐ Yes ☐ No

Results/Comments: N/A

Source of information: Personal Representative of the Estate

D. RADON/WATER - Current or previously existing:

Has the property been tested? ☐ Yes ☐ No ☒ Unknown

If Yes: Date: N/A By: N/A

Results: N/A

If applicable, what remedial steps were taken? N/A

Has the property been tested since remedial steps? ☐ Yes ☐ No ☐ Unknown

Are test results available? ☐ Yes ☐ No

Results/Comments: N/A

Source of information: Personal Representative of the Estate

E. METHAMPHETAMINE - Current or previously existing:

☐ Yes ☐ No ☒ Unknown

Comments: N/A

Source of information: Personal Representative of the Estate

Buyer Initials _____

Page 4 of 7

Seller Initials  _____

PROPERTY LOCATED AT: 1092 Main Road, Phippsburg, ME**F. LEAD-BASED PAINT/PAINT HAZARDS** — (Note: Lead-based paint is most commonly found in homes constructed prior to 1978)Is there now or has there ever been lead-based paint and/or lead-based paint hazards on the property?
☐ Yes ☐ No ☒ Unknown ☐ Unknown (but possible due to age)

If Yes, describe location and basis for determination: _____

Do you know of any records/reports pertaining to such lead-based paint/lead-based paint hazards: ☐ Yes ☒ No

If Yes, describe: _____

Are you aware of any cracking, peeling or flaking paint? ☐ Yes ☒ NoComments: Property has vinyl siding.Source of information: Personal Representative of the Estate, Broker Observation**G. OTHER HAZARDOUS MATERIALS** - Current or previously existing:TOXIC MATERIAL: ☐ Yes ☐ No ☒ UnknownLAND FILL: ☐ Yes ☐ No ☒ UnknownRADIOACTIVE MATERIAL: ☐ Yes ☐ No ☒ UnknownOther: N/ASource of information: Personal Representative of the Estate**Buyers are encouraged to seek information from professionals regarding any specific issue or concern.****SECTION V — GENERAL INFORMATION**Is the property subject to or have the benefit of any encroachments, easements, rights-of-way, leases, rights of first refusal, life estates, private ways, trails, homeowner associations (including condominiums and PUD's) or restrictive covenants? ☐ Yes ☒ No ☐ Unknown

If Yes, explain: _____

Source of information: Personal Representative of the Estate, Public RecordIs access by means of a way owned and maintained by the State, a county, or a municipality over which the public has a right to pass? ☒ Yes ☐ No ☐ UnknownIf No, who is responsible for maintenance? N/ARoad Association Name (if known): N/A

Buyer Initials _____

Page 5 of 7

Seller Initials  _____

PROPERTY LOCATED AT: 1092 Main Road, Phippsburg, ME

Are there any tax exemptions or reductions for this property for any reason including but not limited to:

Tree Growth, Open Space and Farmland, Veteran's, Homestead Exemption, Blind, Working Waterfront?.....

..... ☒ Yes ☐ No ☐ Unknown

If Yes, explain: **VA and Homestead Exemption**

Is a Forest Management and Harvest Plan available?..... ☐ Yes ☒ No ☐ Unknown

Is house now covered by flood insurance policy (not a determination of flood zone) ☐ Yes ☒ No ☐ Unknown

Equipment leased or not owned (including but not limited to, propane tank, hot water heater, satellite dish, water filtration system, photovoltaics, wind turbines): Type: **Propane Tanks**

Year Principal Structure Built: 1962

What year did Seller acquire property? 2008

Roof: Year Shingles/Other Installed: 2016, when addition added

Water, moisture or leakage: **None known**

Comments: **Water staining around center chimney is believed to be from before the roofing was redone.**

Foundation/Basement:

Is there a Sump Pump? ☒ Yes ☐ No ☐ Unknown

Water, moisture or leakage since you owned the property: ☐ Yes ☐ No ☒ Unknown

Prior water, moisture or leakage? ☐ Yes ☐ No ☒ Unknown

Comments: **None**

Mold: Has the property ever been tested for mold? ☐ Yes ☐ No ☒ Unknown

If Yes, are test results available? ☐ Yes ☐ No

Comments: **N/A**

Electrical: ☐ Fuses ☒ Circuit Breaker ☐ Other: _____ ☐ Unknown

Comments: **100 amp service**

Has all or a portion of the property been surveyed? ☐ Yes ☐ No ☒ Unknown

If Yes, is the survey available? ☐ Yes ☐ No ☐ Unknown

Manufactured Housing – Is the residence a:

Mobile Home ☐ Yes ☒ No ☐ Unknown

Modular ☐ Yes ☒ No ☐ Unknown

Known defects or hazardous materials caused by insect or animal infestation inside or on the residential structure

..... ☐ Yes ☐ No ☒ Unknown

Comments: _____

KNOWN MATERIAL DEFECTS about Physical Condition and/or value of Property, including those that may have an adverse impact on health/safety: **Unknown**

Comments: **None**

Source of Section V information: **Personal Representative of the Estate**

Buyer Initials _____

Page 6 of 7

Seller Initials 

PROPERTY LOCATED AT: 1092 Main Road, Phippsburg, ME

SECTION VI – ADDITIONAL INFORMATION

Personal Representative of the Estate has never lived at the property.


^{DS}
 Previous contract was terminated due to apparent mold in attic and basement

ATTACHMENTS EXPLAINING CURRENT PROBLEMS, PAST REPAIRS OR ADDITIONAL INFORMATION IN ANY SECTION IN DISCLOSURE: ☐ Yes ☒ No

Seller shall be responsible and liable for any failure to provide known information regarding known material defects to the Buyer.

Neither Seller nor any Broker makes any representations as to the applicability of, or compliance with, any codes of any sort, whether state, municipal, federal or any other, including but not limited to fire, life safety, building, electrical or plumbing.

As Sellers, we have provided the above information and represent that all information is correct. To the best of our knowledge, all systems and equipment, unless otherwise noted on this form, are in operational condition.

DocuSigned by:
 2/15/2024
SELLER _____ DATE _____ SELLER _____ DATE _____
Karen Philip

SELLER _____ DATE _____ SELLER _____ DATE _____

I/We have read and received a copy of this disclosure, the arsenic in wood fact sheet, the arsenic in water brochure, and understand that I/we should seek information from qualified professionals if I/we have questions or concerns.

BUYER _____ DATE _____ BUYER _____ DATE _____

BUYER _____ DATE _____ BUYER _____ DATE _____