

PROPERTY LOCATED AT: 65 Autumn Drive, Poland, ME 04274

### PROPERTY DISCLOSURE

Under Maine Law, certain information must be made available to buyers prior to or during preparation of an offer. This statement has been prepared to assist prospective buyers in evaluating this property. This disclosure is not a warranty of the condition of the property and is not part of any contract between Seller and any Buyer. Seller authorizes the disclosure of the information in this statement to real estate licensees and to prospective buyers of this property. The Seller agrees to provide prompt notice of any changes in the information and this form will be appropriately changed with an amendment date. Inspections are highly recommended.

**DO NOT LEAVE ANY QUESTIONS BLANK. STRIKE, WRITE N/A OR UNKNOWN IF NEEDED.**

### SECTION I – WATER SUPPLY

TYPE OF SYSTEM:  Public  Private  Seasonal \_\_\_\_\_  Unknown  
 Drilled  Dug  Other \_\_\_\_\_

MALFUNCTIONS: Are you aware of or have you experienced any malfunctions with the (public/private/other) water system?

Pump (if any): .....  N/A  Yes  No  Unknown  
Quantity: .....  Yes  No  Unknown  
Quality: .....  Yes  No  Unknown

If Yes to any question, please explain in the comment section below or with attachment.

WATER TEST: Have you had the water tested? .....  Yes  No  
If Yes, Date of most recent test: 2013 Are test results available? ..  Yes  No  
To your knowledge, have any test results ever been reported as unsatisfactory or satisfactory with notation? .....  Yes  No  
If Yes, are test results available? .....  Yes  No  
What steps were taken to remedy the problem? N/A

IF PRIVATE: (Strike Section if Not Applicable):

INSTALLATION: Location: Right of driveway

Installed by: Hansen's Well Drilling Inc

Date of Installation: 2012

USE: Number of persons currently using system: 0

Does system supply water for more than one household?  Yes  No  Unknown

Comments: Water softener and sediment filter installed in 2019.

Source of Section I information: Seller

Buyer Initials \_\_\_\_\_

Page 1 of 7

Seller Initials NCT BJ

PROPERTY LOCATED AT: 65 Autumn Drive, Poland, ME 04274

**SECTION II – WASTE WATER DISPOSAL**

TYPE OF SYSTEM:  Public  Private  Quasi-Public \_\_\_\_\_  Unknown

~~IF PUBLIC OR QUASI-PUBLIC (Strike Section if Not Applicable):~~

~~Have you had the sewer line inspected? .....  Yes  No~~

~~If Yes, what results: \_\_\_\_\_~~

~~Have you experienced any problems such as line or other malfunctions? .....  Yes  No~~

~~What steps were taken to remedy the problem? \_\_\_\_\_~~

IF PRIVATE (Strike Section if Not Applicable):

Tank:  Septic Tank  Holding Tank  Cesspool  Other: \_\_\_\_\_

Tank Size:  500 Gallon  1000 Gallon  Unknown  Other: \_\_\_\_\_

Tank Type:  Concrete  Metal  Unknown  Other: \_\_\_\_\_

Location: Rear of home OR  Unknown

Date installed: 2012 Date last pumped: 9/2019 Name of pumping company: Unknown

Have you experienced any malfunctions? .....  Yes  No

If Yes, give the date and describe the problem: N/A

Date of last servicing of tank: N/A Name of company servicing tank: N/A

Leach Field: .....  Yes  No  Unknown

If Yes, Location: Rear of home

Date of installation of leach field: 2012 Installed by: \_\_\_\_\_

Date of last servicing of leach field: N/A Company servicing leach field: N/A

Have you experienced any malfunctions? .....  Yes  No

If Yes, give the date and describe the problem and what steps were taken to remedy: N/A

Do you have records of the design indicating the # of bedrooms the system was designed for?  Yes  No

If Yes, are they available? .....  Yes  No

Is System located in a Shoreland Zone? .....  Yes  No  Unknown

Comments: 3-Bedroom Septic. Buyer forgets the name of the company who pumped last, though remembers they are out of L/A.

Source of Section II information: Seller and Public Records

Buyer Initials \_\_\_\_\_

Page 2 of 7

Seller Initials NCT BJ

PROPERTY LOCATED AT: 65 Autumn Drive, Poland, ME 04274

**SECTION III – HEATING SYSTEM(S)/HEATING SOURCES(S)**

Heating System(s) or Source(s)	SYSTEM 1	SYSTEM 2	SYSTEM 3	SYSTEM 4
TYPE(S)	<b>FHW - Propane</b>			
Age of system(s) or source(s)	<b>2017</b>			
Name of company that services system(s) or source(s)	<b>Aire Serv</b>			
Date of most recent service call	<b>10/23/2019</b>			
Annual consumption per system or source (i.e., gallons, kilowatt hours, cords)	<b>501 in past 12 months</b>			
Malfunction per system(s) or source(s) within past 2 years	<b>N/A</b>			
Other pertinent information	<b>N/A</b>			

Are there fuel supply lines? .....  Yes  No  Unknown  
 Are any buried? .....  Yes  No  Unknown  
 Are all sleeved? .....  Yes  No  Unknown  
 Chimney(s): .....  Yes  No  
     ~~If Yes, are they lined: .....  Yes  No  Unknown~~  
     ~~Is more than one heat source vented through one flue? .....  Yes  No  Unknown~~  
     ~~Had a chimney fire: .....  Yes  No  Unknown~~  
     ~~Has chimney(s) been inspected? .....  Yes  No  Unknown~~  
     ~~If Yes, date: \_\_\_\_\_~~  
     ~~Date chimney(s) last cleaned: \_\_\_\_\_~~  
 Direct/Power Vent(s): .....  Yes  No  Unknown  
     Has vent(s) been inspected? .....  Yes  No  Unknown  
     If Yes, date: N/A

Comments: N/A

Source of Section III information: Seller

**SECTION IV – HAZARDOUS MATERIAL**

The licensee is disclosing that the Seller is making representations contained herein.

**A. UNDERGROUND STORAGE TANKS** - Are there now, or have there ever been, any underground storage tanks on the property? .....  Yes  No  Unknown  
 If Yes, are tanks in current use? .....  Yes  No  Unknown  
 If no longer in use, how long have they been out of service? \_\_\_\_\_  
 If tanks are no longer in use, have tanks been abandoned according to DEP?  Yes  No  Unknown  
 Are tanks registered with DEP? .....  Yes  No  Unknown  
 Age of tank(s): \_\_\_\_\_ Size of tank(s): \_\_\_\_\_  
 Location: \_\_\_\_\_

Buyer Initials \_\_\_\_\_

Seller Initials NCT BJ

PROPERTY LOCATED AT: 65 Autumn Drive, Poland, ME 04274

~~What materials are, or were, stored in the tank(s)?~~ \_\_\_\_\_

~~Have you experienced any problems such as leakage:~~ \_\_\_\_\_  Yes  No  Unknown

Comments: None known

Source of information: Seller

**B. ASBESTOS** — Is there now or has there been asbestos:

As insulation on the heating system pipes or duct work? .....  Yes  No  Unknown

In the ceilings? .....  Yes  No  Unknown

In the siding? .....  Yes  No  Unknown

In the roofing shingles? .....  Yes  No  Unknown

In flooring tiles? .....  Yes  No  Unknown

Other: \_\_\_\_\_  Yes  No  Unknown

Comments: Home built in 2012

Source of information: Seller

**C. RADON/AIR** - Current or previously existing:

Has the property been tested? .....  Yes  No  Unknown

If Yes: Date: 2013 By: Unknown

Results: Satisfactory

If applicable, what remedial steps were taken? None

Has the property been tested since remedial steps? .....  Yes  No  Unknown

Are test results available? .....  Yes  No

Results/Comments: Piped for mitigation system.

Source of information: Seller

**D. RADON/WATER** - Current or previously existing:

Has the property been tested? .....  Yes  No  Unknown

If Yes: Date: 2013 By: Unknown

Results: Satisfactory

If applicable, what remedial steps were taken? \_\_\_\_\_

Has the property been tested since remedial steps? .....  Yes  No  Unknown

Are test results available? .....  Yes  No

Results/Comments: N/A

Source of information: Seller

**E. METHAMPHETAMINE** - Current or previously existing:

Yes  No  Unknown

Comments: N/A

Source of information: Seller

Buyer Initials \_\_\_\_\_

Seller Initials NCT BJ

PROPERTY LOCATED AT: 65 Autumn Drive, Poland, ME 04274

**F. LEAD-BASED PAINT/PAINT HAZARDS** — (Note: Lead-based paint is most commonly found in homes constructed prior to 1978)

Is there now or has there ever been lead-based paint and/or lead-based paint hazards on the property? .....  
.....  Yes  No  Unknown  Unknown (but possible due to age)

If Yes, describe location and basis for determination: \_\_\_\_\_

Do you know of any records/reports pertaining to such lead-based paint/lead-based paint hazards:  Yes  No

If Yes, describe: \_\_\_\_\_

Are you aware of any cracking, peeling or flaking paint? .....  Yes  No

Comments: N/A

Source of information: Seller

**G. OTHER HAZARDOUS MATERIALS** - Current or previously existing:

TOXIC MATERIAL: .....  Yes  No  Unknown

LAND FILL: .....  Yes  No  Unknown

RADIOACTIVE MATERIAL: .....  Yes  No  Unknown

Other: N/A

Source of information: Seller

**Buyers are encouraged to seek information from professionals regarding any specific issue or concern.**

**SECTION V — GENERAL INFORMATION**

Is the property subject to or have the benefit of any encroachments, easements, rights-of-way, leases, rights of first refusal, life estates, private ways, trails, homeowner associations (including condominiums and PUD's) or restrictive covenants? .....  Yes  No  Unknown

If Yes, explain: Bylaws, covenants, etc. See deed.

Source of information: Deed

Is access by means of a way owned and maintained by the State, a county, or a municipality over which the public has a right to pass? .....  Yes  No  Unknown

If No, who is responsible for maintenance? \_\_\_\_\_

Road Association Name (if known): \_\_\_\_\_

Buyer Initials \_\_\_\_\_

Seller Initials NCT BJ

PROPERTY LOCATED AT: 65 Autumn Drive, Poland, ME 04274

Are there any tax exemptions or reductions for this property for any reason including but not limited to: Tree Growth, Open Space and Farmland, Veteran's, Homestead Exemption, Blind, Working Waterfront?.....  
.....  Yes  No  Unknown

If Yes, explain: N/A

Is a Forest Management and Harvest Plan available?.....  Yes  No  Unknown  
Is house now covered by flood insurance policy (not a determination of flood zone)  Yes  No  Unknown  
Equipment leased or not owned (including but not limited to, propane tank, hot water heater, satellite dish, water filtration system, photovoltaics, wind turbines): Type: Propane Tank

Year Principal Structure Built: 2012  
What year did Seller acquire property? 2013  
Roof: Year Shingles/Other Installed: 2012

Water, moisture or leakage: None

Comments: N/A

Foundation/Basement:

Is there a Sump Pump? .....  Yes  No  Unknown  
Water, moisture or leakage since you owned the property: .....  Yes  No  Unknown  
Prior water, moisture or leakage? .....  Yes  No  Unknown

Comments: Basement is dry. Foundation features Insulated Concrete Form

Mold: Has the property ever been tested for mold? .....  Yes  No  Unknown  
If Yes, are test results available? .....  Yes  No

Electrical:  Fuses  Circuit Breaker  Other: \_\_\_\_\_  Unknown

Has all or a portion of the property been surveyed? .....  Yes  No  Unknown  
If Yes, is the survey available? .....  Yes  No  Unknown

Manufactured Housing – Is the residence a:

Mobile Home .....  Yes  No  Unknown  
Modular .....  Yes  No  Unknown

KNOWN MATERIAL DEFECTS about Physical Condition and/or value of Property, including those that may have an adverse impact on health/safety: Corner siding chipped, screen on slider has scratches, insulation

**Continued... See Addendum Known material defects 1**

Source of Section V information: Seller

Buyer Initials \_\_\_\_\_

Seller Initials NCT BJ

PROPERTY LOCATED AT: 65 Autumn Drive, Poland, ME 04274

**SECTION VI – ADDITIONAL INFORMATION**

**Recent updates include carpet upgrade in ground floor office/playroom, flooring upgrade to laminate in all second floor bedrooms, carpet on steps upgraded to oak with runners, backsplash added to kitchen, and seamless gutter added to rear of home.**

ATTACHMENTS EXPLAINING CURRENT PROBLEMS, PAST REPAIRS OR ADDITIONAL INFORMATION IN ANY SECTION IN DISCLOSURE: .....  Yes  No

Seller shall be responsible and liable for any failure to provide known information regarding known material defects to the Buyer.

Neither Seller nor any Broker makes any representations as to the applicability of, or compliance with, any codes of any sort, whether state, municipal, federal or any other, including but not limited to fire, life safety, building, electrical or plumbing.

As Sellers, we have provided the above information and represent that all information is correct. To the best of our knowledge, all systems and equipment, unless otherwise noted on this form, are in operational condition.

Nathan C Thayer 06-04-2020  
SELLER DATE  
**Nathan C. Thayer**

Brittany Thayer 06-04-2020  
SELLER DATE  
**Brittany Thayer**

\_\_\_\_\_  
SELLER DATE

\_\_\_\_\_  
SELLER DATE

I/We have read and received a copy of this disclosure, the arsenic in wood fact sheet, the arsenic in water brochure, and understand that I/we should seek information from qualified professionals if I/we have questions or concerns.

\_\_\_\_\_  
BUYER DATE

\_\_\_\_\_  
BUYER DATE

\_\_\_\_\_  
BUYER DATE

\_\_\_\_\_  
BUYER DATE

