

PROPERTY LOCATED AT: 191 Woodbury Rd, Auburn, ME 04201

PROPERTY DISCLOSURE

Under Maine Law, certain information must be made available to buyers prior to or during preparation of an offer. This statement has been prepared to assist prospective buyers in evaluating this property. This disclosure is not a warranty of the condition of the property and is not part of any contract between Seller and any Buyer. Seller authorizes the disclosure of the information in this statement to real estate licensees and to prospective buyers of this property. The Seller agrees to provide prompt notice of any changes in the information and this form will be appropriately changed with an amendment date. Inspections are highly recommended.

DO NOT LEAVE ANY QUESTIONS BLANK. STRIKE, WRITE N/A OR UNKNOWN IF NEEDED.

SECTION I – WATER SUPPLY

TYPE OF SYSTEM: Public Private Seasonal _____ Unknown
 Drilled Dug Other _____

MALFUNCTIONS: Are you aware of or have you experienced any malfunctions with the (public/private/other) water system?
Pump (if any): N/A Yes No Unknown
Quantity: Yes No Unknown
Quality: Yes No Unknown

If Yes to any question, please explain in the comment section below or with attachment.

WATER TEST: Have you had the water tested? Yes No
~~If Yes, Date of most recent test: _____ Are test results available? .. Yes No~~
~~To your knowledge, have any test results ever been reported as unsatisfactory or satisfactory with notation? Yes No~~
~~If Yes, are test results available? Yes No~~
~~What steps were taken to remedy the problem? _____~~

IF PRIVATE: (Strike Section if Not Applicable):
INSTALLATION: Location: **To Be Installed**
Installed by: **Affordable Well Drilling**
Date of Installation: **N/A**
USE: Number of persons currently using system: **--**
Does system supply water for more than one household? Yes No Unknown

Comments: **N/A**

Source of Section I information: **Seller**

Buyer Initials _____ Page 1 of 7 Seller Initials **KB** _____

PROPERTY LOCATED AT: 191 Woodbury Rd, Auburn, ME 04201

SECTION II – WASTE WATER DISPOSAL

TYPE OF SYSTEM: Public Private Quasi-Public _____ Unknown

IF PUBLIC OR QUASI-PUBLIC (Strike Section if Not Applicable):

Have you had the sewer line inspected?..... Yes No

If Yes, what results: _____

Have you experienced any problems such as line or other malfunctions? Yes No

What steps were taken to remedy the problem? _____

IF PRIVATE (Strike Section if Not Applicable):

Tank: Septic Tank Holding Tank Cesspool Other: _____

Tank Size: 500 Gallon 1000 Gallon Unknown Other: _____

Tank Type: Concrete Metal Unknown Other: _____

Location: **Front yard** _____ OR Unknown

Date installed: 2020 Date last pumped: N/A Name of pumping company: N/A

Have you experienced any malfunctions? Yes No

If Yes, give the date and describe the problem: N/A

Date of last servicing of tank: N/A Name of company servicing tank: N/A

Leach Field: Yes No Unknown

If Yes, Location: **Front Yard**

Date of installation of leach field: 2020 Installed by: **Dean Smith Construction**

Date of last servicing of leach field: N/A Company servicing leach field: N/A

Have you experienced any malfunctions? Yes No

If Yes, give the date and describe the problem and what steps were taken to remedy: N/A

Do you have records of the design indicating the # of bedrooms the system was designed for? Yes No

If Yes, are they available? Yes No

Is System located in a Shoreland Zone? Yes No Unknown

Comments: N/A

Source of Section II information: **Seller**

Buyer Initials _____

Seller Initials KB

PROPERTY LOCATED AT: 191 Woodbury Rd, Auburn, ME 04201

SECTION III – HEATING SYSTEM(S)/HEATING SOURCES(S)

Heating System(s) or Source(s)	SYSTEM 1	SYSTEM 2	SYSTEM 3	SYSTEM 4
TYPE(S)	FHW, Propane			
Age of system(s) or source(s)	2020			
Name of company that services system(s) or source(s)	Bill Pinard and Sons			
Date of most recent service call	_20200313			
Annual consumption per system or source (i.e., gallons, kilowatt hours, cords)	TBD			
Malfunction per system(s) or source(s) within past 2 years	N/A			
Other pertinent information	New Construction			

Are there fuel supply lines? Yes No Unknown
 Are any buried? Yes No Unknown
 Are all sleeved? Yes No Unknown
 Chimney(s): Yes No
 If Yes, are they lined: Yes No ~~Unknown~~
~~Is more than one heat source vented through one flue? Yes No Unknown~~
~~Had a chimney fire: Yes No Unknown~~
~~Has chimney(s) been inspected? Yes No Unknown~~
 ~~If Yes, date: _____~~
 ~~Date chimney(s) last cleaned: _____~~
 Direct/Power Vent(s): Yes No Unknown
 Has vent(s) been inspected? Yes No Unknown
 If Yes, date: N/A

Comments: N/A

Source of Section III information: Builder

SECTION IV – HAZARDOUS MATERIAL

The licensee is disclosing that the Seller is making representations contained herein.

A. UNDERGROUND STORAGE TANKS - Are there now, or have there ever been, any underground storage tanks on the property? Yes No Unknown
 If Yes, are tanks in current use? Yes No ~~Unknown~~
~~If no longer in use, how long have they been out of service? _____~~
~~If tanks are no longer in use, have tanks been abandoned according to DEP? Yes No Unknown~~
~~Are tanks registered with DEP? Yes No Unknown~~
~~Age of tank(s): _____ Size of tank(s): _____~~
~~Location: _____~~

Buyer Initials _____ - _____ - _____

Seller Initials KB

PROPERTY LOCATED AT: 191 Woodbury Rd, Auburn, ME 04201

~~What materials are, or were, stored in the tank(s)?~~ _____

~~Have you experienced any problems such as leakage:~~ _____ Yes No Unknown

Comments: **None Known**

Source of information: **Seller**

B. ASBESTOS — Is there now or has there been asbestos:

As insulation on the heating system pipes or duct work? Yes No Unknown

In the ceilings? Yes No Unknown

In the siding? Yes No Unknown

In the roofing shingles? Yes No Unknown

In flooring tiles? Yes No Unknown

Other: _____ Yes No Unknown

Comments: **None**

Source of information: **Seller**

C. RADON/AIR - Current or previously existing:

Has the property been tested? Yes No Unknown

~~If Yes: Date: _____ By: _____~~

~~Results: _____~~

~~If applicable, what remedial steps were taken? _____~~

~~Has the property been tested since remedial steps? Yes No Unknown~~

~~Are test results available? Yes No~~

Results/Comments: **New Construction**

Source of information: **Seller**

D. RADON/WATER - Current or previously existing:

Has the property been tested? Yes No Unknown

~~If Yes: Date: _____ By: _____~~

~~Results: _____~~

~~If applicable, what remedial steps were taken? _____~~

~~Has the property been tested since remedial steps? Yes No Unknown~~

~~Are test results available? Yes No~~

Results/Comments: **New Construction**

Source of information: **Seller**

E. METHAMPHETAMINE - Current or previously existing:

Yes No Unknown

Comments: **New Construction**

Source of information: **Seller**

Buyer Initials _____

Seller Initials **KB**

PROPERTY LOCATED AT: 191 Woodbury Rd, Auburn, ME 04201

F. LEAD-BASED PAINT/PAINT HAZARDS — (Note: Lead-based paint is most commonly found in homes constructed prior to 1978)

Is there now or has there ever been lead-based paint and/or lead-based paint hazards on the property?
..... Yes No Unknown Unknown (but possible due to age)

If Yes, describe location and basis for determination: _____

Do you know of any records/reports pertaining to such lead-based paint/lead-based paint hazards: Yes No

If Yes, describe: _____

Are you aware of any cracking, peeling or flaking paint? Yes No

Comments: **New Construction**

Source of information: **Seller**

G. OTHER HAZARDOUS MATERIALS - Current or previously existing:

TOXIC MATERIAL: Yes No Unknown

LAND FILL: Yes No Unknown

RADIOACTIVE MATERIAL: Yes No Unknown

Other: **N/A**

Source of information: **Seller**

Buyers are encouraged to seek information from professionals regarding any specific issue or concern.

SECTION V — GENERAL INFORMATION

Is the property subject to or have the benefit of any encroachments, easements, rights-of-way, leases, rights of first refusal, life estates, private ways, trails, homeowner associations (including condominiums and PUD's) or restrictive covenants? Yes No Unknown

If Yes, explain: **N/A**

Source of information: **Deed**

Is access by means of a way owned and maintained by the State, a county, or a municipality over which the public has a right to pass? Yes No Unknown

If No, who is responsible for maintenance? _____

Road Association Name (if known): _____

Buyer Initials _____

Seller Initials **KB**

PROPERTY LOCATED AT: 191 Woodbury Rd, Auburn, ME 04201

Are there any tax exemptions or reductions for this property for any reason including but not limited to:

Tree Growth, Open Space and Farmland, Veteran's, Homestead Exemption, Blind, Working Waterfront?.....
..... Yes No Unknown

If Yes, explain: _____

Is a Forest Management and Harvest Plan available?..... Yes No Unknown

Is house now covered by flood insurance policy (not a determination of flood zone) Yes No Unknown

Equipment leased or not owned (including but not limited to, propane tank, hot water heater, satellite dish, water filtration system, photovoltaics, wind turbines): Type: N/A

Year Principal Structure Built: 2020

What year did Seller acquire property? 2019

Roof: Year Shingles/Other Installed: 2020

Water, moisture or leakage: N/A

Comments: N/A

Foundation/Basement:

Is there a Sump Pump? Yes No Unknown

Water, moisture or leakage since you owned the property: Yes No Unknown

Prior water, moisture or leakage? Yes No Unknown

Comments: **Some water came into basement due to drainage issue. Has been resolved.**

Mold: Has the property ever been tested for mold? Yes No Unknown

If Yes, are test results available? Yes No

Electrical: Fuses Circuit Breaker Other: _____ Unknown

Has all or a portion of the property been surveyed? Yes No Unknown

If Yes, is the survey available? Yes No Unknown

Manufactured Housing – Is the residence a:

Mobile Home Yes No Unknown

Modular Yes No Unknown

KNOWN MATERIAL DEFECTS about Physical Condition and/or value of Property, including those that may have an adverse impact on health/safety: N/A

Source of Section V information: Seller

Buyer Initials _____

Seller Initials KB

